OMB No. 2040-0042 Approval Expires 12/31/2018 United States Environmental Protection Agency **\$EPA** Washington, DC 20460 **Completion Form For Injection Wells** Administrative Information 1. Permittee Florence Copper Inc. (Permanent Mailing Address) (Street, City, and ZIP Code) 1575 W Hunt Hwy, Florence, AZ 85132 2. Operator Florence Copper Inc. Address (Street, City, State and ZIP Code) 1575 W Hunt Hwy, Florence, AZ 85132 3. Facility Name Telephone Number Florence Copper Inc. (520) 374-3984 Address (Street, City, State and ZIP Code) 1575 W Hunt Hwy, Florence, AZ 85132 4. Surface Location Description of Injection Well(s) State County Arizona Pinal Surface Location Description SW 1/4 of SW 1/4 of NE 1/4 of SW 1/4 of Section 28 Township 4S Range 9E Locate well in two directions from nearest lines of quarter section and drilling unit Location 1010 ft. frm (N/S) N Line of quarter section and 1180 ft. from (E/W) E Line of quarter section. **Well Activity** Well Status Type of Permit Individual Class I x Operating Class II x Area: Number of Wells 33 Modification/Conversion Brine Disposal Proposed _ Enhanced Recovery __ Hydrocarbon Storage X Class III Other Well Number 0-06 Lease Number NA Submit with this Completion Form the attachments listed in Attachments for Completion Form.

	Certification	
this document and all attachments and that, base obtaining the information, I believe that the inform	enally examined and am familiar with the information s d on my inquiry of those individuals immediately resp nation is true, accurate, and complete. I am aware that on, including the possibility of fine and imprisonment	onsible for there are
lame and Official Title <i>(Please type or print)</i> Ian Ream, Senior Hydrogeologist	Signature	Date Signed 9-12-2018

PAPERWORK REDUCTION ACT

The public reporting and record keeping burden for this collection of information is estimated to average 49 hours per response for a Class I hazardous facility, and 47 hours per response for a Class I non-hazardous facility. Burden means the total time, effort, or financial resource expended by persons to generate, maintain, retain, or disclose or provide information to or for a Federal Agency. This includes the time needed to review instructions; develop, acquire, install, and utilize technology and systems for the purposes of collecting, validating, and verifying information, processing and maintaining information, and disclosing and providing information; adjust the existing ways to comply with any previously applicable instructions and requirements; train personnel to be able to respond to the collection of information; search data sources; complete and review the collection of information; and, transmit or otherwise disclose the information. An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a currently valid OMB control number. Send comments on the Agency's need for this information, the accuracy of the provided burden estimates, and any suggested methods for minimizing respondent burden, including the use of automated collection techniques to Director, Collection Strategies Division, U.S. Environmental Protection Agency (2822), 1200 Pennsylvania Ave., NW, Washington, D.C. 20460. Include the OMB control number in any correspondence. Do not send the completed forms to this address.

Attachments to be submitted with the Completion report:

I. Geologic Information

- 1. Lithology and Stratigraphy
- A. Provide a geologic description of the rock units penetrated by name, age, depth, thickness, and lithology of each rock unit penetrated.
- B. Provide a description of the injection unit.
- (1) Name
- (2) Depth (drilled)
- (3) Thickness
- (4) Formation fluid pressure
- (5) Age of unit
- (6) Porosity (avg.)
- (7) Permeability
- (8) Bottom hole temperature
- (9) Lithology
- (10) Bottom hold pressure
- (11) Fracture pressure
- C. Provide chemical characteristics of formation fluid (attach chemical analysis).
- D. Provide a description of freshwater aquifers.
- (1) Depth to base of fresh water (less than 10,000 mg/l TDS).
- (2) Provide a geologic description of aquifer units with name, age, depth, thickness, lithology, and average total dissolved solids.

II. Well Design and Construction

- 1. Provide data on surface, intermediate, and long string casing and tubing. Data must include material, size, weight, grade, and depth set.
- 2. Provide data on the well cement, such as type/class, additives, amount, and method of emplacement.
- 3. Provide packer data on the packer (if used) such as type, name and model, setting depth, and type of annular fluid used.

- 4. Provide data on centralizers to include number, type and depth.
- 5. Provide data on bottom hole completions.
- 6. Provide data on well stimulation used.

III. Description of Surface Equipment

1. Provide data and a sketch of holding tanks, flow lines, filters, and injection pump.

IV. Monitoring Systems

- 1. Provide data on recording and nonrecording injection pressure gauges, casing-tubing annulus pressure gauges, injection rate meters, temperature meters, and other meters or gauges.
- 2. Provide data on constructed monitor wells such as location, depth, casing diameter, method of cementing, etc.

V. Logging and Testing Results

Provide a descriptive report interpreting the results of geophysical logs and other tests. Include a description and data on deviation checks run during drilling.

- **VI.** Provide an as-built diagrammatic sketch of the injection well(s) showing casing, cement, tubing, packer, etc., with proper setting depths. The sketch should include well head and gauges.
- **VII.** Provide data demonstrating mechanical integrity pursuant to 40 CFR 146.08.
- **VIII.** Report on the compatibility of injected wastes with fluids and minerals in both the injection zone and the confining zone.
- IX. Report the status of corrective action on defective wells in the area of review.
- **X.** Include the anticipated maximum pressure and flow rate at which injection will operate.



HALEY & ALDRICH, INC. One Arizona Center 400 E. Van Buren St., Suite 545 Phoenix, AZ 85004 602.760.2450

TECHNICAL MEMORANDUM

14 September 2018 File No. 129687-010

TO: Florence Copper Inc.

Ian Ream, Senior Hydrogeologist

FROM: Haley & Aldrich, Inc.

Lauren Candreva, R.G.

Subject: Drilling, Installation, and Integrity Testing Summary

PTF Observation Well O-06

Florence Copper Inc., Florence, Arizona

GERED GEO GERAPICATE OF 49659 LAUREN A. CANDREVA A.

This document describes drilling, installation, and testing of the Production Test Facility (PTF) observation well O-06 for Florence Copper Inc. (Florence Copper) in Florence, Arizona, including a description of the equipment used to perform the work, details of the completed work, and the results of well testing activities. Separate well completion reports have been created for each PTF well.

The Arizona Department of Water Resources Registry ID for well O-06 is 55-227235; the Well Registry Report is included in Appendix A. Well O-06 is located in the southeast quarter of the northwest quarter of the southwest quarter of Section 28 of Township 4 north, Range 9 East of the Gila and Salt River Baseline and Meridian (D(4-9)28CBD). Well O-06 is located within the Underground Injection Control (UIC) Permitted Area of Review (AOR) for UIC Permit R9UIC-AZ3-FY11-1 and was completed as a Class III observation well for the PTF (Figure 1).

Florence Copper contracted Hydro Resources to drill, install, and test well O-06 in accordance with *Bid Specification: Drilling, Installation, and Testing of Class III Observation Wells, Production Test Facility, Florence, Arizona* (Haley & Aldrich, Inc. [Haley & Aldrich], 2017). A Challenger 320 drilling rig was used for all drilling and construction activities. Haley & Aldrich provided oversight of drilling activities, geophysical logging, well installation, and testing. All reported depths are in feet below ground surface unless otherwise noted.

Geologic Information I.

1. Lithology and Stratigraphy

A. Geology of Penetrated Units

The geology penetrated during the drilling of the Class III Well O-06 is summarized in the table below and a lithologic log is included in Appendix B.

Lithologic Unit Name	Depth to Bottom of Unit (feet)	Thickness of Unit (feet)	Lithology and Age of Unit
Upper Basin Fill Unit (UBFU)	278	278	Alluvium; Quaternary to Tertiary
Middle Fine-Grained Unit (MFGU)	298	20	Alluvium; Tertiary
Lower Basin Fill Unit (LBFU)	365	67	Alluvium; Tertiary to Cretaceous
Bedrock Oxide Unit (Oxide)	Not encountered	>855	Igneous porphyry – Precambrian

B. Description of Injection Unit

Name	Bedrock Oxide Unit
Depth Drilled	1,220 feet
Thickness	>855 feet
Formation Fluid Pressure	Atmospheric plus head of freshwater – no additional formation pressure
Age of Unit	Precambrian with intrusions of Precambrian to Tertiary rocks
Porosity ¹	Approximately 6 to 8.5%
Permeability	Hydraulic Conductivity = 0.56 feet per day
Bottom Hole Temperature	34.5 degrees Celsius
Lithology	Igneous porphyry – quartz monzonite, granodiorite with diabase and andesite dykes (detailed log included in Appendix B)
Bottom Hole Pressure	Approximately 430 pounds per square inch (PSI) (pressure exerted by the column of freshwater with no additional contribution from formation pressure)
Fracture Pressure	0.65 PSI per foot
¹ Porosity values for the bedrock of	xide unit are approximate values from calculated neutron porosity values from

injection well borehole surveys.



C. Chemical Characteristics of Formation Fluid

The chemical characteristics of the formation fluid in the injection zone are summarized below and the results of the sampling of the center PTF wellfield well R-09. The table below summarizes the primary chemical characteristics detected in a formation fluid sample collected on 23 April 2018. The complete analytical report is included in Appendix C.

Analyte	Result (mg/L)
Metals	
Aluminum	<0.08
Antimony	<0.005
Arsenic	0.0016
Barium	0.071
Beryllium	<0.0005
Cadmium	<0.00025
Calcium	140
Chromium	0.0051
Cobalt	<0.00025
Copper	0.011
Iron	<0.30
Lead	<0.0005
Magnesium	27
Manganese	0.002
Mercury	<0.001
Nickel	0.0033
Potassium	6.8
Selenium	<0.0025
Sodium	170
Thallium	<0.0005
Zinc	<0.04
Anions	
Bicarbonate	150
Chloride	310
Fluoride	<0.5
Nitrate	8.8
Sulfate	190
Field Parameters	
Total Dissolved Solids	1,000
рН	7.8
Radiochemicals	
Uranium	0.016
Notes:	
mg/L = milligrams per liter	

Results of the sampling of well O-06 are included in the *PTF Mine Block Ambient Groundwater Concentrations and Initial Discharge Characterization of the Underground Workings* (Brown and Caldwell, 2018).



D. Description of Freshwater Aquifers

- 1) The depth to the base of the freshwater aquifer is defined by the interface where deeper formation fluid exhibits a total dissolved solids (TDS) value of 10,000 milligrams per liter (mg/L). The depth of the 10,000 mg/L interface is deeper than all of the wells drilled at the site and consequently has not been defined.
- 2) The geologic description of the aquifer units is included below:

Aquifer Unit Name	Age	Depth (feet)	Thickness (feet)	Lithology	Average Total Dissolved Solids ¹ (mg/L)
UBFU	Quaternary/Tertiary	0 to 278	278	Alluvium	914
LBFU	Tertiary	298 to 365	67	Alluvium	754

 $^{^{1}}$ Average TDS values calculated from UBFU and LBFU monitoring well ambient monitoring results near the PTF.

II. Well Design and Construction

1. Well O-06 Casing Installed:

Casing	Material	Diameter (inches)	Weight (pounds per foot)	Depths (feet)	Borehole Diameter (inches)	Drilling Method
Surface	Mild Steel	14 O.D. 13%I.D.	47.36	0 to 40	24	Solid-stem auger
Well Casing	Fiberglass Reinforced Plastic	5.47 O.D. 4.74 I.D.	5.40	-1.0 to 499	121⁄4	Reverse Flooded Rotary
Screen	PVC SCH80 with 0.020-inch wide slots	5.56 O.D. 4.81 I.D.	4.08	499 to 1,201	12¼	Reverse Flooded Rotary

Notes:

I.D. = inside diameter

O.D. = outside diameter

PVC = polyvinyl chloride

SCH = Schedule



2. Well Cement

Cement Interval	Cement Type	Additives	Amount Installed (cubic yards)	Method of Emplacement
Surface Casing	Type V Neat 21 sack slurry	None	4.5	Submerged tremie
Well Casing	Type V Neat 21 sack slurry	None	31.7	Submerged Tremie

Field forms documenting pipe tallies, annular materials, and cement tickets are included in Appendix D.

3. Annular Packers

No annular packers were used during construction of well O-06.

4. Centralizers

Casing	Centralizer Type	Number and Spacing
Well – FRP and PVC	Stainless steel – Heavy Duty	26 installed – every 40 feet
Notes:		
FRP = fiberglass reinforced plastic		
PVC = polyvinyl chloride		

5. Bottom Hole Completion

There is no bottom hole completion as this is not an oil/gas well. The well was completed at the bottom with a stainless-steel endcap of the same diameter as the well screen.

6. Well Stimulation

No well stimulation was used during the drilling and construction of well O-06.

III. Description of Surface Equipment

1. Surface Equipment

Well O-06 is an observation well and has been equipped with a pressure transducer for monitoring water level and a low-flow pump for collecting fluid samples for analysis of specific conductance. A diagram of the wellhead is included in the well as-built in Figure 2.



IV. Monitoring Systems

1. Well Monitoring Equipment

Equipment Type	Location	Туре	Purpose
Pressure Transducer	Well Casing	Recording	Monitor water column/pressure
Electrical Conductivity Sensors	Well Annulus	Non-recording	Monitor formation conductivity
Annular Conductivity Sensors	Well Annulus	Non-recording	Monitor formation conductivity

2. Monitoring Wells

There are a total of 16 monitoring wells associated with the PTF: 7 point-of-compliance (POC) wells, 7 United States Environmental Protection Agency (USEPA) supplemental monitoring wells, and 2 operational monitoring wells. The POC wells are located outside the AOR and are not constructed as Class III wells. The supplemental monitoring and operational monitoring wells are located within the AOR and are constructed as Class III wells as required by the UIC Permit. The wells are summarized in the tables below by type.

	POC Wells								
Well ID	Location X/Y (State Plane NAD 83)	Depth (feet)	Well Nom. Diameter (inches)	Cementing Method	Screened Interval (feet)	Screened Lithologic Unit			
M14-GL	846750.23 746461.52	859	5 9/16 OD	Submerged tremie	778 to 838	LBFU			
M15-GU	846697.17 746464.82	615	5 9/16 OD	Submerged tremie	554 to 594	LBFU			
M22-O	846751.26 746514.47	1,140	5 9/16 OD to 528 feet; 4½ OD to 1,140 feet	Submerged tremie	932 to 1,130	Oxide			
M23-UBF	846688.13 746512.48	250	6% OD	Submerged tremie	210 to 250	UBFU			
M52-UBF	851092.00 774178.00	274	5 9/16	Submerged tremie	198 to 273	UBFU			
M54-LBF	847331.96 746682.61	630	5 9/16	Submerged tremie	310 to 629	LBFU			
M54-O	847342.99 746702.36	1,199	5 9/16	Submerged tremie	668 to 1,198	Oxide			



	Supplemental Monitoring Wells								
Well ID	Location X/Y (State Plane NAD 83)	Depth (feet)	Well Nom. Diameter (inches)	Cementing Method	Screened Interval (feet)	Screened Lithologic Unit			
M55-UBF	847541.46 746280.63	261	5	Submerged tremie	240 to 260	UBFU			
M56-LBF	847518.70 746303.41	340	5	Submerged tremie	320 to 340	LBFU			
M57-O	847378.37 746248.93	1,200	5	Submerged tremie	523 to 1,199	Oxide			
M58-O	847672.23 746595.97	1,200	5	Submerged tremie	594 to 1,199	Oxide			
M59-O	847934.95 746218.89	1,201	5	Submerged tremie	534 to 1,199	Oxide			
M60-O	847599.37 745903.70	1,201	5	Submerged tremie	444 to 1,200	Oxide			
M61-LBF	848184.46 746148.88	629	5	Submerged tremie	429 to 629	LBFU			

Operational Monitoring Wells							
Well ID	Location X/Y (State Plane NAD 83) Depth (feet) Depth (feet) Depth (feet) Diameter (inches) Cementing Method Interval (feet)						
MW-01-LBF	847487.97 746360.54	444	5	Submerged tremie	330 to 440	LBFU	
MW-01-0	847499.04 746369.31	1,200	5	Submerged tremie	500 to 1,200	Oxide	

V. Logging and Testing Results

Borehole geophysical logging was conducted on well O-06 in two phases: 1) open-hole surveys in the 12.25-inch borehole prior to installation of the well casing and screen, and 2) cased-hole surveys in the completed well.

The open-hole geophysical surveys completed at well O-06 included:

- Spontaneous potential;
- Natural gamma;



- Electrical resistivity (short and long normal);
- Caliper with calculated volume;
- Temperature;
- Sonic; and
- Deviation.

The cased-hole geophysical surveys completed included:

- Sonic (for cement bond with fiberglass reinforced plastic [FRP]);
- 4 Pi Density (for cement bond with FRP);
- Dual Density (for cement bond with FRP);
- Natural Gamma;
- Fluid Conductivity;
- Temperature;
- · Gyroscopic Deviation Survey; and
- Video Survey.

Open-hole geophysical surveys were used to support identification of the lithologic contacts, to evaluate the condition of the borehole, and to evaluate the deviation of the borehole.

The primary logs used to evaluate lithologic contacts are natural gamma ray, short (16-inch) and long (64-inch) normal electrical resistance, and single-point resistance. The lithologic contacts for the Middle Fine-Grained Unit (MFGU) were selected based on the short and long resistance and the single-point resistance. All the resistivity logs decreased and stayed consistently low through the MFGU. This contact is generally a relatively sharp decrease in resistance at the top of the unit and a gradual increase in resistance below the bottom of the unit.

The contact between the Lower Basin Fill Unit (LBFU) and the bedrock was identified primarily with natural gamma and correlated with the resistance logs. There is a consistent increase in gamma at the contact between the LBFU and the bedrock that had been identified and documented at the site during exploration in the 1990s. For well O-06, the gamma is consistently at approximately 50 American Petroleum Institute (API) units throughout the Upper Basin Fill Unit (UBFU) and MFGU, a slight increase to approximately 60 API units in the LBFU, and an increase at starting at 365 feet to over 160 API units. After the increase at 365 feet, the natural gamma begins to vary significantly more than it did in the alluvial units. This change in the response of the natural gamma indicates the contact with the bedrock unit. Also, at this approximate depth there is also an increase in the single-point resistance and the short normal resistance indicating the formation has become more resistant. This is likely primarily due to the bedrock containing less water than the alluvial formation above.



Cased-hole geophysical surveys were conducted to evaluate the cement seal, the casing-cement bond, to document baseline fluid temperature and conductivity and to evaluate the plumbness of the well. The cement-bond is discussed in Section VII.

Copies of all the open-hole geophysical logs and cased-hole temperature, fluid conductivity, and natural gamma are included in Appendix E; a figure summarizing the open-hole logs used to evaluate geology is included as Figure 3. The cased-hole logs used to evaluate cement bond are included in Appendix F.

VI. Well As-Built Diagram

An as-built diagram for well O-06 is included as Figure 2.

VII. Demonstration of Mechanical Integrity

A demonstration of Part I mechanical integrity of the well was completed using a standard annular pressure test (SAPT) in accordance with Part II.E.3.a.i.A of the UIC Permit. Mechanical integrity will be demonstrated every 2 years during operations and will be confirmed by daily injection pressure monitoring that will be conducted per the UIC Permit once the well is operational. Well O-06 SAPT is summarized below.

The mechanical integrity of the blank well casing was tested by performing a SAPT on 5 April 2018. The SAPT was conducted by installing an inflatable straddle packer assembly in the well. The bottom packer was installed near the bottom of the FRP-cased portion of the well and the top packer was near the surface. The packers were inflated to form a seal against the casing. The bottom 5 feet of the packer drop pipe was perforated to allow for communication between the tubing and the annulus of the packer assembly. The drop pipe extended through the wellhead and a high pressure/low volume pump was attached to the drop pipe to pressurize the test interval. A valve on the drop pipe at the surface was used to isolate the test interval once the planned test pressure was achieved.

An In-Situ LevelTROLL® pressure transducer with a data logger was installed at the well head and was connected to the packer assembly annulus interval via a National Pipe Thread adapter. The LevelTROLL was used to monitor and record pressure inside the well during the SAPT. To conduct the SAPT, water was pumped from a nearby well immediately prior to testing. Before the water was pumped into the test well, the water temperature was measured to ensure that it was similar to the ambient groundwater temperature of the test well to reduce the potential of differential temperature effects on the well casing. The SAPT for the Class III well was conducted by applying hydraulic pressure to the well casing and shutting in pressure between the packer and wellhead assembly, monitoring the shut-in pressure for a 30-minute period, then measuring the volume of water returned from the well casing after the pressure was released.



On 05 April 2018, the packer was installed to approximately 482 feet and the SAPT was conducted successfully two times. The USEPA SAPT form, a table of the data, and a chart of the data is provided in Appendix G.

Part II mechanical integrity is demonstrated by the cementing records included in this report in accordance with Part II.E.3.ii.C of the UIC Permit and will be demonstrated during operations by annular conductivity monitoring on the observation and multi-level sampling wells in accordance with Part II.E.3.a.ii.A of the UIC Permit.

Cemented Interval	Cement Type	Calculated Grout Volume (cubic yards)	Installed Grout Volume (cubic yards)
Surface Casing	Type V 21 sack neat cement slurry	3.1	4.5
Well Casing	Type V 21 sack neat cement slurry	25.5	31.7

On 22 March 2018, a suite of geophysical logs was run over the entire length of the completed well to verify the grout seal. A summary of the logs completed to demonstrate cement bond are included in Appendix F.

There is not a bond log tool designed to evaluate cement bond with FRP casing, so the cement interval with FRP casing of well O-06 was evaluated using density logs. The logs collected included sonic, focused density, and 4pi density. Based on the measured density of the FRP cased interval of well O-06, no significant cement deficiencies were noted in the sonic data collected from approximately 240 feet (static water level) to 471 feet, and no significant deficiencies were noted in the 4pi density data collected from 35 to 471 feet. There were some very localized, low density intervals identified in the 4pi density logs but they were insignificant, only extending 2 to 3 feet. A summary of the FRP cased data is included in the well completion summary in Appendix F.

VIII. Compatibility of Injected Waste

The Florence Copper Project is a Class III mineral extraction project and does not include the injection of any waste products of any kind. The injected fluid (lixiviant) is a carefully constituted in-situ copper recovery solution that will be recovered and recycled following injection.

The compatibility of the lixiviant was evaluated as part of the geochemical modeling completed by Florence Copper and summarized in the *Geochemical Evaluation to Forecast Composition of Process Solutions for In-Situ Copper Recovery Pilot Test Facility at Florence Copper, Florence Arizona* (Daniel B. Stephens Inc., 2014) which was included in Attachment H of the UIC Permit Application.



IX. Status of Corrective Action on Defective Wells in the Area of Review

There are not currently any defective wells in the AOR.

X. Maximum Pressures and Flow Rates for O-06

Maximum Operating Pressure	Maximum Flow
Atmospheric	Not applicable – observation well

This well is an observation well used to monitor hydraulic control of the PTF. No fluids will be injected and only fluid to measure specific conductivity will be extracted using the installed low-flow pump.

XI. Well Development

Well O-06 was developed by the airlift method, followed by pumping, and was completed by Hydro Resources using a workover rig. To purge drilling fluids and solids, the well was airlift developed from 19 February to 24 February 2018 at various depths ranging from 400 to 1,200 feet. During development, the airlift pump was turned on and off to surge the well. On 21 February 2018, approximately 3 gallons of AquaClear PFD® were added to the well to break down the drilling mud used during drilling and to aid in well development. The discharge was clear to milky and sand-free at the end of the airlift development period.

On 27 February 2018, a submersible pump was temporarily installed to approximately 1,164 feet to pump develop the well. Pump development was conducted at approximately 50 to 80 gallons per minute until 1 March 2018, during which time the submersible pump was raised to 900 feet and then 600 feet (both on 1 March 2018), and periodically turned off to surge the well. The depth to water at the end of each pumping period was approximately 250 feet; water levels would recover to approximately 220 feet prior to the next pumping period. The discharge was visually clear and sand-free throughout the pump development period, with turbidity values less than 5 Nephelometric Turbidity Units at the end of the development period. Well development forms are included in Appendix H.

XII. Well Completion

A well video survey was conducted on 21 March 2018. The video log report is included as Appendix I. The video log depths are presented in feet below the top of the casing and so vary slightly from what is recorded but with the correction for stick up are the same.

The video log indicates the top of fill in the well is at 1,195 feet.



The surveyed location for well O-06 is:

Northing (feet)	Easting (feet)	Measuring Point Elevation (feet amsl)
746201.82	847553.01	1479.01

Notes:

Northing and easting locations provided in State Plane North American Datum 1983, vertical location provided in North American Vertical Datum 1988. amsl – feet above mean sea level

XIII. Downhole Equipment

The equipment installed in well O-06 includes:

- QED® low-flow sampling pump hung on drop tubing pump at 600 feet; and
- Pressure transducer.

The type and depth of equipment installed in each well is not constrained by the UIC Permit or the Aquifer Protection Permit (APP). This information is provided in accordance with Section 2.7.4.3 of the APP. Operational consideration may require that the type and depth of equipment may need to be changed in response to conditions observed during operations.

XIV. References

Brown and Caldwell, Inc., 2018. PTF Mine Block Ambient Groundwater Concentrations and Initial Discharge Characterization of the Underground Workings. September.

Daniel B. Stephens, Inc., 2014. *Geochemical Evaluation to Forecast Composition of Process Solutions for In-Situ Copper Recovery Pilot Test Facility at Florence Copper, Florence Arizona*. May.

Haley & Aldrich, Inc., 2017. *Bid Specification: Drilling, Installation, and Testing of Class III Observation Wells, Production Test Facility, Florence, Arizona*. Revised September 2017.



Enclosures:

Figure 1 – Well Locations

Figure 2 – Well O-06 As-Built Diagram

Figure 3 – Geophysical Data and Lithologic Log

Appendix A – Arizona Department of Water Resources Well Registry Report

Appendix B – Lithologic Log

Appendix C – Chemical Characteristics of Formation Water

Appendix D – Well Completion Documentation

Appendix E – Geophysical Logs

Appendix F – Cement Bond Log Summary

Appendix G – SAPT Documentation


Appendix H – Well Development Field Forms


Appendix I – Well Video Log and Gyroscopic Survey Reports

G:\Projects\Florence Copper\129687 PTF Well Drilling\Deliverables\Well Summary Reports\0-06\2018-0914_0-06 Well Install Comp Letter Report_EPA vers_F.docx









NOTES

- 1. WELL REGISTRATION NO.: 55-227235
- 2. CADASTRAL LOCATION: D (4-9) 28 CBD
- 3. I.D. = INSIDE DIAMETER
- 4. O.D. = OUTSIDE DIAMETER
- 5. PVC = POLYVINYL CHLORIDE
- 6. FRP = FIBERGLASS REINFORCED PLASTIC
- 7. ACD = ANNULAR CONDUCTIVITY DEVICE
- 8. EC = ELETRICAL CONDUCTIVITY
- 9. ERT = ELECTRICAL RESISTIVITY TOMOGRAHY




PRODUCTION TEST FACILITY FLORENCE COPPER, INC. FLORENCE, ARIZONA

OBSERVATION WELL O-06 AS-BUILT DIAGRAM



SCALE: NOT TO SCALE SEPTEMBR 2018


FIGURE 2





PRODUCTION TEST FACILITY FLORENCE COPPER, INC. FLORENCE, ARIZONA

OBSERVATION WELL O-06 GEOPHYSICAL DATA AND LITHOLOGIC LOG



APPENDIX A Arizona Department of Water Resources Well Registry Report

Arizona Department of Water Resources

Water Management Division
P.O. Box 36020 Phoenix, Arizona 85067-6020
(602) 771-8627 • (602) 771-8690 fax
• www.azwater.gov



Well Driller Report and Well Log



THIS REPORT MUST BE FILED WITHIN 30 DAYS OF COMPLETING THE WELL.

PLEASE PRINT CLEARLY USING BLACK OR BLUE INK.

D (4-9) 28 CBD
WELL REGISTRATION NUMBER
55 - 227235

PERMIT NUMBER (IF ISSUED)

Drilling	ON 1. DRILLING AUTHORIZ	ATION					-					
Drining	NAME		DWRLICEN	SE NUMBER								
	Hydro Resources I	nc	816									
0	ADDRESS	IC.	TELEPHONE NUMBER									
Mail To:	13027 County Rd.	18 Unit C			544							
Ž	CITY/STATE/ZIP	io onico	(303) 857-7544 (303) 857-2826									
	Ft. Lupton, CO 806	21										
SECTIO	ON 2. REGISTRY INFORMAT	TION		-								
Well Ov			Location	n of Well								
	ence Copper Inc.	NDIVIDUAL	WELL LOCA	ATION ADDRI	ESS (IF ANY)							
MAILING A	DDRESS		TOWNSHIP	RANGE	SECTION	160 ACRE	40 ACRE	10 ACRE				
1575	W. Hunt Hwy		(N/S) 4S	9E	28	SW 1/4	NW 1/4	SE 1/2				
	TE / ZIP CODE	LATITUDE	JUL	20	LONGITUDE		OL /					
Flore	ence A7 85132	33 •	_	1.41 "N	-111 °	26 .	6.34 "w					
CONTACT	ence, AZ 85132 PERSON NAME AND TITLE		Degrees METHOD OF		Seconds	Degrees	Minutes	Seconds				
	Ream - Sr. Hydrologist		METHOD OF LATITUDE/LONGITUDE (CHECK ONE)									
	NE NUMBER FAX				ION AT WELL	vey-Grade						
(520	0) 374-3984		1492 Feet Above Sea Leve									
WELL NAM	IE (e.g., MW-1, PZ-3, Lot 25 Well, Smith	Well, etc.)	METHOD OF ELEVATION (CHECK ONE)									
	O - 06		*GPS: Hand-Held									
	0 00		*GEOGRAPHIC COORDINATE DATUM (CHECK ONE) NAD-83 Other (please specify):									
				3 U Other								
			COUNTY			DR'S PARCEL						
			PINAL		BOOK	MAP	P	ARCEL				
SECTIO	N 3. WELL CONSTRUCTIO	N DETAILS										
Drill Met	hod	Method of Well De	evelopment		Method	of Sealing	at Reducti	on Points				
	THAT APPLY	CHECK ALL THAT APP	LY		CHECK O							
☐ Air R	Rotary				☐ Nor	ne						
Bore	d or Augered	☐ Bail		Packed								
	e Tool	☐ Surge Block				Swedged						
	Rotary	Surge Pump				Welded						
Mud D Boy	erse Circulation	Other (please	specify):		☐ Oth	er (please	specify):					
X Reve □ Drive												
☐ Jette		Condition of Well			0 1							
	ercussion / Odex Tubing	CHECK ONE			CONTRACTOR OF THE PARTY OF THE	LL CONSTRUC						
	r (please specify):	☐ Capped				2/2018	TION STARTE	:0				
	(produce opeony).	☐ Pump Installe	d			LL CONSTRUC	TION COMPI	ETED				
		- rump mstalle	u			4/2018	TION COMPL	ETED				
state that	t this notice is filed in compliance	with A.R.S. § 45-596 a	nd is complete	and corre		of my know	ledge and i	belief.				
GNATURE	OF QUALIFYING PARTY				DATE	./	/					
1					5/29	1/2018						

SECTION 4. WELL CONSTRUCTION DI	ESIGN (AS BUILT) (attach add	ditional page if needed)	
Depth			
DEPTH OF BORING 1220	Feet Below Land Surface	DEPTH OF COMPLETED WELL 1200	Feet Below Land Surface

Water Level Inform	nation	Section 1		
STATIC WATER LEVEL 228	Feet Below Land Surface	03/22/2018	1 PM	IF FLOWING WELL, METHOD OF FLOW REGULATION Valve Other:

Borehole			Installed Casing												
FACE						MA	ERIA	L TYPE (T)		PE	RFO	RAT	ION	TYPE (T)	
TO (feet)	BOREHOLE DIAMETER (inches)	FROM (feet)	TO (feet)	OUTER DIAMETER (inches)	STEEL	PVC	ABS	IF OTHER TYPE, DESCRIBE	BLANK OR NONE	WIRE WRAP	SHUTTER SCREEN	MILLS KNIFE	SLOTTED	IF OTHER TYPE, DESCRIBE	SLOT SIZE IF ANY (inches)
40	30	0	40	24.5	×				×						
474	20	0	474	14.5	X				X						
1220	12.25	0	500	5.44				FRP	X						
		500	1200	5.56		×							X		.020
							+		\vdash	-					
	TO (feet)	TO BOREHOLE DIAMETER (inches) 40 30 474 20	BOREHOLE FROM (feet)	DEPTH FROM SURFACE DEPTH FROM SURFACE TO (feet) DIAMETER (inches) FROM (feet) TO (feet)	DEPTH FROM SURFACE DIAMETER (inches) FROM (feet) TO (feet) DIAMETER (inches) OUTER	DEPTH FROM SURFACE DIAMETER (inches) DEPTH FROM SURFACE DIAMETER (inches) DIAMETER (inches) DIAMETER (inches) DOUTER DIAMETER (inches) DIAMETER (inches) DOUTER DIAMETER (inches) DEPTH FROM SURFACE DIAMETER (inches) DIAMETER (inches)	DEPTH FROM SURFACE DIAMETER (inches) FROM (feet) TO (feet) DIAMETER (inches) DIAMETER (inches)	DEPTH FROM SURFACE DIAMETER (inches) D	DEPTH FROM SURFACE DIAMETER (inches) FROM (feet) TO (feet) DIAMETER (inches) FROM (feet) DIAMETER (inches) DUTER DIAMETER (inches)	DEPTH FROM SURFACE DIAMETER (inches) DOUTER (inches) DOUTE	DEPTH FROM SURFACE DEPTH FROM SURFACE DUTER DIAMETER (inches) DUTER DIAMETER (inches)	DEPTH FROM SURFACE DEPTH FROM SURFACE DESCRIBE DESCRIBE	TO (feet) DEPTH FROM SURFACE TO (feet) DIAMETER (inches) DUTER (inches) DIAMETER (inches) DESCRIBE DESCRI	TO BOREHOLE TO Greet TO Greet	TO BOREHOLE TO (feet) TO (feet)

	400							Ir	stalled Annular Material			
	H FROM		_			25		AN	ULAR MATERIAL TYPE (T)		FIL	TER PACK
SUR	FACE	4			ш	BE	NTON	IITE				
FROM (feet)	TO (feet)	NONE	CONCRETE	NEAT CEMENT OF CEMENT GROUT	CEMENT-BENTONITE GROUT	GROUT	CHIPS	PELLETS	IF OTHER TYPE OF ANNULAR MATERIAL, DESCRIBE	SAND	GRAVEL	SIZE
0	40			X								
0	474			X								
474	490							×				
490	1220									×		6-9

DEPTH	FROM	OLOGIC LOG OF WELL	Obsel (T)
SURI	FACE	Description	Check (T) ever interval where
FROM (feet)	TO (feet)	Describe material, grain size, color, etc.	water was encountered (if known)
0	278	UPPER BASIN FILL UNIT	
278	298	MIDDLE FINE GRAINED UNIT	
298	365		
365	1220	BEDROCK OXIDE UNIT	


Well Driller Report and Well Log

WELL REGISTRATION NUMBER

SECTION 6. WELL SITE PLAN			Section 1997
NAME OF WELL OWNER	COUNTY ASSESS	SOR'S PARCEL ID NUMBER	2
Florence Copper Inc.	воок	MAP	PARCEL

- Please draw the following: (1) the boundaries of property on which the well was located; (2) the well location; (3) the locations of all septic tank systems and sewer systems on the property or within 100 feet of the well location, even if on neighboring properties; and (4) any permanent structures on the property that may aid in locating the well.
- Please indicate the distance between the well location and any septic tank system or sewer system.

		W S E
SEE ATTACH	HED MAP	1" = ft
	SEE ATTACH	SEE ATTACHED MAP



Run Date: 02/21/2018

AZ DEPARTMENT OF WATER RESOURCES **WELL REGISTRY REPORT - WELLS55**

Well Reg.No

Location D 4.0 9.0 28 C B D

55 - 227235

AMA PINAL AMA

Registered Name

AZ STATE LAND DEPT. 1616 W. ADAMS ST.

ATTN: LISA ATKINS

PHOENIX

Application/Issue Date 04/19/2017

AZ 85007

Owner OWNER

Well Type ENV - MONITOR

Driller No. 816

Driller Name HYDRO RESOURCES - ROCKY MOUNTAIN, INC.

Driller Phone 303-857-7540 County PINAL

Watershed UPPER GILA RIVER Registered Water Uses MONITORING

SubBasin ELOY

Registered Well Uses MONITOR

0.00 **Intended Capacity GPM**

Discharge Method NO DISCHARGE METHOD LISTED

Power NO POWER CODE LISTED

Well Depth

Pump Cap.

0.00

Case Diam

0.00 0.00 **Tested Cap** CRT

Log

Draw Down

0.00 0.00

Case Depth Water Level Acres Irrig

0.00 0.00

Finish NO CASING CODE LISTED

0.00

File Type NEW WELLS (INTENTS OR APPLICATIONS)

NO - NOT IN ANY REMEDIAL ACTION SITE Contamination Site:

Tribe: Not in a tribal zone

Comments NP

AZ State Land Dept. Mineral Lease #11-026500

Current Action

2/21/2018

CHANGE OF DRILLER PACKET ISSUED 869

Action Comment: NTP

Action History

2/16/2018

CHANGE OF DRILLER RECEIVED 865

Action Comment: NTP

4/25/2017

DRILLING AUTHORITY ISSUED 550 Action Comment: TNV

4/25/2017 555

DRILLER & OWNER PACKETS MAILED

Action Comment: TNV

NOI RECEIVED FOR A NEW NON-PRODUCTION WELL 155 4/19/2017

Action Comment: TNV

ARIZONA DEPARTMENT OF WATER RESOURCES 1110 W. Washington St. Suite 310 Phoenix, Arizona 85007

REISSUE

THIS AUTHORIZATION SHALL BE IN POSSESSION OF THE DRILLER DURING ALL DRILLING OPERATIONS

WELL REGISTRATION NO: 55-227235 WELL OWNER ID: 0-06

AUTHORIZED DRILLER: HYDRO RESOURCES - ROCKY MOUNTAIN, INC.

LICENSE NO: 816

NOTICE OF INTENTION TO DRILL ENV - MONITOR WELL(S) HAS BEEN FILED WITH THE DEPARTMENT BY:

WELL OWNER: AZ STATE LAND DEPT. 1616 W. ADAMS ST. ATTN: LISA ATKINS PHOENIX, AZ, 85007

THE WELL(S) IS/ARE TO BE LOCATED IN THE:

EAST Range 9.0 SE 1/4 of the NW 1/4 of the SW 1/4 Section 28 Township 4.0 SOUTH

NO. OF WELLS IN THIS PROJECT: 1

THIS AUTHORIZATION EXPIRES AT MIDNIGHT ON THE DAY OF April 19, 2018



GROUNDWATER PERMITTING AND WELLS

THE DRILLER MUST FILE A LOG OF THE WELL WITHIN 30 DAYS OF COMPLETION OF DRILLING.



ARIZONA DEPARTMENT of WATER RESOURCES

1110 W. Washington St. Suite 310 Phoenix, AZ 85007 602-771-8500 azwater.gov

February 21, 2018

AZ STATE LAND DEPT. 1616 W. ADAMS ST. ATTN: LISA ATKINS PHOENIX, AZ 85007

Registration No. 55- 227235 File Number: D(4-9) 28 CBD

Dear Well Applicant:



DOUGLAS A. DUCEY Governor

THOMAS BUSCHATZKE Director

Enclosed is a copy of the Notice of Intention to Drill (NOI) a well which you or your driller recently filed with the Department of Water Resources. This letter is to inform you that the Department has approved the NOI and has mailed, or made available for download, a drilling authorization card to your designated well drilling contractor. The driller may not begin drilling until he/she has received the authorization, and must keep it in their possession at the well site during drilling. Although the issuance of this drill card authorizes you to drill the proposed well under state law, the drilling of the well may be subject to restrictions or regulations imposed by other entities.

Well drilling activities must be completed within one year after the date the NOI was filed with the Department. If drilling is not completed within one year, a new NOI must be filed and authorization from this Department received before proceeding with drilling. If the well cannot be successfully completed as initially intended (dry hole, cave in, lost tools, etc.), the well must be properly abandoned and a Well Abandonment Completion Report must be filed by your driller [as required by A.A.C. R12-15-816(F)].

If you change drillers, you must notify the Department of the new driller's identity on a Request to Change Well Information (form 55-71A). Please ensure that the new driller is licensed by the Department to drill the type of well you require. A new driller may not begin drilling until he/she receives a new drilling authorization card from the Department.

If you find it necessary to change the location of the proposed well(s), you may not proceed with drilling until you file an amended NOI with the Department. An amended drilling authorization card will then be issued to the well drilling contractor, which must be in their possession before drilling begins.

Arizona statute [A.R.S. § 45-600] requires registered well owners to file a Pump Installation Completion Report (form 55-56) with the Department within 30 days after the installation of pumping equipment, if authorized. A blank report is enclosed for your convenience. State statute also requires the driller to file a complete and accurate Well Drillers Report and Well Log (form 55-55) within 30 days after completion of drilling. A blank report form was provided to your driller with the drilling authorization card. You should insist and ensure that all of the required reports are accurately completed and timely filed with the Department.

Please be advised that Arizona statute [A.R.S. § 45-593(C)] requires a registered well owner to notify the Department of a change in ownership of the well and/or information pertaining to the physical characteristics of the well in order to keep this well registration file current and accurate. Any change in well information or a request to change well driller must be filed on a Request to Change Well Information form (form 55-71A) that may be downloaded from the ADWR Internet website at www.azwater.gov.

Sincerely,

Groundwater Permitting and Wells Section

notan Pawer



Arizona Department of Water Resources Groundwater Permitting and Wells Section P.O. Box 36020 Phoenix, Arizona 85067-6020 (602) 771-8527 · www.azwater.gov

Request to Change Well Information

Review instructions prior to completing form in black or blue ink.

You must include with your Notice:

> check or money order for any required fee(s)

Authority for fee: A.R.S. § 45-113 and A.A.C. R12-15-104

Well ID: O-06

FILE NUMBER

WELL REGISTRATION NUMBER

Well Owner	INFORMATION		- 100			-/				
		Location of Well WELL LOCATION ADDRESS (IF ANY) / OR CROSS STREETS								
FULL NAME OF COMPANY, ORGA		WELL LOCAT	TION ADDRESS	(IF ANY) / O	R CROSS STR	REETS				
Florence Copper Company	У									
MAILING ADDRESS			RANGE (E/W)	Contract of Marketine	14-51 S.	40 ACRE	10 ACRE			
1575 W Hunt Hwy		4.0 S	9.0 E	28	SW 1/4	NW 1/4	SE 1			
CITY / STATE / ZIP CODE		LATITUDE	2 1	4 40 11.	LONGITUDE	26 '	6.35 "			
Florence, AZ 85132		33 ° Degrees	3 Minutes	1.40 "N Seconds	111 ° Degrees	26 ' Minutes	Seconds			
CONTACT PERSON NAME AND TI	TLE		LATITUDE/LOI			*GPS: Ha				
lan Ream, Senior Hydroge			USED, GEOG	RAPHIC COO		*GPS: St	urvey-Grad			
TELEPHONE NUMBER	FAX 500 074 0000	☐ NAD-83	Other (p	lease specif	(y):	Locusto	UEDE MEI			
520-374-3984	520-374-3999	BOOK	SESSOR'S PAF		BER PARCEL	IS LOCATED				
		BOOK	IVIA		1001	PINAL				
					1001	THALL				
Type of Request (CHECK C	ONE)			01	£\A/= =£=					
Change of Well Drilling		/ell Ownership			f Well Info		action ()			
(Fill out Section 2)	(Fill out Sect			(location,	use, etc.)					
	TO CHANGE WELL DRILLING					FEE \$120	per Wel			
If drilling or abandoning	a well, the Department must receiv	e this request a	nd issue aut	norization t	to the new I					
	the commencement of well drilling of	r abandonment								
Current Well Drilling Co	ntractor	New Wel	I Drilling C	ontracto	r	VIDITAL				
FULL NAME OF COMPANY, ORGA National EWP	NIZATION, OR INDIVIDUAL	FULL NAME OF COMPANY, ORGANIZATION, OR INDIVIDUAL HydroResources								
DWR LICENSE NUMBER		DWRIICEN	SE NUMBER		SE CATEGOR	Y				
823		DVVICEIOEIV	816			02 0/1120011				
TELEPHONE NUMBER (480) 558-3500	(480) 558-3525	816 A-4 TELEPHONE NUMBER (303) 857-7540								
	IT OF CHANGE OF WELL OW	NERSHIP			F	EE \$30 pe	r Well			
ezementere muzika						200000				
Previous Well Owner		New Wel	I Owner							
FULL NAME OF COMPANY, ORGA	ANIZATION, OR INDIVIDUAL	FULL NAME OF COMPANY, ORGANIZATION, OR INDIVIDUAL								
MAILING ADDRESS		MAILING ADDRESS RECEIVED								
CITY / STATE / ZIP CODE		CITY / STAT	E / ZIP CODE							
				F	EB 16 20	18				
	ITLE	CONTACT P	ERSON NAME							
CONTACT PERSON NAME AND TI				IRIZON	A DEPAR	TMENT				
	Lew	TELEDITONI	- AU IMPED		FAV					
CONTACT PERSON NAME AND TI	FAX	TELEPHONE	NUMBER	F WATE	Ŕ [^] ŘESC	URCES				

Printed: 2/16/2018 9:53:20 AM

Arizona Department of Water Resources

1110 West Washington Street, Suite 310 Phoenix AZ 85007

Customer:

BURLINGTON, MA 01803 70 BLANCHARD ROAD SUITE 204 LINDA L. DOMBRAWSKI

> Receipt #: 18-56793

Office: Engineering and Peri

Receipt Date: 02/16/2018

Sale Type: Cashier: Mail WRPXA

360.00	TOTAL:	RECEIPT TOTAL:		
				CONTRACTOR OR REISSUE
360.00	120.00	3		CHANGE OF WELL DRILLER
Ext Price	Qty Unit Price	Qty	Ref ID	Description

Payment type: CREDIT CARD

91

WRFREV

4439-12

Item No. Function Code

AOBJ

Amount Paid: \$360.00

Authorization 011621

Payment Received Date: 02/16/2018

Notes: Credit Card Payment for \$360.00 is for well registration number 55-227231, 55-227233 and 55-227235

Arizona Department of Water Resources Groundwater Permitting and Wells Section P.O. Box 36020 Phoenix, Arizona 85067-6020 (602) 771-8500 • (602) 771-8690 · www.azwater.gov ·

Notice of Intent to Drill, Deepen, or Modify a Monitor / Piezometer / Environmental Well

\$150 FEE

FILE NUMBER D(4-9)28 CBD WELL REGISTRATION NUMBER 08


	Review instructions prior to completing form in black or blue ink.
*	You must include with your Notice:

\$150 check or money order for the filing fee.
Well construction diagram, labeling all specifications listed in

Authority for fee: A.R.S.	§ 45-596 and A.A.C. R12-15-104.		4/2	5/	2017 dou		3112 30	Let	16	ر			
SECTION 1. REGISTRY	INFORMATION	7 300		11.						-	1		
To determine the location of well, ple	ase refer to the Well Registry Map (http://doi.org/10.1011/j.j.chm.)	s://gisweb	azwater.go	ov/Wel	IIRegistry/Defau	III.aspx) and	Vor Google	Earth					
(http://www.earthpoint.us/Townships			1.					W 50 V					
Well Type CHECK ONE	Proposed Action	20			of Well								
324757 575	CHECK ONE		WELL	OCAT	ION ADDRESS	(IF ANY)							
☑ Monitor	☑ Drill New Well												
☐ Piezometer	☐ Deepen APA	70.	TOWNSHIP	P(N/S)	RANGE (E/W)	SECTION	160 ACR	E 40 A	CRE	10 AC	CRE		
☐ Vadose Zone	☐ Modify	195	14.0 S	3 /	9.0 E	28	SW	W NW	1/4	SE	1/4		
☐ Air Sparging	1		COUNT	YASS	ESSOR'S PAR	CEL ID NUI		74	/4		/4		
Soil Vapor Extraction	WELL REGISTRATION NUMBER		воок	1	1	MAP		Loan	CEL	100	11		
Other (please specify):	(if Deepening or Modifying)	9	CEE	2 10/11				PAR	CEL	100	, ,		
U Other (please specify).	55 -		COUNT	Y VVHE	ERE WELL IS L								
SECTION 2. OWNER IN	FORMATION				1114/16				-	3031			
Land Owner	OMMENTON		Well	Own	er (check this	hoy if I and	Owner and I	Nell Owne	r are car	ma [7 ,		
FULL NAME OF COMPANY, ORGAN	NIZATION, OR INDIVIDUAL		FULL NA	AME O	F COMPANY,	GOVERNM	ENT AGEN	Y, OR IN	DIVIDUA	AL.	1		
AZ State Land Dept (Mine	eral Lease # 11-026500)				opper, Inc.		18-0						
MAILING ADDRESS	,		MAILING							-	_		
1616 W Adams St			1575 V	V Hu	int Hwy								
CITY / STATE / ZIP CODE					/ ZIP CODE								
Phoenix, AZ 85007					Z 85132								
CONTACT PERSON NAME AND TO			CONTAC	CT PE	RSON NAME A	ND TITLE							
Lisa Atkins, State Land Co	ommissioner		lan Re	am,	Senior Hyd	rogeolo	gist						
TELEPHONE NUMBER	FAX		TELEPH	ONE N	NUMBER		FAX		0.00				
(602) 542-4631				(520) 374-3984			(520)	374-3	3999			
SECTION 3. DRILLING A	UTHORIZATION							100					
Drilling Firm			Const	ultar	it (if applicable)							
NAME National EWP			CONSUL										
mum i laminer	ROC LICENSE		CONTAC	CT PER	drich, Inc.		_			_			
NUMBER 823	CATEGORY A-4			CONTACT PERSON NAME lark Nicholls									
TELEPHONE NUMBER (480) 558-3500	FAX 480-558-3525		TELEPHONE										
EMAIL interhancements	nalewn com		EMAIL ADDRESS mnicholls@haleyaldrich.com										
	naicwp.com		ADDRESS	5 111	incholis@i	laleyalu	ilcii.com						
SECTION 4.		I V	L N 1	-		103,12							
Questions		Yes	No		planation:	***	alal at t	-1	- 16				
 Are all annular spaces between the placement of grout at least 	the casing(s) and the borehole for 2 inches?	\boxtimes		in an	th annular space of near ground ARF, DOD, LU	water conta ST).	amination s	ites (such	as CEF	RCLA,			
Is the screened or perforated in feet in length?	terval of casing greater than 100	\boxtimes		locat	foot maximum ed in and near CLA, WQARF	groundwa	ter contami	special s nation site	andard es (such	for wel	ls		
Are you requesting a variance to of steel casing in the surface se			\boxtimes	The v	wells must be 15-801 (27) a	constructed "vault" is de	d in a vault. efined as a	tamper-re	sistant	C. watertig	ght		
4. Is there another well name or ic		V		If yes	ture used to co	14		ne land st	лпасе.				
with this well? (e.g., MW-1, PZ 5. Have construction plans been of					se state s, please state	O-06		no numb	· ·	_			
Department of Environmental C		X		Day	vid Haag, 6	602-771-	4669						
6. For monitor wells, is dedicated			\boxtimes	(Gallo	s, please state ons per Minute)								
Is this well a new well located in AND intended to pump water for groundwater?			\boxtimes	unles	must also file a s the well is a able wells on the	replaceme	nt well and	the total	number	of			
Will the well registration number on the upper part of the casing?	be stamped on the vault cover or	X		If no,	where will the	registration	n number b	e placed?					

Notice	of Intent	to Dr	ill, E	Deep	oen,	or I	Vlodi	ify a	Monitor / Pie	ezo	me	ter	/ Environme	ental V	Vell				EGIST 22		35 ION NUMBER
SECTIO	N 6. WE	LL C	ONS	STR	UCT	ION				į.	Må T			Egg	100	, III		Die			
Drill Me						4			d of Well De	vel	opi	nei	nt				lace	eme	nt N	leth	od
☐ Cab	Rotary ed or Aug le Tool I Rotary	ered					100	Sui	lift	cify)	:					nie I	e G	rout		comm	nended)
	erse Circi	ulatio	n				M		d of Sealing	190		duc	tion Points	Sur	face	or	Cor	ndu	ctor	Cas	sina
☐ Othe	ed Percussio er (please s	pecify):	Tub	ing		СН	No.	NE	32				CHEC	K ON	E h M	oun	t in	a va	ult	ve grade
DATE CON	STRUCTION 05/01						1 =		cked ner (please spe	cifv)											
SECTIO	N 7. PR	OPO	SED	WE	LL (CON	ISTF					add	itional page if r	needed	1)			10	115		SW S.
Attach a			ion (diag	ram I	abe	ling a	all sp	ecifications b	elo	w.										
DEPTH	Boreho	le	_		1	FPT	'H FRO	MC			MA	ERI	Casing AL TYPE (T)	P	ERFO	RATI	ON T	YPE	(T)		
	TO (feet)	DIA	REHO METE	ER	FRC	SUF	RFACE		OUTER DIAMETER (inches)	STEEL	PVC	ABS	IF OTHER TYPE, DESCRIBE	BLANK OR NONE WIRE WRAP	T			IF (OTHE TYPE,		SLOT SIZE IF ANY (inches)
0	20		18		0	j		20	14	X		E	- 14	X						1	
20	1210		10		0 500 5 X Pre-Force X																
					500 1200 5 🗆 🗵 🗆												\boxtimes				0.020
									Annular										-		
			T	T~	T	BE	ENTON		NNULAR MATER	IAL	IYPI	(1).						FII	LIER	PACK
FROM (feet)								PELLETS	IF C	OTHER TYPE OF ANNULAR MATERIAL, DESCRIBE								SAND	GRAVEL		SIZE
0	490			X				П													
490	495										0							X		No	o. 30-70
495	1210																	X		N	o.10-20
IF THIS WE	LL HAS NES	TED C	ASINO	SS, SI	PECIF	Y NU	MBER	OF CA	ASING STRINGS	1	EXPE	CTE	D DEPTH TO WA	TER (Fe		low G	roun	d Sun	face)		
SECTIO	N 8. PEF	RMIS	SIO	N TO) AC	CE	SS			+				Ten			TAG	RE	TE T		
	y checking neasureme								permission to	en	ter t	he	property for the	purpo	ose o	f tak	king	wate	er lev	/el	
						_			ER SIGNAT				7.05	Ti.							
I state that	this notice	is filed				_	A.R.S	§ 45	-596 and is com	plet	e an	_	rrect to the best		_		_		455		
PRINT NAME			Lai	na C	wne	r					INT	MAN	Ell Owner (if di Elan Ream,							ictions	5)
SIGNATURE		-								SIG	D TI	URE	OF T	2	, , , ,	uiu	950	Jugi	JL		
AND OWNE	IN.	_									TE	VVIV	15	4-1	7	7	7	17			
☐ By ch	ecking this		you	agree	to a	llow	ADV	JR to	contact you	×			necking this box	you a	agree					to co	intact you
EMAIL ADDRESS										EM	AIL	-	lanReam@fl	orence	ecop	per	.co	m			

CTION 5. Well Construction Diagide a well construction diagram showing a	es listed in Section 6 and Section 7	
See attached well diagram.		
dee attached well diagram.		



	ON 6. WE									162	OITE	rei	/ Environm	entai	vveli		55 -			
Drill Me		N/F		-	.00		_		d of Well D	eve	lon	me	nt	Gro	ut F	mnl	acer	ent	Matt	nod
CHECK O								HECK		CVC	юр	ine	ill.	CHEC	CKON	E	acen	ient	vietr	100
☐ Cab	ed or Aug ole Tool al Rotary d Rotary							Su		ecify	·):				Trer Grav Pres	nie F vity ssure	Gro ase sp	ut	ecomn	nended)
☐ Rev	erse Circ	ulatio	on				IV	letho	d of Sealing	at	Re	duc	tion Points	Sur	face	or C	ond	ucto	r Ca	sina
☐ Jett								HECK (Contract of the Party of the Pa	1000				CHEC		1990	ond	ucto	- Oa	Silig
Air I	Percussio	n/C	dex	Tub	ing		[No.						1000			unt i	nav	ault	
☐ Oth	er (please s	specify	v):				1 -	_	elded redged					\boxtimes	Exte	nds	at lea	st 1'	abo	ve grade
DATE CON	ISTRUCTION 05/0						1] Pa	cked											
SECTIO	N 7. PR	OPO	SEL	WE	ELL (CON	IST	RUCT	TION PLAN	(atta	ach	add	tional page if i	needed	D		100007		Opt on	
Attach a	well cons	struc	tion	diag	ram	labe	ling	all sp	ecifications	belo	w.									
DEPTI	Boreho H FROM	le				DEPT	U ED	2M	OREM E	-	144		Casing	18	16			1980	1	7 00
	FACE	4					FACI			-	MA	ERI	AL TYPE (T)	100 D			N TYP	E(T)	-	
FROM (feet)	TO (feet)	DIA	REHO AMET inches	ER	FRI (fe			TO (feet)	OUTER DIAMETER (inches)	STEEL	PVC	ABS	IF OTHER TYPE, DESCRIBE	BLANK OR NONE WIRE WRAP	SHUTTER	MILLS	티	TYPE ESCRI		SLOT SIZE IF ANY (inches)
0	20		18		()		20	14	X				X						
20	1210		10		()		500	5				(FRP)	X						
		500 1200 5															3			0.020
DEPTH	FROM			-11				A	Annula NNULAR MATER					100			_	-		
	DEPTH FROM SURFACE BENTO											7.						T	LIEK	PACK
FROM (feet)	TO (feet)	NONE	CONCRETE	NEAT CEMENT	CEMENT- BENTONITE GROUT	GROUT	CHIPS	PELLETS	IF (FOTHER TYPE OF ANNULAR MATERIAL, DESCRIBE							SAND	GRAVEL		SIZE
0	490			X							_			-		_	-			
490	495																X		No	. 30-70
495	1210																X		_	0.10-20
THIS WEL	L HAS NEST	ED CA	ASING	SS, SP	ECIFY	NUN	MBER	OF CA	SING STRINGS	E	XPE	CTE	DEPTH TO WAT	ER (Fee		w Gro	und Su	rface)		
	8. PER													E TO		-	Williams.			Shep -
By me	checking easuremen	this l	oox, this	her well.	eby p	rovio	de A	DWR	permission to	ent	er th	e p	roperty for the	purpos	se of	takin	g wa	ter lev	/el	
									ER SIGNATI							- 7			- 15-	
state that	this notice is	filed					.R.S.	§ 45-	596 and is com	plete	_	_	rect to the best				_			
INT NAME			Lan	d O	wne	r				PPI	NTN		I Owner (if diff	ferent fro	m Lar	d Owr	er; Se	e instru	ctions)
D TITLE)F				_					ANI	TIT	LE	lan Ream,	Senior	Нус	droge	eolog	ist		
ID OWNER										WEI	L O									
TE By cho	okin - ALI-				40.					DAT										
J via elec	cking this stronic mail.	box, y	ou a	gree	to al	low A	ADW	R to c	contact you	x	By via	che	cking this box, ctronic mail.	you ag	gree	to all	OW AD	WR t	o cor	ntact you
AIL DRESS										ADD		s 1	anReam@flo	rence	conr	or c	om			



Arizona Department of Water Resources

Groundwater Permitting and Wells
PO Box 36020 • Phoenix, Arizona 85067-6020 (602) 771-8527 • 602-771-8500 www.azwater.gov

Well Driller Report and Well Log

THIS REPORT MUST BE FILED WITHIN 30 DAYS OF COMPLETING THE WELL. PLEASE PRINT CLEARLY USING BLACK OR BLUE INK

FILE NUMBER D(4-9) 28 CBD WELL REGISTRATION NUMBER

55 - 227235

PERMIT NUMBER (IF ISSUED)

1616 W. ADAMS ST. CITY / STATE / ZIP PHOENIX, AZ, 85007 CONTACT PERSON NAME AND TITLE METHOD OF LATITUDE/LONGITUDE (CHECK ONE) GPS: Hand-Held Conventional Survey TELEPHONE NUMBER 602 542-4631 WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.) O-06 METHOD OF ELEVATION AT WELL METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held Conventional Survey "IF GPS: Was USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) NAD-83 Other (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK METHOD OF Sealing CHECK ONE GHECK ONE Air Rotary Airlift Bored or Augered Air Rotary Bored or Augered Cable Tool Surge Block Surge Pump LATITUDE NETHOD OF LETITUDE/LONGITUDE (CHECK ONE) TO DEGREE NINUTES SECONDS NETHOD OF LEVATION AT WELL CONVENTION AT WELL CONVENTION AT WELL CONVENTION AT WELL CONVENTION OF SEALONS NAD-83 Other (please specify) CHECK ONE CHECK ONE Airlift None Bail Packed Swedged Swedged Welded	_	1. DRILLING	AUTHUR	RIZATION												
HYDRO RESOURCES - ROCKY MOUNTAIN, INC. ADDRESS ADDRESS 13027 COUNTY ROAD 18, UNIT C CITY / STATE / ZIP FORT LUPTON, CO, 80621-9217 SECTION 1. REGISTRY INFORMATION Well Owner Location of Well FELL NAME OF COMPANY, ORGANIZATION, OR INDIVIDUAL AZ STATE LAND DEPT. MILLINA ADDRESS TOWNSHIP (NIS) PEGREES MINUTES EGREES MINUTES EGREES MINUTES SECTION 1. BEGTION 160 ACI 160 ACI 1616 W. ADAMS ST. CITY / STATE / ZIP PHOENIX, AZ, 85007 CONTACT PERSON NAME AND TITLE METHOD OF LATITUDE/LORITUDE/LORITUDE/CONGITUDE (CHECK ONE) GPS: Hand-Held CONVENTION AT WELL WELL NAME (e.g., MW-1, P.Z.3, Iol 25 Well, Smith Well, etc.) O-06 METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held CONVENTION ASSESSOR'S PARCEL ID SOOK METHOD OF ADDRESS SECTION ASSESSOR'S PARCEL ID GPS: Hand-Held CONVENTION ASSESSOR'S PARCEL ID SOOK METHOD OF ADDRESS SECTION ASSESSOR'S PARCEL ID GPS: Hand-Held CONVENTION ASSESSOR'S PARCEL ID GOOK METHOD OF ADDRESS SECTION ASSESSOR'S PARCEL ID GPS: Hand-Held CONVENTION ASSESSOR'S PARCEL ID GOOK METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held CONVENTION ASSESSOR'S PARCEL ID GOOK METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held CONVENTION ASSESSOR'S PARCEL ID GOOK METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held CONVENTION ASSESSOR'S PARCEL ID GOOK METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held CHECK ONE GPS: Hand-Held CONVENTION ASSESSOR'S PARCEL ID GOOK METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held CONVENTION ASSESSOR'S PARCEL ID GOOK METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held CHECK ONE GPS: Hand-Held CHECK ONE GPS: Hand-Held CHECK ONE GPS: Hand-Held CHECK ONE GPS: Hand-Held CONTENTION OF THE C	_					DWP LICENSE NUM	IDED									
ADDRESS 13027 COUNTY ROAD 18, UNIT C GTY / STATE / 2IP FORT LUPTON, CO, 80621-9217 SECTION 1. REGISTRY INFORMATION Well Owner Location of Well FULL NAME OF COMPANY, ORGANIZATION, OR INDIVIDUAL AZ STATE LAND DEPT. MILLING ADDRESS 1616 W. ADAMS ST. CITY / STATE / 2IP PHOENIX, AZ, 85007 CONTACT PERSON NAME AND TITLE METHOD OF LATITUDEL, ONGITUDE (CHECK ONE) GOSS. Hand-Held Conventional Survey TELEPHONE NUMBER 602 542-4631 WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.) O-06 METHOD OF ELEVATION AT WELL METHOD OF ELEVATION (CHECK ONE) GOSS. Hand-Held Conventional Survey TIFLE PHONE NUMBER 602 542-4631 WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.) O-07 SECTION 3. WELL CONSTRUCTION DETAILS Drilling Method Method of Well Development Method of Sealing CHECK ONE GONE GOTOR ALIGN BBII GOTOR ALIGN GOTOR			PCES PC	OCKA WOLINI	TAIN INC		IDEK									
SECTION 1. REGISTRY INFORMATION Well Owner FULL NAME OF COMPANY, ORGANIZATION, OR INDIVIDUAL AZ STATE LAND DEPT. MAILING ADDRESS 1616 W. ADAMS ST. CITY / STATE / ZIP HOPINIAN ADDRESS 1616 W. ADAMS ST. CITY / STATE / ZIP HOPINIAN ADDRESS 1616 W. ADAMS ST. CITY / STATE / ZIP HOPINIAN ADDRESS 1616 W. ADAMS ST. LATITUDE METHOD OF LATITUDEALONGITUDE (CHECK ONE) GOZ 542-4631 WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.) O-06 METHOD OF ELEVATION AT WELL METHOD OF LATTURE AND AT WELL METHOD OF LATTURE AND AT WELL METHOD OF LATTURE AND AT WELL METHOD OF LATTURE	-		NCES - NC	JCKT WOON	TAIN, INC.	-	-									
SECTION 1. REGISTRY INFORMATION Well Owner FULL NAME OF COMPANY, ORGANIZATION, OR INDIVIDUAL AZ STATE LAND DEPT. MAILING ADDRESS 1616 W. ADAMS ST. CITY / STATE / ZIP HOPIONIX, AZ, 85007 CONTACT PERSON NAME AND TITLE METHOD OF LATITUDEALONGITUDE (CHECK ONE) GODG SAMELL CONSTRUCTION DETAILS DITIIING Method Method of Well Development Method of Sealing CHECK ONE GODG ALITICALS Method of Well Development Method of Sealing CHECK ONE GODG ALITICALS Method of Well Development Method of Sealing CHECK ONE GODG ALITICALS Method of Well Development Method of Sealing CHECK ONE GODG ALITICALS Method of Well Development Method of Sealing CHECK ONE GODG ALITICALS Method of Well Development Method of Sealing CHECK ONE GODG ALITICALS Method of Well Development Method of Sealing CHECK ONE GODG ALITICALS Method of Well Development Method of Sealing CHECK ONE GODG ALITICALS Method of Well Development Method of Sealing CHECK ONE GODG ALITICALS Method of Well Development Method of Sealing CHECK ONE GODG ALITICALS Method of Well Development Method of Sealing CHECK ONE GODG ALITICALS Method of Well Development Method of Sealing CHECK ONE GODG ALITICALS Method of Well Development Method of Sealing CHECK ONE GODG ALITICALS Method of Well Development Method of Sealing CHECK ONE GODG ALITICALS Method of Well GODG ALITICALS Method of Well GODG ALITICALS METHOD OF ELEVATION (CHECK ONE) GODG ALITICALS METHOD OF ELEVATION (CHECK ONE) GODG ALITICALS METHOD OF LATITUDEALONGITUDE (CHECK ONE) GODG ALITICALS TO MACHONICALS TO MACHONICALS METHOD OF LATITUDEALONGITUDE (CHECK ONE) GODG ALITICALS TO MACHONICALS TO MACHONICALS TO MACHONICALS METHOD OF LATITUDEALONGITUDE (CHECK ONE) GODG ALITICALS T			DO 4 D 40	LINUT			ER									
SECTION 1. REGISTRY INFORMATION Well Owner LUCATION ADDRESS (IF ANY) MILLIAMS DEPT. MILLIAMS DEPT. MILLIAMS ADDRESS 1616 W. ADAMS ST. CONTACT PERSON NAME AND TITLE METHOD OF LATITUDEL CONSTRUCTION DETAILS DITIING Method of Well Development METHOD OF LEVATION (CHECK ONE) "IF GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) "OBOR Hand-Held CHECK ONE) "IF GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) "OBOR Hand-Held CHECK ONE) "IF GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) "OBOR Hand-Held CHECK ONE) "IF GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) "OHOR (PIRASS PARCEL ID BOOK METHOD OF LATITUDE) SECTION 3. WELL CONSTRUCTION DETAILS DITIING Method Method of Well Development CHECK ONE AIF ROTATY ASSESSOR'S PARCEL ID BOIL AIF ROTATY Bord or Augered Salli CHECK ONE AIF ROTATY AIF ROTATY DUAL ROTATY MULL CONSTRUCTION SUrge Plump Other (please specify) Convertional Survey CHECK ONE CHECK ONE OTHER CHE	_		ROAD 18,	UNITC		303-657-7540										
SECTION 1. REGISTRY INFORMATION Well Owner FULL NAME OF COMPANY, ORGANIZATION, OR INDIVIDUAL AZ STATE LAND DEPT. MAILING ADDRESS 1616 W. ADAMS ST. CITY / STATE / ZIP PHOENIX, AZ, 85007 CONTACT PERSON NAME AND TITLE METHOD OF LATITUDEL/LONGITUDE (CHECK ONE) TELEPHONE NUMBER 602 542-4631 WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.) O-06 SECTION 3. WELL CONSTRUCTION DETAILS DIIling Method Method of Well Development METHOD OF LEVATION (CHECK ONE) TIP GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) NAD-83 Other (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK METHOD OF LEVATION (CHECK ONE) TIP GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) NAD-83 Other (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK METHOD OF LEVATION (CHECK ONE) TIP GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) ASSESSOR'S PARCEL ID BOOK METHOD OF LEVATION (CHECK ONE) TIP GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) ASSESSOR'S PARCEL ID BOOK METHOD OF LEVATION (CHECK ONE) TIP GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) ASSESSOR'S PARCEL ID BOOK METHOD OF LEVATION (CHECK ONE) TIP GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) ASSESSOR'S PARCEL ID BOOK METHOD OF LEVATION (CHECK ONE) TIP GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) ASSESSOR'S PARCEL ID BOOK METHOD OF LEVATION (CHECK ONE) TIP GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) TIP GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) TIP GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) TIP GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) TIP GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) TIP GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) TIP GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) TO WASHINGTON OR TIP GRAPH OR T			00 00004	0047		FAX										
Vell Owner																
FULL NAME OF COMPANY, ORGANIZATION, OR INDIVIDUAL AZ STATE LAND DEPT. MAILING ADDRESS TOWNSHIP (N/S) RANGE (EW) SECTION 160 ACI 1616 W. ADAMS ST. CITY / STATE / ZIP PHOENIX, AZ, 85007 CONTACT PERSON NAME AND TITLE METHOD OF LATITUDE/ GPS: Hand-Held Conventional Survey TELEPHONE NUMBER FAX LAND SURFACE ELEVATION (CHECK ONE) GPS: Hand-Held Conventional Survey WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.) O-06 WETHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held Conventional Survey "IF GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) NAD-83 Ofther (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK Method of Well Development CHECK ONE Air Rotary Bored or Augered Cable Tool Gair Rotary Borl Rotary Bail GHECK ONE Cable Tool Gair Rotary Mud Rotary Check One Check On	_	CONTRACTOR OF THE PARTY OF THE	Y INFOR	MATION												
AZ STATE LAND DEPT. MAILING ADDRESS 1616 W, ADAMS ST. CITY / STATE / ZIP PHOENIX, AZ, 85007 CONTACT PERSON NAME AND TITLE CONTACT PERSON NAME AND TITLE TELEPHONE NUMBER 602 542-4631 WELL NAME (e.g., MW-1, P.Z.3, lot 25 Well, Smith Well, etc.) O-06 SECTION 3. WELL CONSTRUCTION DETAILS Drilling Method CHECK ONE Air Rotary Borner Borner Cable Tool Cable Tool Dual Rotary Meverse Circulation Driven Condition of Well Construction Date Check ONE Check ONE Check ONE Condition of Well Construction Date Check ONE Check ONE Check ONE Check ONE Condition of Well Construction Date Check ONE Check ONE Condition of Well Construction Date Check ONE Check ONE Condition of Well Construction Date Check ONE Check ONE Condition of Well Construction Date Check ONE Check ONE Check ONE Condition of Well Construction Date Check ONE Check ONE Condition of Well Construction Date Check ONE Check ONE Condition of Well Construction Date Check ONE Check ONE Check ONE Check ONE Condition of Well Construction Date Check ONE Check ONE Check ONE Check ONE Check ONE Condition of Well Construction Date Check ONE Check ONE Check ONE Check ONE Check ONE Check ONE Condition of Well Construction Date Check ONE Check ONE Check ONE Check ONE Check ONE Check ONE Condition of Well Construction Date Check ONE C																
MAILING ADDRESS 1616 W. ADAMS ST. 1616 W. ADAMS ST. 1617 / STATE / ZIP PHOENIX, AZ, 85007 CONTACT PERSON NAME AND TITLE METHOD OF LATITUDE/LONGITUDE (CHECK ONE)			NIZATION, OF	RINDIVIDUAL		WELL LOCATION AD	DRESS (I	IF ANY)								
1616 W. ADAMS ST. CITY / STATE / ZIP PHOENIX, AZ, 85007 CONTACT PERSON NAME AND TITLE METHOD OF LATITUDE/LONGITUDE (CHECK ONE) GPS: Hand-Held Conventional Survey TELEPHONE NUMBER 602 542-4631 WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.) O-06 METHOD OF ELEVATION AT WELL METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held Conventional Survey "IF GPS: WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) NAD-83 Other (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held Conventional Survey "IF GPS: WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) NAD-83 Other (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held Conventional Survey "IF GPS: WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) NAD-83 Other (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK METHOD OF ELEVATION (CHECK ONE) NAD-83 Other (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK METHOD OF ELEVATION (CHECK ONE) NAD-83 Other (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK METHOD OF ELEVATION (CHECK ONE) NAD-83 Other (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK METHOD OF ELEVATION (CHECK ONE) NAD-83 Other (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK METHOD OF ELEVATION (CHECK ONE) NAD-83 Other (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK METHOD OF ELEVATION (CHECK ONE) NAD-83 OTHER (PLECK ONE) NAD-84 OTHER (PLECK ONE) OTHER	_	THE PERSON NAMED IN THE PE														
CITY / STATE / ZIP PHOENIX, AZ, 85007 CONTACT PERSON NAME AND TITLE METHOD OF LATITUDE/LONGITUDE (CHECK ONE) GPS: Hand-Held Conventional Survey TELEPHONE NUMBER 602 542-4631 WELL NAME (e.g., MW-1, P2-3, lot 25 Well, Smith Well, etc.) O-06 METHOD OF ELEVATION AT WELL METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held Conventional Survey "F GPS: Hand-Held Convent						TOWNSHIP (N/S)	RAN	IGE (E/W)	SECTION	160 ACRE	40 ACRE	10 ACRE				
PHOENIX, AZ, 85007 DEGREES MINUTES SECONDS DEGREE CONTACT PERSON NAME AND TITLE METHOD OF LATITUDE/LONGITUDE (CHECK ONE) GPS: Hand-Held Conventional Survey TELEPHONE NUMBER 602 542-4631 WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.) O-06 METHOD OF ELEVATION AT WELL METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held Conventional Survey "IF GPS: Was USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) NAD-83 Other (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK METHOD OF SELEVATION CHECK ONE) ASSESSOR'S PARCEL ID BOOK METHOD OF SELEVATION CHECK ONE AIR ROTATION CHECK ONE CHECK ONE AIR ROTATION CHECK ONE CONSTRUCTION CONSTRUCTION CONSTRUCTION CONSTRUCTION CHECK ONE CONSTRUCTION CHECK ONE CHECK ONE CONSTRUCTION CONSTRUCTION CHECK ONE CONSTRUCTION CHECK ONE CONSTRUCTION CHECK ONE CHECK	D	AMS ST.								1/4	1/4	1/				
PHOENIX, AZ, 85007 DEGREES MINUTES SECONDS DEGREI CONTACT PERSON NAME AND TITLE METHOD OF LATITUDE/LONGITUDE (CHECK ONE) GOZ 542-4631 WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.) O-06 METHOD OF ELEVATION AT WELL LAND SURFACE ELEVATION AT WELL METHOD OF ELEVATION (CHECK ONE) GOZ 542-4631 WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.) O-06 METHOD OF ELEVATION (CHECK ONE) GOZ 542-4631 METHOD OF ELEVATION (CHECK ONE) GOZ 542-4631 METHOD OF ELEVATION (CHECK ONE) GOZ 542-4631 METHOD OF ELEVATION (CHECK ONE) GOZ 642-4631 METHOD OF LEVATION (CHECK ONE) GOZ 642-4631 METHOD OF LEVATION AT WELL METHOD OF LEVATION AT WELL GOZ 642-4631 METHOD OF LEVATION AT WELL GOZ 642-4631 METHOD OF LEVATION AT WELL GOUNTY ASSESSOR'S PARCEL ID BOOK METHOD OF LEVATION AT WELL GOL 64-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-	1	ZIP							"N	LONGITUDE		-				
TELEPHONE NUMBER FAX LAND SURFACE ELEVATION AT WELL WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.) O-06 WETHOD OF ELEVATION (CHECK ONE) "IF GPS: Hand-Held	, /	AZ, 85007					МІ	INUTES		DEGREES	MINUTES	SECONDS				
TELEPHONE NUMBER 602 542-4631 WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.) O-06 METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held Conventional Survey "IF GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ONE) NAD-83 Other (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK M Method of Well Development Method of Sealing CHECK ONE Air Rotary Airlifft None Bord or Augered Sail Cable Tool Surge Block Surge Block Dual Rotary Surge Pump Welded Mud Rotary Other (please specify) Mud Rotary Other (please specify) Condition of Well Construction Date Condition of Well Construction Date Check One Check O	ER	SON NAME AND TIT	TLE			METHOD OF LATITU	DE/LONG	SITUDE (CHEC	K ONE)							
WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.) O-06 METHOD OF ELEVATION (CHECK ONE) GPS: Hand-Held						*GPS: Hand-Held		Conv	rentional Survey		*GPS: Surv	ey-Grade				
WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.) O-06 *GPS: Hand-Held	N	UMBER	F	AX		LAND SURFACE ELE	VATION	AT WELL								
O-06 *GPS: Hand-Held Conventional Survey	02 542-4631										Feet Abo	ve Sea Level				
O-06 *GPS: Hand-Held Conventional Survey	WELL NAME (e.g., MW-1, PZ-3, lot 25 Well, Smith Well, etc.)						TION (CH	ECK ONE)								
*IF GPS WAS USED, GEOGRAPHIC COORDINATE DATUM (CHECK ON NAD-83 Other (please specify) COUNTY ASSESSOR'S PARCEL ID BOOK M. **METHOD METHOD M								_	antinual Common		—					
NAD-83 Other (please specify)								Conv	rentional Survey		*GPS: Surv	ey-Grade				
SECTION 3. WELL CONSTRUCTION DETAILS Drilling Method CHECK ONE CHECK ONE CAIR Rotary Bored or Augered Cable Tool Dual Rotary Mud Rotary Mud Rotary Mud Rotary Check one Check o	ī					*IF GPS WAS USED,	GEOGRA	APHIC COORD	INATE DATUM (CHECK ONE)						
SECTION 3. WELL CONSTRUCTION DETAILS Drilling Method CHECK ONE CONDITION CONSTRUCTION CONSTRUCTION CAPPED AIR PERCURSION / Odex Tubing COUNTY ASSESSOR'S PARCEL ID BOOK M MEthod of Sealing CHECK ONE CHECK						□NAD-83 □O	ther (pleas	se specify)								
SECTION 3. WELL CONSTRUCTION DETAILS Drilling Method							inor (produc	1	ASSESSOR'S PARCEL ID NUMBER (MOST RECENT							
SECTION 3. WELL CONSTRUCTION DETAILS Drilling Method						COUNTY										
Drilling Method Method of Well Development Method of Sealing CHECK ONE CHECK ONE CHECK ONE ☐ Air Rotary ☐ Airlift ☐ None ☐ Bail ☐ Packed ☐ Cable Tool ☐ Surge Block ☐ Swedged ☐ Dual Rotary ☐ Other (please specify) ☐ Other (please specify) ☐ Reverse Circulation ☐ Other (please specify) ☐ Other (please specify) ☐ Driven Condition of Well Construction Date ☐ Jetted CHECK ONE ☐ DATE WELL CONSTRUCTION ☐ Air Percussion / Odex Tubing ☐ Capped									BOOK	MAP	PA	RCEL				
Drilling Method Method of Well Development Method of Sealing	-	. WELL CO	NOTPHO	TION DET												
CHECK ONE Air Rotary Bored or Augered Cable Tool Dual Rotary Mud Rotary Reverse Circulation Driven Jetted Air Percussion / Odex Tubing CHECK ONE Airlift None Packed Surge Block Surge Block Surge Pump Other (please specify) Condition of Well Construction Date CHECK ONE CHECK ONE DATE WELL CONSTRUCTION			NSTRUC	TION DETA		II Dovolonment	-		Anthod of 9	Cooling at I	Poduction	Dointo				
Air Rotary Bored or Augered Bail Cable Tool Surge Block Surge Pump Welded Mud Rotary Cother (please specify) Condition of Well Construction Driven Air Percussion / Odex Tubing Airlift None None None None None None None None	ne	etriou				ii Developinent										
Bored or Augered Cable Tool Dual Rotary Mud Rotary Reverse Circulation Driven Jetted Air Percussion / Odex Tubing Bail Packed Swedged Swedged Other (please specify) Condition of Well Construction Date DATE WELL CONSTRUCTION Capped					727											
□ Cable Tool □ Surge Block □ Welded □ Dual Rotary □ Other (please specify) □ Other (please specify) □ Reverse Circulation □ Other (please specify) □ Other (please specify) □ Driven □ Condition of Well Construction Date □ Jetted □ CHECK ONE □ DATE WELL CONSTRUCTION □ Air Percussion / Odex Tubing □ Capped		•														
□ Dual Rotary □ Surge Pump □ Other (please specify) □ Mud Rotary □ Other (please specify) □ Other (please specify) □ Reverse Circulation □ Condition of Well Construction Date □ Date Well Construction □ DATE WELL CONSTRUCTION □ Air Percussion / Odex Tubing □ Capped																
☐ Mud Rotary ☐ Other (please specify) ☐ Reverse Circulation ☐ Condition of Well ☐ Driven ☐ Check one ☐ Jetted ☐ Check one ☐ Air Percussion / Odex Tubing ☐ Capped									1							
Reverse Circulation Driven Condition of Well Check one Air Percussion / Odex Tubing Condition of Well Check one Capped	□ Dual Rotary □ Surge Pump □ Mud Rotary □ Other (please □ Reverse Circulation □ Condition of V					:6.3			☐ Welded☐ Other (please specify)							
□ Driven Condition of Well Construction Date □ Jetted CHECK ONE DATE WELL CONSTRUCTION □ Air Percussion / Odex Tubing □ Capped						specify)										
☐ Jetted CHECK ONE DATE WELL CONSTRUCTION ☐ Air Percussion / Odex Tubing ☐ Capped						Well		-	Construction	n Dates		4 544				
Air Percussion / Odex Tubing Capped										Telling to the original	ARTED					
		osion / Oday Tu	hina								100					
☐ Other (please specify) ☐ Pump Installed ☐ DATE WELL CONSTRUCTION			ibilig						ATE WELL COM	STRUCTION CO	MDIETED					
	IE	ease specity)			☐ Pump Installe	d			ATE WELL CON	STRUCTION CC	MILLETED					
	_															
I state that this notice is filed in compliance with A.R.S. § 45-596 and is complete and correct to the best of my knowledge and belie	+1	his notice is files	d in compli	ance with A E	C & 45-506 and in	complete and corre	ot to the	host of m	knowlodgo	and haliaf						
	-			ance with A.R		complete and corre	ci io ine			and beller.						
IGNATURE OF QUALIFYING PARTY DATE	- (QUALIFYING PARTY	r					DAT	E							

Well Driller Report and Well Log

WELL REGISTRATION NUMBER 55 - 227235

Depth				
DEPTH OF BORING		DEPTH OF	COMPLETED WELL	
	Feet Below Land S	Surface		Feet Below Land Surface
Water Level Information				
		TIME MEASURED	IF FLOWING WELL, METHOD OF FLOW REGULATION	
STATIC WATER LEVEL	DATE MEASURED	TIME MEASURED	IF FLOWING WELL, METHOD OF FLOW REGULATION	

	Boreh	ole						In	stalled Casi	ng						
DEF FRO SURF	MC MC		DEF FRO SURF	MC			MATER				PERF	ORATIO	ON TYP	PE (X	()	
FROM (feet)	TO (feet)	BOREHOLE DIAMETER (inches)	FROM (feet)	TO (feet)	OUTER (inches)	STEEL	PVC	ABS	IF OTHER TYPE, DESCRIBE	BLANK OR NONE	WIRE WRAP	SHUTTER SCREEN	MILLS KNIFE	SLOTTED	IF OTHER TYPE, DESCRIBE	SLOT SIZE (inches)

				, LI == 7	A Septiment				stalled Annular Material					
DEPTH	FROM							ANNUL	AR MATERIAL TYPE (X)		FILTER PACK			
SUR	FACE				ш	В	ENTON	NITE						
FROM (feet)	TO (feet)	NONE	CONCRETE	NEAT CEMENT OR CEMENT GROUT	CEMENT-BENTONITE GROUT	GROUT	CHIPS	PELLETS	IF OTHER TYPE OF ANNULAR MATERIAL, DESCRIBE	SAND	GRAVEL	SIZE		

WELL REGISTRATION NUMBER 55 - 227235

SECT	TION 5. C	GEOLOGIC LOG OF WELL	
DEPTH FRO FROM (feet)	TO (feet)	Description Describe material, grain size, color, etc.	Check (X) every interval where water was encountered (if known)
			4

SECTION 6. WELL SITE PLAN			Except State District
NAME OF WELL OWNER	COUNTY ASSESSOR'S PARCE	EL ID NUMBER (MOST RECENT	n
AZ STATE LAND DEPT.	воок	MAP	PARCEL

- Required for all wells, please draw the following: (1) the boundaries of property on which the well was located; (2) the well location; (3) the locations of all septic tank systems and sewer systems on the property or within 100 feet of the well location, even if on neighboring properties; and (4) any permanent structures on the property that may aid in locating the well.
- Please indicate the distance between the well location and any septic tank system or sewer system.



Run Date: 04/25/2017

AZ DEPARTMENT OF WATER RESOURCES WELL REGISTRY REPORT - WELLS55

Well Reg.No

Location D 4.0 9.0 28 C B D

55 - 227235

AMA PINAL AMA

Registered

AZ STATE LAND DEPT.

Name

1616 W. ADAMS ST.

ATTN: LISA ATKINS

PHOENIX

AZ 85007

File Type NEW WELLS (INTENTS OR APPLICATIONS)

Application/Issue Date 04/19/2017

Owner OWNER

Driller No. 823

Driller Name NATIONAL EWP, INC.

Driller Phone 480-558-3500

County PINAL

Well Type ENV - MONITOR

SubBasin ELOY

Watershed UPPER GILA RIVER

Registered Water Uses MONITORING

Registered Well Uses MONITOR

Discharge Method NO DISCHARGE METHOD LISTED

Power NO POWER CODE LISTED

Intended Capacity GPM

0.00

Case Diam 0.00 **Tested Cap** 0.00

Pump Cap. 0.00 Case Depth 0.00 CRT 0.00 Water Level 0.00

Draw Down Log Acres Irrig 0.00 Finish NO CASING CODE LISTED

Contamination Site: NO - NOT IN ANY REMEDIAL ACTION SITE

0.00

Tribe: Not in a tribal zone

Comments Well O-06

AZ State Land Dept. Mineral Lease #11-026500

Current Action

Well Depth

4/25/2017

DRILLER & OWNER PACKETS MAILED 555

Action Comment: TNV

Action History

4/25/2017

DRILLING AUTHORITY ISSUED 550

Action Comment: TNV

4/19/2017

155 NOI RECEIVED FOR A NEW NON-PRODUCTION WELL

Action Comment: TNV

ARIZONA DEPARTMENT OF WATER RESOURCES 1110 W. Washington St. Suite 310 Phoenix, Arizona 85007

THIS AUTHORIZATION SHALL BE IN POSSESSION OF THE DRILLER DURING ALL DRILLING OPERATIONS

WELL REGISTRATION NO: 55-227235 WELL OWNER ID: O-06

AUTHORIZED DRILLER: NATIONAL EWP, INC.

LICENSE NO: 823

NOTICE OF INTENTION TO DRILL ENV - MONITOR WELL(S) HAS BEEN FILED WITH THE DEPARTMENT BY:

WELL OWNER: AZ STATE LAND DEPT. 1616 W. ADAMS ST. ATTN: LISA ATKINS PHOENIX, AZ, 85007

THE WELL(S) IS/ARE TO BE LOCATED IN THE:

SE 1/4 of the NW 1/4 of the SW 1/4 Section 28 Township 4.0 SOUTH Range 9.0 EAST

NO. OF WELLS IN THIS PROJECT: 1

THIS AUTHORIZATION EXPIRES AT MIDNIGHT ON THE DAY OF April 19, 2018

Sulla murillo

GROUNDWATER PERMITTING AND WELLS

THE DRILLER MUST FILE A LOG OF THE WELL WITHIN 30 DAYS OF COMPLETION OF DRILLING.



ARIZONA DEPARTMENT of WATER RESOURCES 1110 W. Washington St. Suite 310

Phoenix, AZ 85007 602-771-8500 azwater.gov

April 25, 2017

AZ STATE LAND DEPT. 1616 W. ADAMS ST. ATTN: LISA ATKINS PHOENIX, AZ 85007

Registration No. 55- 227235 File Number: D(4-9) 28 CBD

Dear Well Applicant:



DOUGLAS A. DUCEY Governor

THOMAS BUSCHATZKE Director

Enclosed is a copy of the Notice of Intention to Drill (NOI) a well which you or your driller recently filed with the Department of Water Resources. This letter is to inform you that the Department has approved the NOI and has mailed, or made available for download, a drilling authorization card to your designated well drilling contractor. The driller may not begin drilling until he/she has received the authorization, and must keep it in their possession at the well site during drilling. Although the issuance of this drill card authorizes you to drill the proposed well under state law, the drilling of the well may be subject to restrictions or regulations imposed by other entities.

Well drilling activities must be completed within one year after the date the NOI was filed with the Department. If drilling is not completed within one year, a new NOI must be filed and authorization from this Department received before proceeding with drilling. If the well cannot be successfully completed as initially intended (dry hole, cave in, lost tools, etc.), the well must be properly abandoned and a Well Abandonment Completion Report must be filed by your driller [as required by A.A.C.

If you change drillers, you must notify the Department of the new driller's identity on a Request to Change Well Information (form 55-71A). Please ensure that the new driller is licensed by the Department to drill the type of well you require. A new driller may not begin drilling until he/she receives a new drilling authorization card from the Department.

If you find it necessary to change the location of the proposed well(s), you may not proceed with drilling until you file an amended NOI with the Department. An amended drilling authorization card will then be issued to the well drilling contractor, which must be in their possession before drilling begins.

Arizona statute [A.R.S. § 45-600] requires registered well owners to file a Pump Installation Completion Report (form 55-56) with the Department within 30 days after the installation of pumping equipment, if authorized. A blank report is enclosed for your convenience. State statute also requires the driller to file a complete and accurate Well Drillers Report and Well Log (form 55-55) within 30 days after completion of drilling. A blank report form was provided to your driller with the drilling authorization card. You should insist and ensure that all of the required reports are accurately completed and timely filed with the Department.

Please be advised that Arizona statute [A.R.S. § 45-593(C)] requires a registered well owner to notify the Department of a change in ownership of the well and/or information pertaining to the physical characteristics of the well in order to keep this well registration file current and accurate. Any change in well information or a request to change well driller must be filed on a Request to Change Well Information form (form 55-71A) that may be downloaded from the ADWR Internet website at www.azwater.gov.

Sincerely,

Groundwater Permitting and Wells Section

Arizona Department of Water Resources Groundwater Permitting and Wells Section P.O. Box 36020 Phoenix, Arizona 85067-6020 (602) 771-8500 • (602) 771-8690 · www.azwater.gov ·

\$150 Notice of Intent to FEE Drill, Deepen, or Modify a

Monitor / Piezometer / Environmental Well

Review instructions prior to completing	form	in	black	or	blue	ink

You must include with your Notice:

\$150 check or money order for the filing fee.

Well construction diagram, labeling all specifications listed in Section 6 and Section 7. Authority for fee: A.R.S. § 45-596 and A.A.C. R12-15-104.


Pine!	PIN II	FILE NUMBER
4/19/2017	OB UCR	WELL REGISTRATION NUMBER
4/25/2017	REMEDIAL ACTION SITE	55 - 227235


SECTION 1. REGISTRY I									
To determine the location of well, plea (http://www.earthpoint.us/Townships.a	se refer to the Well Registry Map (http://www.	os://gisweb	.azwater.gov	//WellRegistry/De	efault.aspx) and	d/or Google Ear	th		
Well Type	Proposed Action		Locati	on of Well					
CHECK ONE	CHECK ONE		100000000000000000000000000000000000000	CATION ADDRE	SS (IF ANY)			_	
☑ Monitor	☑ Drill New Well		100						
☐ Piezometer	☐ Deepen APA		TOWNSHIP	N/S) RANGE (E/	W) SECTION	160 ACRE	40 ACRE	10 AC	RE
☐ Vadose Zone	☐ Madifi	192	MAN S	9.0 E	28	0111		100000000	
Towns of the Control	☐ Modify	41	COUNTY	ASSESSOR'S F		/4	NW 1/4	SE	1/4
☐ Air Sparging ☐ Soil Vapor Extraction	WELL REGISTRATION NUMBER		COUNTY	ASSESSUR'S F	ARCEL ID NO	MBEK	1		
	(if Deepening or Modifying)		воок		MAP		PARCEL	100	1
Other (please specify):	55 -		COUNTY	WHERE WELL			·		
				PIN	IAL				
SECTION 2. OWNER INF	ORMATION								
Land Owner			Well O	wner (check t	his box if Land	Owner and Wel	l Owner are san	ne 🗆)
FULL NAME OF COMPANY, ORGANI			FULL NAM	ME OF COMPAN	IY, GOVERNM	ENT AGENCY,	OR INDIVIDUA	L	
AZ State Land Dept (Miner	rai Lease # 11-026500)			e Copper, I	nc.				-
1616 W Adams St			Section of the sectio	ADDRESS					
CITY / STATE / ZIP CODE				Hunt Hwy					
Phoenix, AZ 85007			The second second second	ATE / ZIP CODE e, AZ 85132					
CONTACT PERSON NAME AND TITL	E	-	CONTACT	F PERSON NAM	F AND TITLE				-
Lisa Atkins, State Land Cor	mmissioner		Propries and the control of the	m, Senior F		nist			
TELEPHONE NUMBER	FAX			NE NUMBER	iyarogcolo	FAX			
(602) 542-4631	1000			520) 374-39	84	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	520) 374-3	999	
SECTION 3. DRILLING A	UTHORIZATION								
Drilling Firm			Consu	Itant (if applica	able)			-	
NAME National EWP			CONSULT	ING FIRM				_	-
DIAM HOENES	DOC HOENCE		Haley &	Aldrich, Inc					
DWR LICENSE NUMBER 823	ROC LICENSE CATEGORY A-4		Mark Ni						
TELEPHONE (480) 558-3500	FAX 480-558-3525		TELEPHON	(F	60-2423	FAX COL	700 0440		
EMAIL	100 000 0020		NUMBER EMAIL		2.6.000.1.000		2-760-2448		
ADDRESS jstephens@nation	alewp.com		ADDRESS	mnicholls	@haleyald	rich.com			
SECTION 4.									
Questions		Yes	No	Explanation	n:				
Are all annular spaces between the placement of grout at least 2	the casing(s) and the borehole for inches?	\boxtimes		2-inch annular s n and near grou WQARF, DOD,	indwater cont	ecial standards amination sites	required for w (such as CER	ells loca CLA,	ited
Is the screened or perforated interfeet in length?	erval of casing greater than 100	\boxtimes		100-foot maxim ocated in and n CERCLA, WQA	ear groundwa	ter contaminati	ecial standard ion sites (such	for wells as	3
Are you requesting a variance to of steel casing in the surface sea	il?		IXIII	The wells must R12-15-801 (27 structure used to) a "vault" is di	efined as a tarr	per-resistant v	C. vatertigi	ht
 Is there another well name or ide with this well? (e.g., MW-1, PZ2 	entification number associated	X		f yes, please state	O-06		and surface.		
 Have construction plans been construction plans been construction plans been construction. 	ordinated with the Arizona	X		f yes, please sta David Haac	ate agency co	ntact & phone	number		
6. For monitor wells, is dedicated p	ump equipment to be installed?			f yes, please st Gallons per Minu	ate design pur				
7. Is this well a new well located in AND intended to pump water for groundwater?	the purpose of remediating		VIII	ou must also fi Inless the well i Operable wells o	s a replaceme	ent well and the	total number	of	
8. Will the well registration number on the upper part of the casing?	be stamped on the vault cover or	X		f no, where will					

Notice	of Intent	to Dr	ill, I	Deep	oen,	or N	Mod	fy a l	Monitor / Pie	ezo	me	ter	/ Environm	ental V	Vell		55	_ /	12	7235
	N 6. WE	LL C	ON	STR	UCT	ION	_	DEC PART AND									- 30			
CHECK ON	224272147							ethod ECK O	of Well De	vel	opr	ner	nt	Gro			acei	me	nt N	ethod
☐ Air I ☐ Bore ☐ Cab ☐ Dua	Rotary ed or Aug le Tool I Rotary I Rotary							Airli Bail Sur Sur	ift	cify)					Tren Grav Pres	nie F vity sure	Pump e Gro	out		ommended)
☐ Rev	erse Circi	ulatio	n				M	ethod	d of Sealing	at	Red	duc	tion Points	Surf	face	or (Con	du	ctor	Casing
☐ Jette	ed Percussio er (please s	pecify):	Tub	ing		CH	Nor We	NE					CHEC	K ON	E h Mo	ount	in	a va	
DATE CON	STRUCTION 05/01] [ked er (please spec	nifi.										
SECTIO				WE	LL (ON	IST		ION PLAN (addi	itional page if	needed	1)				=3	
	well cons	truct							ecifications b											
DEPT	Boreho	le			г	EDT	H FRO	204			MAAT	EDI	Casing	1 00	-050	DATI	YT NC	/DE	/ T \	
	TO (feet)	DIA	REHO METE	ER	FRC	SUR	FACE		OUTER DIAMETER (inches)	STEEL	PVC	ABS	IF OTHER TYPE, DESCRIBE		7		ОТТЕР	IF (OTHER TYPE, SCRIB	SLO1 SI
0	20		18	7	0			20	14	\boxtimes		Ħ		X			1			
20	1210		10		0			500	5	X			renforces	X	Ī					
					50	0	1	200	5		\times		7				X			0.020
									Annular		200	1000								
	FACE			œ.	15	BE	NTO		NNULAR MATER	IALT	TYPE	(T)					7	FIL	TER PACK
FROM (feet)	TO (feet)	NONE	CONCRETE	NEAT CEMENT OR CEMENT GROUT	CEMENT- CEMENT- BENTONITE GROUT	GROUT	CHIPS	PELLETS	IF O	THE	RT		OF ANNULAR MA	ATERIAL,				SAND	GRAVEL	SIZE
0	490			X													T	1		
490	495																5	Ħ		No. 30-7
495	1210																Š	Ť		No.10-2
IF THIS WE	LL HAS NES	TED C	ASINO	SS, SF	PECIFY	/ NUN	MBER	OF CA	SING STRINGS	E	XPE	CTE	D DEPTH TO WA	TER (Fee		ow Gr	ound .	Surf	ace)	
SECTIO	N 8. PEF	MIS	SIO	N TO) AC	CE	SS	-		_					0		-	-	-	
B	y checking neasureme	this nts at	box,	l her	eby p	rovi e ins	de A	DWR	permission to	ent	er ti	ne p	property for th	e purpo	se o	f taki	ing w	/ate	er lev	el
									ER SIGNATI	JRI	=									
I state that	this notice	is filea					A.R.S	§ 45-	596 and is com	olete	anı	d co	rrect to the bes	t of my k	nowl	edge	and			
			Lai	nd C)wne	r					-		ell Owner (if a	ifferent fro	om La	nd Ov	vner;	See	instruc	ctions)
PRINT NAME AND TITLE										AN	TNI D TIT	LE	lan Ream,	Senio	r Hy	drog	geolo	ogis	st	
SIGNATURE LAND OWNE										WE	NAT LL O	URE	OF T	2						
DATE										DA.				4-1	7-	2	01	7		
	ecking this ectronic mai		you	agree	to a	llow	ADW	/R to d	contact you	×			ecking this bo ectronic mail.	x, you a	gree	to a	illow	ΑD	WR to	contact yo
EMAIL ADDRESS										EMA	AIL	SS	lanReam@f	orence	con	ner	com			

WELL REGISTRATION NUMBER


SECTION 5. Well Construction Diagram	
Provide a well construction diagram showing all existing	well construction features listed in Section 6 and Section 7.
Con attached well discusses	
See attached well diagram.	
	OE:






	20031054B
	1101010A
	200310450
29	
20035007	20031054A
20035002B	28
	PINAL AMA
20035003	ARIZONA
	T 4S R 9E
20035006B	
20035006A	
	200310200
200370010	20038001A
32	33
	20038001B
20037013A	200380020 20031019C

Arizona State Land Department



April 25, 17



Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User

Torren Valdez

From: Justina Speas <jspeas@nationalewp.com>
Sent: Wednesday, April 26, 2017 10:10 AM

To: Torren Valdez
Subject: FW: ADWR Issue
Attachments: Rev_pg3_FRP.pdf

Please see below.

Thank you,

Justina Speas
Office Manager
National EWP, Inc.
1200 W. San Pedro St.
Gilbert, AZ 85233
480-558-3500 PH
480-798-4722 CL
480-558-3525 FX
jspeas@nationalewp.com

From: Candreva, Lauren [mailto:LCandreva@haleyaldrich.com]

Sent: Wednesday, April 26, 2017 10:05 AM

To: Justina Speas < speas@nationalewp.com

Cc: lan Ream < lanReam@florencecopper.com

Subject: RE: ADWR Issue

Hi Justina,

Please see the attached pg 3 of the NOI form, this form will be the same for all 7 wells since it does not contain any of the well names or locations. However, it is also the page that has the signature block, so please confirm with your ADWR contact that it will not require a signature to complete this file.

Thanks, Lauren

From: Justina Speas [mailto:jspeas@nationalewp.com]

Sent: Tuesday, April 25, 2017 2:09 PM

To: Candreva, Lauren < <u>LCandreva@haleyaldrich.com</u>> **Cc:** Ian Ream < IanReam@florencecopper.com>

Subject: ADWR Issue

Good Afternoon,

I just spoke with Torren Valdez with ADWR, and he informed me of an error with some of the NOI's we just turned in. On O-01 through O-07 the well construction plan shows 0 to 500' as steel, but that is not what the diagram shows.

He said we can just fix the page with the construction plan and email him a copy, and he will put it with the file.

Justina Speas Office Manager National EWP, Inc. 1200 W. San Pedro St. Gilbert, AZ 85233 480-558-3500 PH 480-798-4722 CL 480-558-3525 FX jspeas@nationalewp.com

SECTIO	ON 6. WE	ELL (CON	STI	RUC	TION	I DE	ETAIL	S								ũ							-
Drill M	Cold for the Cold of the Cold						V	/letho	d of Well D)ev	/elo	ıq	ne	nt		G	ro	ut E	mp	lac	em	ent	Met	hod
☐ Cat	Rotary ed or Aug ble Tool al Rotary d Rotary						C	HECK C Air Ba Su Su	Iift							C [] []	CHECK ONE Tremie Pumped (Recommended) Gravity Pressure Grout Other (please specify):							
☐ Rev		ulatio	on					letho	d of Sealing	g a	at R	ec	luc	tion F	oints		Surface or Conductor Casing							
☐ Air ☐ Oth	Percussio er (please s	specif	y):	Tuk	oing		CHECK ONE ☐ None ☐ Welded ☐ Swedged ☐ Swedged ☐ CHECK ONE ☐ Flush Mount in a vault ☐ Extends at least 1' above											ove grade						
	05/0	1/20	17	2.200				Pac Oth	cked er (please sp	eci	fy):													
SECTIO	N 7. PR	OPO	SEL	W	ELL	CON	ST	RUCT	ION PLAN	(a	ttacl	ı a	ddi	tional p	age if	need	led)						
Attach a	Boreho		tion	diag	ram	label	ing	all sp	ecifications	be	low	_												
DEPT	FROM	ie	_			DEPTH	1 ED	OM.		-		A.T.	EDI	Cas	ing									
	TO (feet)		REHO		FR	SUR	FACE	TO	OUTER DIAMETER	1	SIEEL	M	ABS	TY	THER PE,	BLANK OR NONE		SHUTTER SCREEN O		SLOTTED 20	IF	OTHI		SLOT SIZ
0	20	0	inches 18)	(re	et)		(feet)	(inches)	1				DESC	RIBE		WIRE	SS S	2 2	SLC	DE	SCRI	BE	(inches)
		-	-					20 14 🗵 🗆 🗵																
20	1210		10		50			200	5	L				(FF	RP)	\boxtimes								0.000
								70.7	Annula	rN			<u>ا</u>			Щ			_	싀	_			0.020
	FACE		7						NULAR MATER											T		FI	LTER	PACK
FROM (feet)	TO (feet)	NONE	CONCRETE	NEAT CEMENT OR	CEMENT. BENTONITE GROUT	GROUT	CHIPS	PELLETS	IF	оті	HER	TYI	PE (OF ANNU	LAR MA	TERL	AL,				SAND	GRAVEL		SIZE
0	490			X	-					-										F				
490	495																			5	X		N	o. 30-70
495 IF THIS WE	1210 L HAS NEST	ED CA	ASING	S, SF	ECIF	NUM	BER	OF CAS	SING STRINGS		EYD	EC	TEC	DEPTH	TOWA	TED /	-				X			0.10-20
								5, 5,16	0		LA		1	DEFIN	TO WA		20		w Gr	ound	Sun	ace)		
SECTIO	8. PER	MIS	SION	I TC) AC	CES	S					Š											-	
	ododi Cilici	ILO CIL	uno	WEII.	100	HISH	ucuc	ins.)	ermission to			the	e pi	operty	for the	pur	oos	e of	taki	ing w	vate	er lev	/el	
SECTION	9. LAN	D 01	WNE	RA	ND	WEL	L C	WNE	R SIGNAT	UF	RE													
state that	nis notice is	filed	In co.	mplia	ince v	ith A.	R.S.	§ 45-5	96 and is com	ple	te a													
RINT NAME ND TITLE			Lan	a U	wne	1					RINT ND T	NA	ME	I Own Ian R								-	ctions	5)
GNATURE (IND OWNER										SI W	GNA ELL (TUI	REC)F		# ST II	JI	. iyo	09	0010	Jan			
ATE										D,	ATE													
	cking this I tronic mail.	box, y	ou a	gree	to al	low A	DW	R to co	ontact you	×	Z V	y ia	che elec	cking th	nis box nail.	, you	ag	ree 1	o al	llow ,	ADI	NR t	o co	ntact you
MAIL DDRESS										EN AD	MAIL	SS	la	nRea	m@flo	reno	cec	agos	er.	com				

Torren Valdez

From:

Robert Harding <RHarding@azland.gov>

Sent:

Tuesday, April 25, 2017 9:49 AM

To:

Torren Valdez

Subject:

ASLD (Landowner) Approval for NOI's - Lease #11-26500

FYL

From: Robert Harding

Sent: Wednesday, March 15, 2017 2:31 PM

To: samurillo@azwater.gov

Cc: Fred Breedlove <FBreedlove@azland.gov>; Joe Dixon <jdixon@azland.gov>; Heide Kocsis <HKocsis@azland.gov>

Subject: ASLD (Landowner) Approval for NOI's - Lease #11-26500

Stella,

As you are aware, Florence Copper is in the presence of registering a number of existing wells on State Trust Lease #11-26500 which were originally installed using single registration numbers to permit multiple monitor well installations. A number of these wells will then be permanently abandoned in accordance with Arizona Department of Water Resources (ADWR) requirements. The lessee, Florence Copper, has discussed the specifics of this registration/abandonment process with the Arizona State Land Department (ASLD), and the Department has no objection to the proposed activities.

Please accept this email as documentation of Landowner's approval for the Notice of Intent (NOI) application filings for well registration and abandonment, currently being submitted to ADWR by Florence Copper on ASLD Lease #11-26500, Section 28, T4S, R9E.

Thank you. Best regards,

Bob Harding Hydrologist Water Rights Section Arizona State land Department 602.542.2672



Torren Valdez

Evanu	Ian Ream <ianream@florencecopper.com></ianream@florencecopper.com>
From: Sent:	Friday, January 13, 2017 9:06 AM
To:	Torren Valdez
Subject:	Re: Map of monitor well locations
	And and all the second of the
Hi Torren,	
The pumps will be QED samples. The flow rate foot.	I micro purge. They typically do a liter or two a minute. Very low flow. Looking for discreet interval is based on drawdown. The goal is not to draw down the well much more than a half a foot or 1
Thanks,	
Ian Ream	
Senior Hydrogeologist	
Florence Copper	
On Jan 13, 2017, at 8:5	66 AM, Torren Valdez < <u>tvaldez@azwater.gov</u> > wrote:
lan,	
Would you hap those monitor	ppen to know the pump capacity (gpm) for the low-flow pumps that will be installed on ing wells?
Thank you,	
	& Permitting Division nent of Water Resources
<image002.jpg< td=""><td>></td></image002.jpg<>	>
Sent: Thursday To: Torren Val	m [mailto:lanReam@florencecopper.com] y, January 12, 2017 11:13 AM dez <tvaldez@azwater.gov> of monitor well locations</tvaldez@azwater.gov>
Hi Torren,	
Here is a map	with the well locations.
Please don't he	esitate to contact me if you need anything else or have any questions.
Cheers,	
lan	

ian Ream Senior Hydrogeologist

<image003.jpg>

Florence Copper Inc.
1575 W. Hunt Highway Florence AZ USA 85132
C 520-840-9604 T 520-374-3984 F 520-374-3999
E janream@florencecopper.com Web florencecopper.com

*Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you."

*Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you."

NOTICE

A.R.S. § 41-1030(B), (D), (E) and (F) provide as follows:

- B. An agency shall not base a licensing decision in whole or in part on a licensing requirement or condition that is not specifically authorized by statute, rule or state tribal gaming compact. A general grant of authority in statute does not constitute a basis for imposing a licensing requirement or condition unless a rule is made pursuant to that general grant of authority that specifically authorizes the requirement or condition.
- D. This section may be enforced in a private civil action and relief may be awarded against the state. The court may award reasonable attorney fees, damages and all fees associated with the license application to a party that prevails in an action against the state for a violation of this section.
- E. A state employee may not intentionally or knowingly violate this section. A violation of this section is cause for disciplinary action or dismissal pursuant to the agency's adopted personnel policy.
- F. This section does not abrogate the immunity provided by section 12-820.01 or 12-820.02.

ARIZONA DEPARTMENT of WATER RESOURCES 1110 W. Washington St. Suite 310 Engineering and Permits Division Phoenix, AZ 85007 602-771-8500

NOTICE TO WELL DRILLERS

This is a reminder that a valid drill card be present for the drilling of each and every well constructed on a site.* The problem seems to occur during the construction of a well when an unexpected problem occurs. Either the hole collapses, the hole is dry, a drill bit is lost and can't be recovered, or any number of other situations where the driller feels that he needs to move over and start another well. If you encounter this type of scenario, please be aware drillers do not have the authority to start another well without first obtaining drilling authority for the new well. Please note the following statutes and regulations pertaining to well drilling and construction:

ARIZONA REVISED STATUTE (A.R.S.)

A.R.S. § 45-592.A.

A person may construct, replace or deepen a well in this state only pursuant to this article and section 45-834.01. The drilling of a well may not begin until all requirements of this article and section 45-834.01, as applicable, are met.

A.R.S. § 594.A.

The director shall adopt rules establishing construction standards for new wells and replacement wells, the deepening and abandonment of existing wells and the capping of open wells.

A.R.S. § 600.A

A well driller shall maintain a complete and accurate log of each well drilled.

ARIZONA ADMINISTRATIVE CODE (A.A.C.)

A.A.C. R12-15-803.A.

A person shall not drill or abandon a well, or cause a well to be drilled or abandoned, in a manner which is not in compliance with A.R.S. Title 45, Chapter 2, Article 10, and the rules adopted thereunder.

A.A.C. R12-15-810.A.

A well drilling contractor or single well licensee may commence drilling a well only if the well drilling contractor or licensee has possession of a drilling card at the well site issued by the Director in the name of the well drilling contractor or licensee, authorizing the drilling of the specific well in the specific location.

A.A.C. R12-15-816.F.

In the course of drilling a new well, the well may be abandoned without first filing a notice of intent to abandon and without an abandonment card.

* THIS REQUIREMENT DOES NOT PERTAIN TO THE DRILLING OF MINERAL EXPLORATION, GEOTECHNICAL OR HEAT PUMP BOREHOLES

DWR 37-61 (02-13)

Transaction Receipt - Success

Arizona Water Resources Arizona Water Resources MID:347501639533 1700 W Washington St Phoenix, AZ 85012 602-771-8454

04/19/2017 11:49AM Remittance ID Arizona041917144729704Chr Transaction ID: 183294013

KELSEY SHERRARD 500 Main Street WOODLAND, California 95695 United States Visa - 3420 Approval Code: 050257

Sale

Amount: \$1,650.00

multiple N/A Cash receipts

dgchristiana@azwater.gov

Cardmember acknowledges receipt of goods and/or services in the amount of the total shown hereon and agrees to perform the obligations set forth by the cardmember's agreement with the issuer.

Signature ____

click here to continue,

Printed: 4/19/2017 12:26:46 PM

Arizona Department of Water Resources

1110 West Washington Street, Suite 310

Phoenix AZ 85007

Customer:

KELSEY SHERRARD NATIONAL EWP **500 MAIN STREET** WOODLAND, CA 95695

Receipt #:

17-50968

Office:

MAIN OFFICE

Receipt Date: 04/19/2017

Sale Type:

Mail

Cashier:

WRDGC

Item No.	Function Code	AOBJ	Description	Ref ID	Qty	Unit Price	Ext Price
8505	122221	4439-6F	MONITOR, PIEZOMETER, AIR SPARGING, SOIL VAPOR EXTR	multiple wells	11	150.00	1,650.00
					RECEIPT	TOTAL:	1,650.00

Payment type: CREDIT CARD

Amount Paid: \$1,650.00

Payment Received Date: 04/19/2017

Authorization 183294013

Notes:

APPENDIX B

Lithologic Log

HALEY	LITH	HOLOGIC LOG	O-06
Client Florence C	n Test Facility, Florence, Ari Copper, Inc. Drilling LLC	zona	File No. 129687 Sheet No. 1 of 15 Cadastral Location D (4-9) 28 CB
Borehole Diameter(s)	Reverse Rotary 20/12.25 in. Challenger 280	Land Surface Elevation 1477.71 feet, amsl Datum State Plane NAD 83 Location N 746,202 E 847,553	Start 22 January 2018 Finish 9 February 2018 H&A Rep. C. Giusti
Depth (ft) Elevation USCS Symbol Stratum Change Depth (ft)	VISUAL-MANU	AL IDENTIFICATION AND DESCRIPTION	COMMENTS
- 1475 - 1475 - 10	Sand is subangular to subrounde toughness, no dry strength, are	O-45 feet) Primarily gravel up to 25mm with ~15% sands. ed and gravel is subangular. Fines are nonplastic, no gray (GLEY2 A/5B) and no reaction to HCL. UBFU SILT (45-80 feet) Primarily fine to coarse sand with	Well Registry ID: 55-227235 Surface Completion: Locking Well Vault & Concrete Pad Well casing stickup: 1.05 feet als COLOR IDENTIFICATION MADE WITH WET SAMPLES USING MUNSELL CHART Surface Casing: 14-inch mild steel; 0-40 feet Well Casing: Nominal 5-inch diameter Fiberglass Reinforced; -1.05 - 499 feet
- 1430 - 1430 - 50 - 1425 - 1425 - 60 - 1415 - 65 - 1410 - 70 - 1405 - 14405	~15% fines and ~5% gravel u	in to 15mm. Sand is subrounded to subangular and gravel listic, no toughness, no dry strength, (5YR 5/4), and no	Unit Intervals: UBFU: 0 - 278 feet MGFU: 278 - 298 feet LBFU: 298 - 365 feet Oxide Bedrock: 365 - 1220 feet
	ns, group symbols, and grain-size de Field Practice for Soil Identification	eterminations based on the USCS visual-manual method (Haley nand Description).	O-06

HAL	EY DRIC	ЭН	LITHOLOGIC LOG	O-06 File No. 129687 Sheet No. 2 of 15
Depth (ft) Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
-75	SC 5	80 - 120 - 130 -	CLAYEY SAND (80-120 feet) Primarily fine to medium sand with -20% fines and -5% gravel up to 20mm. Sand and gravel is subrounded to subangular. Fines have medium plasticity, medium toughness, medium dry strength, are brown (5YR 4/4) and a weak reaction to HCL. UBFU SANDY CLAY (120-130 feet) Primarily fines with -25% sands up to 4mm. Sand is subangular to subrounded. Fines have high plasticity, high toughness, high dry strength, are brown (7.5YR 5/4), and a moderate reaction to HCL. UBFU CLAYEY SAND (130-170 feet) Primarily fine to medium sand with -20% fines and -5% gravel up to 8mm. Sand is subrounded and gravel is subangular to subrounded. Fines have medium plasticity, low toughness, low dry strength, are brown (5YR 5/4), and a moderate reaction to HCL. UBFU	Seal: Type V neat cement 0 - 474 feet Fine sand/bentonite 474 - 490 feet
NOTE: Li	thologic	descrption DP2001A -	ns, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley Field Practice for Soil Identification and Description).	O-06

H	ΔLE	Y	O-06		
	ALC	PRIC	H	LITHOLOGIC LOG	File No. 129687 Sheet No. 3 of 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
-	1315				
- -165	-				
-	_ -1310-				
_ -170-	-		170	CHANDY SHITE '4 CAND 450 155 C AD ' ' I C A 156 A 156	
-	- -1305- -	МН		CLAYEY SILT with SAND (170-175 feet) Primarily fines with ~15% sands. Sand is subangular to subrounded. Fines have low plasticity, low toughness, no dry strength, (7.5YR 4/6), and a weak reaction to HCL. UBFU	
-175 -	-	SW	175	WELL GRADED SAND (175-215 feet) Primarily medium to fine sand with ~5% gravel	
- - -180-	1300-			up to 4mm. Sand is subangular to subrounded and gravel is subrounded. Fines are nonplastic, no toughness, no dry strength, (7.5YR 4/4), and a weak reaction to HCL. UBFU	
-	_ -1295-				
_ 	F				
	- -1290-				
- -190-	-				
-	Ė				
-	-1285 - -				
-195- - -	F				
-	-1280 -				
200					
<u> </u>	-1275 -				
-205 -					
	-1270- -				
-210- -	Ė				
	1265				
-215-	 - -	GP	215	POORLY GRADED GRAVEL with SAND (215-220 feet) Primarily gravel up to 7mm	
-	1260			with $\sim 5\%$ fines and $\sim 30\%$ sands. Sand is subangular to subrounded and gravel is subangular to angular. Fines are nonplastic, no toughness, no dry strength, (7.5YR 4/4),	
-220-	 -	SP	220	and no reaction to HCL. UBFU POORLY GRADED SAND (220-225 feet) Primarily medium sand with ~5% fines and	
-	1255			trace gravel up to 4mm. Sand and gravel is subangular to subrounded. Fines are nonplastic, no toughness, no dry strength, (7.5YR 4/4), and a weak reaction to HCL.	
- -225-	<u> </u>	CL	225	UBFU CLAY with SILT (225-230 feet) Primarily fines with ~10% sands. Sand is subrounded.	
-	- -1250-			Fines have low plasticity, low to medium toughness, no dry strength, (7.5YR 4/6), and a strong reaction to HCL. UBFU	
-230-	<u> </u>	MH	230	SILT with SAND (230-240 feet) Primarily fines with ~35% sands and trace gravel. Sand	_
-	- -1245			is subangular to subrounded. Fines are nonplastic, low toughness, no dry strength, (7.5YR 4/6), and moderate reaction to HCL. UBFU	
- -235					
	_ -1240-				
- -240-	Ė	SP	240	POORLY GRADED SAND (240-250 feet) Primarily medium sand with $\sim 5\%$ fines. Sand	
-	1235			is subrounded to rounded. Fines are nonplastic, no toughness, no dry strength, (7.5YR 4/6), and no reaction to HCL. UBFU	
_ -245	F			7/0), and no reaction to HeL. OBFO	
	- -1230-				
-	1.200				<u> </u>

H&ALITHOLOG-PHOENX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+.GDT \(\text{NHALEYALDRICH.COM/SHAREBOS_COMMON/129887/GINT/129887-LITH_KF.GPJ 31 Aug 18\)

H	ALE	PRIC	Н	LITHOLOGIC LOG	O-06 File No. 129687 Sheet No. 4 of 15			
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION				
-255- -260-	-1225 - - - - - -1220	SW	250	WELL GRADED SAND (250-278 feet) Primarily fine to coarse sand with ~5% fines and ~5% gravel up to 8mm. Sand is subangular to rounded and gravel is subangular to subrounded. Fines are nonplastic, no toughness, no dry strength, (7.5YR 4/4), and a weak reaction to HCL. UBFU				
- -265- - - - - - -270-	-1215- -1210-				ACD Sensor Depths: 268, 271			
-275 - -275	1205- -1-				feet			
- -280- - - - - - -285-	_ -1195	CL	278	CLAY with SILT (278-298 feet) Primarily fines with ~10% sands. Sand is subangular to subrounded. Fines have low plasticity, low toughness, no dry strength, (7.5YR 4/4), and no reaction to HCL. MGFU				
- -290- - - - - - -295-	_ -1185-							
- -300-	1175	SL- SM	298	CLAYEY SAND with SILT (298-310 feet) Primarily fine to coarse sand with ~25% fines and trace gravel. Sand is subangular to rounded. Fines are nonplastic, low toughness, no dry strength, (7.5YR 4/6), and no reaction to HCL. LBFU				
- -310- - - -	1165	SW	310	WELL GRADED SAND (310-340 feet) Primarily fine to coarse sand with ~5% fines and ~5% gravel up to 5mm. Sand and gravel is subangular to subrounded. Fines are nonplastic, no toughness, no dry strength, (7.5YR 4/6), and a weak reaction to HCL. LBFU				
-315- - - - -320- -	1160-							
- -325- - - - -330- -	1150				CS Sensor Depths: 324, 343, 364, 384 feet			
- -335_ NO								

H	ALE	Y	:H	LITHOLOGIC LOG	O-06 File No. 129687 Sheet No. 5 of 15
(ff)	tion	SS	mg (#)		
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
- -340-	-1140- -135-	SM	340	SILTY SAND (340-365 feet) Primarily fine to coarse sand with ~20% fines and trace gravel up to 4mm. Sand and gravel is subrounded to subangular. Fines are nonplastic, no toughness, no dry strength, (7.5YR 4/4), and weak reaction to HCL. LBFU	
- -345- - - - - -350-	_ -1130-				
- -355- - - -	1120-				
- -365	- -1115- - - - -		365	QUARTZ MONZONITE (365-480 feet) Consists of quartz at approximately 35%, potassium feldspars at approximately 35%, plagioclase at approximately 25%, and biotite at	
- -370-	1105 -			approximately 5%. Abundant Cu at 375	
- - -380-	1100-				
-385 -385 - - - -390	- - - -1090-				
- -395-	-1085 - - - - - -1080-				
400	- - - -1075-				
- - -410-	_ -1070-				
- 415-	- - - -1060-				
<u> </u>	-		422	is group symbols, and grain-size determinations based on the USCS visual-manual method (Haley	0.00

H&ALITHOLOG-PHOENX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+GDT WHALEYALDRICH.COM/SHAREBOS_COMMON/129687/GINT/129687-LITH_KF.GPJ 31 Aug 18

HALEY				O-06	
H	ALE	RIC	H	LITHOLOGIC LOG	File No. 129687 Sheet No. 6 of 15
£	Ľ		5 n 2		
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)		
De	Ele	∪ (S	B C W	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
	1055			QUARTZ MONZONITE (365-480 feet) Continued	
-425 -	_				
E	- -1050-				
430	_				
E	- -1045 -				
-435 -	-				
	- -1040-				
440	_				
E	- -1035-				
445	-				
-	- -1030-				
-450-	-				
	- -1025 -				
- 455	_				
E	- -1020-				
460	_				
E	- -1015-				
465	_				
	1010				
-470-	-				
	1005				
-475 -	_				
	-1000-				
- 480-	- -		480	GRANODIORITE (480-505 feet) Contains mostly plagioclase in a gray aphanitic matrix	
	- -995- -			with biotite crystals composing approximately 10%.	
485	-				
	- -990-				
-490 -	-				Filter Pack: 8 - 12 CO Silica
	- -985- -				Sand; 490 - 1220 feet Thread Adapter: Stainless Steel, SCH 80 F480 PVC to API; 499
- 495	_				feet
E	- -980- -				
500	-				Well Screen: Nominal 5-inch
	- -975- -				diameter, SCH 80 PVC Screen (0.020-inch slots); 499 - 1201 feet
505	- -		505	QUARTZ MONZONITE (505-520 feet) Consists of quartz at approximately 35%,	ERT Sensor Depths: 519, 594, 669, 744, 819, 894, 969, 1045, 1120, 1194 feet
-	- -970-			potassium feldspars at approximately 35% , plagioclase at approximately 25% , and biotite at approximately 5% .	1120, 1177 1001
TON	E: Lith	nologic	descrption	s, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley Field Practice for Soil Identification and Description).	O-06

31 Aug 18

H&A-LITHOLOG-PHOENIX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+.GDT WHALEYALDRICH.COM/SHAREBOS_COMMON/129887/GINT/129887-LITH_KF.GPJ

TE: Lithologic descrptions, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley & Aldrich OP2001A - Field Practice for Soil Identification and Description).

H	ALE	Y	:H	LITHOLOGIC LOG	O-06 File No. 129687 Sheet No. 7 of 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
-510 - - - -515 - -	-965- - - - - - -960-		520		
-520 - - - -525 - - - - - - - - - - - - -	-955- - - - - - -950-		320	GRANODIORITE (520-625 feet) Contains mostly plagioclase in a gray aphanitic matrix with biotite crystals composing approximately 10%.	
-535 535 	-945- - - - - - -940-				
- -545- - - - - - -550-	-930-				
- -555 - - - - - -560	- 920-				
- -565- - - - - -570-	-910- - - - -				
- -575- - - - - -580- -	-900-				
-585 -590 -	- - - -890-				
- -595	-				

31 Aug 18

H&ALITHOLOG-PHOENX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+.GDT WHALEYALDRICH.COM/SHAREBOS_COMMON/129887/GITH_KF.GPJ

875 870 885	HALEY				LITHOLOGIC LOG	O-06 File No. 129687 Sheet No. 8 of 15			
880 870	Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION				
605 875 - 605 886 - 620 886 - 635 846 - 645 846 - 645 830 - 645 825 - 665 820 - 660 825 - 665 820 - 660 815 - 665 820 - 660 820 - 660 820 - 660				596	GRANODIORITE (520-625 feet) Continued				
870 - 605 -	- - -600-	F							
870 870 885 886 885 886 885 886	-								
865	605	H							
615 866 - 625 625 625 625 635 645	_	-							
865	-	F							
625	-610-	-							
880	- :	F							
825 625	-615- -								
855 625 625 625 GUARTZ MONZONITE (625-645 feet) Consists of quartz at approximately 35%, potassium feldspars at approximately 35%, plagioclase at approximately 25%, and biotite at approximately 5%. 840		-860 -	-						
625	620	-							
October Consists of quartz at approximately 35%, plagioclase at approximately 25%, and biotite at approximately 55%.	-	- 855-							
approximately 5%. approximately 5%. approximately 5%. approximately 5%. blabase (645-670 feet) Dark gray to black igneous rock. blabase (645-670 feet) Dark gray to black igneous rock. blabase (645-670 feet) Dark gray to black igneous rock. blabase (645-670 feet) Dark gray to black igneous rock. complete the state of the	625	-		625	QUARTZ MONZONITE (625-645 feet) Consists of quartz at approximately 35%,				
630	- :	- -850-	-		potassium feldspars at approximately 35%, plagioclase at approximately 25%, and biotite at approximately 5%.				
640 - 640 - 645 -	- -630-								
640 - 640 - 645 -		_ -845-							
840	_ -635	F							
645 DIABASE (645-670 feet) Dark gray to black igneous rock. 645 DIABASE (645-670 feet) Dark gray to black igneous rock. 650 820 820 830 830 830 830 830 830 830 830 830 83	-	_							
645 DIABASE (645-670 feet) Dark gray to black igneous rock. 655 - 820 - 666 - 810 - 670 - 810 - 670 - 805 -	-640-	-							
645 645 645 645 670 feet) Dark gray to black igneous rock. 650 655 665 665 665 665 665 665 665 665	_	F							
Babase G48-670 feet) Dark gray to black igneous rock.	-	F		645					
650	645	-		043	<u>DIABASE</u> (645-670 feet) Dark gray to black igneous rock.				
825- 655 820 815- 665 810- 670 805 805 800 800	_ :	-830- -							
665 - 815 - 665 - 815 - 665 - 815 - 665 - 815 - 665 - 805 - 805 - 675 - 800 - 680 - 800 - 680 - 795	-650- -								
- 820 820 815 815 810 810 805 805 800		-825- -	-						
- 815 - 665 - 810 - 670 - 805 - 675 - 680 - 680 - 795	655								
GRANODIORITE (670-690 feet) Contains mostly plagioclase in a gray aphanitic matrix with biotite crystals composing approximately 10%.		820-							
670 - 805 - 675 - 800 - 680 - 795	660	<u> </u>							
GRANODIORITE (670-690 feet) Contains mostly plagioclase in a gray aphanitic matrix with biotite crystals composing approximately 10%.	-	815-							
GRANODIORITE (670-690 feet) Contains mostly plagioclase in a gray aphanitic matrix with biotite crystals composing approximately 10%.	665	-							
GRANODIORITE (670-690 feet) Contains mostly plagioclase in a gray aphanitic matrix with biotite crystals composing approximately 10%.	-	- -810-							
with biotite crystals composing approximately 10%.	- -670-			670	GRANODIORITE (670-690 feet) Contains mostly plagioclase in a gray aphanitic matrix				
-675- 		_ -805-			with biotite crystals composing approximately 10%.				
	675	-							
	-	-							
		-							
	-								

ALDRICH				LITHOLOGIC LOG	O-06 File No. 129687 Sheet No. 9 of 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
685	-				
	- - -790-				
690	-		690	QUARTZ MONZONITE (690-705 feet) Consists of quartz at approximately 35%,	
	- -785-			potassium feldspars at approximately 35%, plagioclase at approximately 25% , and biotite at approximately 5% .	
695	-				
	-780- -				
700-	_				
705	-775- - -		705		
. 00	- - -770-			GRANODIORITE (705-1000 feet) Contains mostly plagioclase in a gray aphanitic matrix with biotite crystals composing approximately 10%.	
710	-				
	- -765-				
715	-				
	- -760-				
720					
705	-755- - -				
725	- - -750-				
730	-				
	- - -745-				
735	- - -				
	- -740- -				
740	- -				
	-735- -				
745	_				
750-	-730- - -				
	- - -725-				
755	-				
	_ -720-				
760	-				
	- -715- -				
765	_				
	-710- -				

H&A-LITHOLOG-PHOENIX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+.GDT WHALEYALDRICH.COM/SHAREBOS_COMMON/129887/GINT/129887-LITH_KF.GPJ 31 Aug 18

HALEY				LITHOLOGIC LOG	O-06 File No. 129687 Sheet No. 10 of 15			
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	WOULAN MANUAL IDENTIFICATION AND DESCRIPTION				
		0,	770	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION				
-770 ⁻	F		770	GRANODIORITE (705-1000 feet) Continued				
L	-705- -							
-775 -	F							
_	-700- -							
-780 -								
-	-695-							
-785 -								
E	-690-							
-790-	<u> </u>							
	685-							
795	-							
-	680-							
800-	-							
-	675							
-805								
-	- -670-							
- -810-								
	- -665-							
- -815-	Ė							
	- 660-	-						
- -820-	F							
Ė	_ -655-							
_ -825	-							
F	- -650-							
- -830-	550-							
-	-							
- - -835-	-645- -							
-	<u> </u>							
-	-640- -							
-840 -	-							
-	-635- -							
845	F							
-	-630-	-						
-850 -								
	625							
-855	-		856					
NOT	NOTE: Lithologic descrptions, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley & Aldrich OP2001A - Field Practice for Soil Identification and Description).							

HALEY ALDRICH			Н	LITHOLOGIC LOG	O-06 File No. 129687
		REDITION			Sheet No. 11 of 15
(ff)	tion	SS	um ige (ft)		
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
	Ш				
-	620-			GRANODIORITE (705-1000 feet) Continued	
860	-				
-	- -615-				
- -865-	Ē				
	_ -610-				
- 870-	F				
-	- -605-				
- - 875-	F				
-	F				
-	-600-				
-880 -					
	-595-				
885	 - -				
-	-590-				
890	-				
-	- -585-				
- -895-	-				
E	_ -580-				
900	F				
-	- -575-				
-	F				
905	F				
-	-570- -				
-910- -					
	-565-				
915	<u> </u>				
-	- -560-				
920	<u> </u>				
-	_ -555-				
925	Ė				
-	- -550-				
930	⊦				
	F				
-	-545- - -				
-935 -	Ē.				
-	-540- -				
940	Ė				
	- -535-		943		
NOT	TC: 1 ;#k	ماممام	daaaratiaa	is group symbols, and grain-size determinations based on the USCS visual-manual method (Haley	0.00

H&ALITHOLOG-PHOENX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+GDT WHALEYALDRICH.COM/SHAREBOS_COMMON/129687/GINT/129687-LITH_KF.GPJ 31 Aug 18

H	USCS Symbol Stratum Change			LITHOLOGIC LOG	O-06 File No. 129687
					Sheet No. 12 of 15
£	ıtion	SS	um nge (ft)		
Depth (ft)	eva	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
	Ш				
945	-			GRANODIORITE (705-1000 feet) Continued	
-	_ -530-				
950	-				
-	-				
.	-525- -				
955					
-	-520-				
960	-				
-	- -515-				
965	-				
. [_ -510-				
970	-				
	_				
.	-505- -				
975					
. [-500-				
980	-				
-	- -495-				
985	-				
-	_ -490-				
- -990-	-				
-	_				
.	-485- -				
995					
.	-480-				
1000	-		1000	DIABASE (1000-1005 feet) Dark gray to black igneous rock.	
.	- -475-				
1005	-		1005	GRANODIORITE and DIABASE (1005-1025 feet) Contains mostly plagioclase in a gray	
	- - -470-			aphanitic matrix with biotite crystals composing approximately 10% and a dark gray to black	
1010	_			igneous rock.	
.	-465- -				
1015					
	- -460-				
1020	_				
	- -455-				
1025	-		1025	DALPI GEOGRAPHI AND A DELL'AND A	
	_			<u>DIABASE</u> (1025-1030 feet) Dark gray to black igneous rock.	
}	-450-				

31 Aug 18

H&A-LITHOLOG-PHOENIX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+.GDT WHALEYALDRICH.COM/SHAREBOS_COMMON/129887/GINT/129887-LITH_KF.GPJ

H	HALEY LOS TO BE			LITHOLOGIC LOG	O-06 File No. 129687 Sheet No. 13 of 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
1030	-		1030	GRANODIORITE (1030-1125 feet) Contains mostly plagioclase in a gray aphanitic	
_	- -445-	-		matrix with biotite crystals composing approximately 10%.	
_ 1035	-				
-	F				
-	-440- -				
104 0	-				
-	435-				
1045	-				
	- -430-				
_ 1050	H				
-	F				
-	-425- -	-			
105 5	-				
-	-420-				
106 0	[
-	- -415-				
_ 106 5	F				
1003	-				
_	-410- -	-			
1070	-				
-	- -405-	_			
- 1075	-				
-	-400-				
-	-				
1080	-				
	-395-				
1085	-				
- -	- -390-	-			
- 1090	-				
-	-385-				
4005	F				
1095	-				
L	-380-				
1100	 				
-	- -375-				
- 1105	F				
-	- -370-				
1440	F				
1110	<u> </u>				
_	-365-				
1115	-				
NO	FE: 1:44	nologia	docorrtis	group symbols, and grain size determinations beard on the LICCS visual mass of mathet distance	2.55
INU	. L. Liti & A	Idrich C)P2001A -	is, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley Field Practice for Soil Identification and Description).	O-06

ŀ	沿	EY	ЭН	LITHOLOGIC LOG	O-06 File No. 129687 Sheet No. 14 of 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
412 - - - - - - - - - - - - - - - - - - -	-355 25- -350 -345	-	1125	DIABASE (1125-1145 feet) Dark gray to black igneous rock.	
RICH COM/SHAREBOS_COMMON/129687/GINT/129687/LITH_KF.GFJ 31 Aug 18	-335 -335 -330 -330 -325	-	. 1145	GRANODIORITE (1145-1220 feet) Contains mostly plagioclase in a gray aphanitic matrix with biotite crystals composing approximately 10%.	
- HALEYALD - 117	-315 -315 -310	-			
- 1 17 - 1 18 - 11 17 17 18 18 18 19 19 19 19 19 19 19 19 19 19 19 19 19	-295 -295 -290				
HOCOG-PHOENIX-NO WELL HA-LIBOS-F 1	-285 -280 -280 -275	_	descrption	s, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley Field Practice for Soil Identification and Description).	O-06

H	ALE	Y	Н	LITHOLOGIC LOG	O-06 File No. 129687 Sheet No. 15 of 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
1205	-		1204	GRANODIORITE (1145-1220 feet) Continued	
- - 1210	-270-				
-	- -265-	_			
1215	- -				
- - 1220	-260- - -		1220		
					Total Borehole Depth: Driller = 1220 feet; Geophysical Logging = 1215 feet
_					

NOTE: Lithologic descrptions, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley & Aldrich OP2001A - Field Practice for Soil Identification and Description).

H&ALITHOLOG-PHOENX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+GDT WHALEYALDRICH.COM/SHAREBOS_COMMON/129687/GINT/129687-LITH_KF.GPJ 31 Aug 18

APPENDIX C

Chemical Characteristics of Formation Water



May 23, 2018

Barbara Sylvester Brown & Caldwell 201 E. Washington Suite 500 Phoenix, AZ 85004

TEL (602) 567-3894 FAX -

Work Order No.: 18D0619
RE: PTF
Order Name: Florence Copper

Dear Barbara Sylvester,

Turner Laboratories, Inc. received 2 sample(s) on 04/25/2018 for the analyses presented in the following report.

All results are intended to be considered in their entirety, and Turner Laboratories, Inc. is not responsible for use of less than the complete report. Results apply only to the samples analyzed. Samples will be disposed of 30 days after issue of our report unless special arrangements are made.

The pages that follow may contain sensitive, privileged or confidential information intended solely for the addressee named above. If you receive this message and are not the agent or employee of the addressee, this communication has been sent in error. Please do not disseminate or copy any of the attached and notify the sender immediately by telephone. Please also return the attached sheet(s) to the sender by mail.

Please call if you have any questions.

Respectfully submitted,

Turner Laboratories, Inc. ADHS License AZ0066

Kevin Brim Project Manager

Client: Brown & Caldwell

Project: PTF Work Order: 18D0619

Date Received: 04/25/2018

Order: Florence Copper

Work Order Sample Summary

Date: 05/23/2018

Lab Sample IDClient Sample IDMatrixCollection Date/Time18D0619-01R-09Ground Water04/23/2018 1555

18D0619-02 TB Ground Water 04/25/2018 0000

Client: Brown & Caldwell

 Project:
 PTF

 Work Order:
 18D0619

 Date Received:
 04/25/2018

Case Narrative

Date: 05/23/2018

The 8015D analysis was performed by TestAmerica Laboratories, Inc. in Phoenix, AZ.

The radiochemistry analysis was performed by Radiation Safety Engineering, Inc. in Chandler, AZ.

D5 Minimum Reporting Limit (MRL) is adjusted due to sample dilution; analyte was non-detect in the

sample.

H5 This test is specified to be performed in the field within 15 minutes of sampling; sample was

received and analyzed past the regulatory holding time.

M3 The spike recovery value is unusable since the analyte concentration in the sample is

disproportionate to the spike level. The associated LCS/LCSD recovery was acceptable.

All soil, sludge, and solid matrix determinations are reported on a wet weight basis unless otherwise noted.

ND Not Detected at or above the PQL

PQL Practical Quantitation Limit

DF Dilution Factor

PRL Project Reporting Limit

Client: Brown & Caldwell Client Sample ID: R-09

Project:PTFCollection Date/Time: 04/23/2018 1555Work Order:18D0619Matrix: Ground WaterLab Sample ID:18D0619-01Order Name: Florence Copper

Analyses	Result	PRL	PQL	Qual	Units	DF	Prep Date	Analysis Date	Analyst
ICP Dissolved Metals-E 200.7 (4.4)									
Calcium	140		4.0	M3	mg/L	1	04/27/2018 144	0 05/04/2018 115	0 MH
Iron	ND		0.30		mg/L	1	04/27/2018 144	0 05/04/2018 115	0 MH
Magnesium	27		3.0		mg/L	1	04/27/2018 144	0 05/04/2018 115	0 MH
Potassium	6.8		5.0		mg/L	1	04/27/2018 144	0 05/04/2018 115	0 MH
Sodium	170		5.0	M3	mg/L	1	04/27/2018 144	0 05/04/2018 115	0 MH
ICP/MS Dissolved Metals-E 200.8 (5.4)									
Aluminum	ND		0.0800	D5	mg/L	2	04/27/2018 144	0 05/07/2018 113	9 MH
Antimony	ND		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Arsenic	0.0016		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Barium	0.071		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Beryllium	ND		0.00050	D5	mg/L	2	04/27/2018 144	0 05/07/2018 113	9 MH
Cadmium	ND		0.00025		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Chromium	0.0051		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Cobalt	ND		0.00025		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Copper	0.011		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Lead	ND		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Manganese	0.0020		0.00025		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Nickel	0.0033		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Selenium	ND		0.0025		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Thallium	ND		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Zinc	ND		0.040		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
CVAA Dissolved Mercury-E 245.1									
Mercury	ND		0.0010		mg/L	L 1	04/26/2018 095	5 04/26/2018 163	9 MH
рН-Е150.1									
pH (pH Units)	7.8			Н5	-	- 1	04/26/2018 161	5 04/26/2018 161	6 AP
Temperature (°C)	22			Н5	-	- 1	04/26/2018 161	5 04/26/2018 161	6 AP
ICP/MS Total Metals-E200.8 (5.4)									
Uranium	0.016		0.00050		mg/L	L 1	04/27/2018 123	0 04/30/2018 134	8 MH

Client: Brown & Caldwell Client Sample ID: R-09

Project:PTFCollection Date/Time: 04/23/2018 1555Work Order:18D0619Matrix: Ground WaterLab Sample ID:18D0619-01Order Name: Florence Copper

Anions by Ion Chromatography-E300.0 (2.1) Chloride 316 Fluoride NI Nitrogen, Nitrate (As N) 8.8 Nitrogen, Nitrite (As N) NI Sulfate 196 Cyanide-E335.4 Cyanide NI	O 3 O 0		25 0.50 0.50 0.10 130	mg/L mg/L mg/L	1 1 1	04/25/2018 120 04/25/2018 120 04/25/2018 120	25 04/26/2018 141 08 04/25/2018 154 08 04/25/2018 154 08 04/25/2018 154 25 04/26/2018 141	4 AP 4 AP 4 AP
Fluoride NI Nitrogen, Nitrate (As N) 8.8 Nitrogen, Nitrite (As N) NI Sulfate 196 Cyanide-E335.4	O 3 O 0		0.50 0.50 0.10 130	mg/L mg/L mg/L	1 1 1	04/25/2018 120 04/25/2018 120 04/25/2018 120	08 04/25/2018 154 08 04/25/2018 154 08 04/25/2018 154	4 AP 4 AP 4 AP
Nitrogen, Nitrate (As N) 8.8 Nitrogen, Nitrite (As N) NI Sulfate 196 Cyanide-E335.4	8 D 0		0.50 0.10 130	mg/L mg/L	1 1	04/25/2018 120 04/25/2018 120	08 04/25/2018 154 08 04/25/2018 154	4 AP 4 AP
Nitrogen, Nitrite (As N) NE Sulfate 196 Cyanide-E335.4	O 0		0.10 130	mg/L	. 1	04/25/2018 120	08 04/25/2018 154	4 AP
Nitrogen, Nitrite (As N) NI Sulfate 19 Cyanide-E335.4	0		130	•				
Cyanide-E335.4				mg/L	25	04/26/2018 122	25 04/26/2018 141	5 AP
·	D)		0.10					
Cyanide NI	D		0.10					
			0.10	mg/L	. 1	04/26/2018 084	5 04/30/2018 154	5 AP
Alkalinity-SM2320B								
Alkalinity, Bicarbonate (As 150 CaCO3)	0		2.0	mg/L	. 1	05/03/2018 103	0 05/03/2018 121	0 EJ
Alkalinity, Carbonate (As CaCO3) NI	D		2.0	mg/L	. 1	05/03/2018 103	0 05/03/2018 121	0 EJ
Alkalinity, Hydroxide (As CaCO3) NI	D		2.0	mg/L	. 1	05/03/2018 103	0 05/03/2018 121	0 EJ
Alkalinity, Phenolphthalein (As NI CaCO3)	D		2.0	mg/L	. 1	05/03/2018 103	0 05/03/2018 121	0 EJ
Alkalinity, Total (As CaCO3) 150	0		2.0	mg/L	. 1	05/03/2018 103	0 05/03/2018 121	0 EJ
Specific Conductance-SM2510 B								
Conductivity 176	00		0.20	μmhos/cm	2	05/09/2018 131	5 05/09/2018 133	0 AP
Total Dissolved Solids (Residue, Filterable)-SM	M2540 C							
Total Dissolved Solids (Residue, 10) Filterable)	00		20	mg/L	. 1	04/26/2018 082	26 05/01/2018 160	0 EJ
Volatile Organic Compounds by GC/MS-SW8	8260B							
Benzene NI	D		0.50	ug/L	. 1	05/07/2018 182	24 05/07/2018 194	3 KP
Carbon disulfide NI			2.0	ug/L			4 05/07/2018 194	
Ethylbenzene NI			0.50	ug/L			4 05/07/2018 194	
Toluene NI	D		0.50	ug/L			24 05/07/2018 194	
Xylenes, Total NI	D		1.5	ug/L		05/07/2018 182	4 05/07/2018 194	3 KP
Surr: 4-Bromofluorobenzene 95		70-130		%REC	1	05/07/2018 182	24 05/07/2018 194	3 KP
Surr: Dibromofluoromethane 10.	1	70-130		%REC	1	05/07/2018 182	24 05/07/2018 194	3 KP
Surr: Toluene-d8 77	,	70-130		%REC	1	05/07/2018 182	24 05/07/2018 194	3 KP

Client: Brown & Caldwell Client Sample ID: TB

Project:PTFCollection Date/Time: 04/25/2018 0000Work Order:18D0619Matrix: Ground WaterLab Sample ID:18D0619-02Order Name: Florence Copper

Analyses	Result	PRL	PQL	Qual	Units]	DF	Prep Date	Analysis Date	Analyst
Volatile Organic Compounds by GC	/MS-SW8260B								
Benzene	ND		0.50		ug/L	1	05/07/2018 182	4 05/07/2018 234	4 KP
Carbon disulfide	ND		2.0		ug/L	1	05/07/2018 182	4 05/07/2018 234	4 KP
Ethylbenzene	ND		0.50		ug/L	1	05/07/2018 182	4 05/07/2018 234	4 KP
Toluene	ND		0.50		ug/L	1	05/07/2018 182	4 05/07/2018 234	4 KP
Xylenes, Total	ND		1.5		ug/L	1	05/07/2018 182	4 05/07/2018 234	4 KP
Surr: 4-Bromofluorobenzene	101	70-130			%REC	1	05/07/2018 182	4 05/07/2018 234	4 KP
Surr: Dibromofluoromethane	110	70-130			%REC	1	05/07/2018 182	4 05/07/2018 234	4 KP
Surr: Toluene-d8	103	70-130			%REC	1	05/07/2018 182	4 05/07/2018 234	4 KP

Client: Brown & Caldwell

 Project:
 PTF

 Work Order:
 18D0619

 Date Received:
 04/25/2018

QC Summary

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC	RPD	RPD Limit	Qual
Batch 1804269 - E 245.1										
Blank (1804269-BLK1)				Prepared &	Analyzed: (04/26/2018				
Mercury	ND	0.0010	mg/L	•						
LCS (1804269-BS1)				Prepared &	Analyzed: (04/26/2018				
Mercury	0.0049	0.0010	mg/L	0.005000	-	98	85-115			
LCS Dup (1804269-BSD1)				Prepared &	Analyzed: (04/26/2018				
Mercury	0.0048	0.0010	mg/L	0.005000	-	95	85-115	2	20	
Matrix Spike (1804269-MS1)	So	urce: 18D0394-	-01	Prepared &	Analyzed: (04/26/2018				
Mercury	0.0050	0.0010	mg/L	0.005000	0.00020	97	85-115			
Matrix Spike Dup (1804269-MSD1)	So	urce: 18D0394-	-01	Prepared &	Analyzed: (04/26/2018				
Mercury	0.0050	0.0010	mg/L	0.005000	0.00020	96	85-115	1	20	
Batch 1804292 - E200.8 (5.4)										
Blank (1804292-BLK1)				Prepared &	Analyzed: (04/30/2018				
Uranium	ND	0.00050	mg/L	1						
LCS (1804292-BS1)				Prepared &	Analyzed: (04/30/2018				
Uranium	0.046	0.00050	mg/L	0.05000		92	85-115			
LCS Dup (1804292-BSD1)				Prepared &	Analyzed: (04/30/2018				
Uranium	0.046	0.00050	mg/L	0.05000		92	85-115	0.2	20	
Matrix Spike (1804292-MS1)	So	urce: 18D0614-	-01	Prepared &	Analyzed: (04/30/2018				
Uranium	0.051	0.00050	mg/L	0.05000	0.0015	99	70-130			
Batch 1805051 - E 200.7 (4.4)										
Blank (1805051-BLK1)				Prepared &	Analyzed: (05/04/2018				
Calcium	ND	4.0	mg/L							
Iron	ND	0.30	mg/L							
Magnesium	ND	3.0	mg/L							
Potassium	ND	5.0	mg/L							
Sodium	ND	5.0	mg/L							
LCS (1805051-BS1)				Prepared &	Analyzed: (05/04/2018				
Calcium	11	4.0	mg/L	10.00		109	85-115			
Iron	1.0	0.30	mg/L	1.000		104	85-115			
Magnesium	10	3.0	mg/L	10.00		105	85-115			
Potassium	10	5.0	mg/L	10.00		105	85-115			
Sodium	10	5.0	mg/L	10.00		105	85-115			
LCS Dup (1805051-BSD1)				Prepared &	Analyzed: (05/04/2018				
Calcium	11	4.0	mg/L	10.00		110	85-115	1	20	
Iron	1.0	0.30	mg/L	1.000		105	85-115	0.5	20	
Magnesium	10	3.0	mg/L	10.00		105	85-115	0.06	20	
Potassium	10	5.0	mg/L	10.00		105	85-115	0.05	20	
Sodium	11	5.0	mg/L	10.00		109	85-115	4	20	

Client: Brown & Caldwell

 Project:
 PTF

 Work Order:
 18D0619

 Date Received:
 04/25/2018

QC Summary

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Qual
Batch 1805051 - E 200.7 (4.4)										
Matrix Spike (1805051-MS1)	So	urce: 18D0619	-01	Prepared &	Analyzed: (05/04/2018				
Calcium	150	4.0	mg/L	10.00	140	59	70-130			M3
Iron	1.1	0.30	mg/L	1.000	0.028	105	70-130			
Magnesium	38	3.0	mg/L	10.00	27	108	70-130			
Potassium	17	5.0	mg/L	10.00	6.8	105	70-130			
Sodium	170	5.0	mg/L	10.00	170	30	70-130			M3
Matrix Spike (1805051-MS2)	So	urce: 18E0021-	-01	Prepared &	Analyzed: (05/04/2018				
Calcium	64	4.0	mg/L	10.00	54	103	70-130			
Iron	1.0	0.30	mg/L	1.000	0.0060	101	70-130			
Magnesium	21	3.0	mg/L	10.00	11	99	70-130			
Potassium	15	5.0	mg/L	10.00	4.7	104	70-130			
Sodium	99	5.0	mg/L	10.00	90	87	70-130			
Batch 1805069 - E 200.8 (5.4)										
Blank (1805069-BLK1)				Prepared &	Analyzed: (05/07/2018				
Aluminum	ND	0.0400	mg/L	-	-					
Antimony	ND	0.00050	mg/L							
Arsenic	ND	0.00050	mg/L							
Barium	ND	0.00050	mg/L							
Beryllium	ND	0.00025	mg/L							
Cadmium	ND	0.00025	mg/L							
Chromium	ND	0.00050	mg/L							
Cobalt	ND	0.00025	mg/L							
Copper	ND	0.00050	mg/L							
Lead	ND	0.00050	mg/L							
Manganese	ND	0.00025	mg/L							
Nickel	ND	0.00050	mg/L							
Selenium	ND	0.0025	mg/L							
Thallium	ND	0.00050	mg/L							
Zinc	ND	0.040	mg/L							
LCS (1805069-BS1)				Prepared &	Analyzed: (05/07/2018				
Aluminum	0.104	0.0400	mg/L	0.1000		104	85-115			
Antimony	0.048	0.00050	mg/L	0.05000		96	85-115			
Arsenic	0.050	0.00050	mg/L	0.05000		100	85-115			
Barium	0.050	0.00050	mg/L	0.05000		100	85-115			
Beryllium	0.049	0.00025	mg/L	0.05000		97	85-115			
Cadmium	0.050	0.00025	mg/L	0.05000		100	85-115			
Chromium	0.051	0.00050	mg/L	0.05000		102	85-115			
Cobalt	0.051	0.00025	mg/L	0.05000		101	85-115			
Copper	0.051	0.00050	mg/L	0.05000		103	85-115			
Lead	0.049	0.00050	mg/L	0.05000		98	85-115			
Manganese	0.050	0.00025	mg/L	0.05000		101	85-115			
Nickel	0.051	0.00050	mg/L	0.05000		102	85-115			
Selenium	0.051	0.0025	mg/L	0.05000		103	85-115			
Thallium	0.050	0.00050	mg/L	0.05000		101	85-115			
Zinc	0.10	0.040	mg/L	0.1000		101	85-115			
•	0.10	0.0.0								

Client: Brown & Caldwell

 Project:
 PTF

 Work Order:
 18D0619

 Date Received:
 04/25/2018

QC Summary

		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Qual
Batch 1805069 - E 200.8 (5.4)										
LCS Dup (1805069-BSD1)				Prepared &	Analyzed: 0	5/07/2018				
Aluminum	0.115	0.0400	mg/L	0.1000		115	85-115	10	20	
Antimony	0.048	0.00050	mg/L	0.05000		96	85-115	0.7	20	
Arsenic	0.050	0.00050	mg/L	0.05000		101	85-115	0.8	20	
Barium	0.051	0.00050	mg/L	0.05000		102	85-115	1	20	
Beryllium	0.049	0.00025	mg/L	0.05000		97	85-115	0.2	20	
Cadmium	0.050	0.00025	mg/L	0.05000		100	85-115	0.2	20	
Chromium	0.051	0.00050	mg/L	0.05000		102	85-115	0.4	20	
Cobalt	0.050	0.00025	mg/L	0.05000		101	85-115	0.5	20	
Copper	0.052	0.00050	mg/L	0.05000		105	85-115	2	20	
Lead	0.049	0.00050	mg/L	0.05000		98	85-115	0.1	20	
Manganese	0.050	0.00025	mg/L	0.05000		101	85-115	0.09	20	
Nickel	0.051	0.00050	mg/L	0.05000		103	85-115	0.8	20	
Selenium	0.052	0.0025	mg/L	0.05000		104	85-115	2	20	
Γhallium	0.050	0.00050	mg/L	0.05000		101	85-115	0.06	20	
Zinc	0.10	0.040	mg/L	0.1000		104	85-115	3	20	
Matrix Spike (1805069-MS1)	Sou	ırce: 18D0693-	-01	Prepared &	Analyzed: 0	5/07/2018				
Aluminum	0.239	0.0400	mg/L	0.1000	0.166	74	70-130			
Antimony	0.045	0.00050	mg/L	0.05000	0.00024	90	70-130			
Arsenic	0.056	0.00050	mg/L	0.05000	0.0035	104	70-130			
Barium	0.16	0.00050	mg/L	0.05000	0.12	94	70-130			
Beryllium	0.045	0.00025	mg/L	0.05000	0.000029	90	70-130			
Cadmium	0.047	0.00025	mg/L	0.05000	ND	94	70-130			
Chromium	0.049	0.00050	mg/L	0.05000	0.00052	98	70-130			
Cobalt	0.048	0.00025	mg/L	0.05000	0.00097	95	70-130			
Copper	0.051	0.00050	mg/L	0.05000	0.0020	98	70-130			
Lead	0.047	0.00050	mg/L	0.05000	0.00016	94	70-130			
Manganese	0.054	0.00025	mg/L	0.05000	0.0075	94	70-130			
Nickel	0.049	0.00050	mg/L	0.05000	0.0018	94	70-130			
Selenium	0.057	0.0025	mg/L	0.05000	ND	114	70-130			
Γhallium	0.048	0.00050	mg/L	0.05000	0.000038	96	70-130			
Zinc	0.11	0.040	mg/L	0.1000	ND	109	70-130			

Client: Brown & Caldwell

 Project:
 PTF

 Work Order:
 18D0619

 Date Received:
 04/25/2018

QC Summary

		Reporting		Spike	Source		%REC		RPD	
Analyte Charles of Cha	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Qual
Batch 1804261 - SM2540 C										
Duplicate (1804261-DUP1)		rce: 18D0606		Prepared: 04		nalyzed: 0	4/27/2018			
Total Dissolved Solids (Residue, Filterable)	630	20	mg/L		630			0.3	5	
Duplicate (1804261-DUP2)	Sou	rce: 18D0606	5-02	Prepared: 04	1/26/2018 A	nalyzed: 0	4/27/2018			
Total Dissolved Solids (Residue, Filterable)	610	20	mg/L		620			0.8	5	
Batch 1804268 - E335.4										
Blank (1804268-BLK1)				Prepared: 04	1/26/2018 A	nalyzed: 0	4/30/2018			
Cyanide	ND	0.10	mg/L							
LCS (1804268-BS1)				Prepared: 04	1/26/2018 A	nalyzed: 0	4/30/2018			
Cyanide	2.0	0.10	mg/L	2.000		101	90-110			
LCS Dup (1804268-BSD1)				Prepared: 04	1/26/2018 A	nalyzed: 0	4/30/2018			
Cyanide	2.0	0.10	mg/L	2.000		101	90-110	0.1	20	
Matrix Spike (1804268-MS1)	Sou	rce: 18D0602	2-03	Prepared: 04	1/26/2018 A	nalyzed: 0	4/30/2018			
Cyanide	2.1	0.10	mg/L	2.000	ND	103	90-110			
Matrix Spike Dup (1804268-MSD1)	Sou	rce: 18D0602	2-03	Prepared: 04	1/26/2018 A	nalvzed: 0	4/30/2018			
Cyanide	2.0	0.10	mg/L	2.000	ND	98	90-110	5	20	
Batch 1804272 - E150.1										
Duplicate (1804272-DUP1)	Sou	rce: 18D0662	2-02	Prepared &						
pH (pH Units)	7.8		-		7.8			0.1	200	H5
Temperature (°C)	21		-		21			2	200	Н5
Batch 1805027 - SM2320B										
LCS (1805027-BS1)				Prepared &	Analyzed: 0	5/03/2018				
Alkalinity, Total (As CaCO3)	240	2.0	mg/L	250.0		96	90-110			
LCS Dup (1805027-BSD1)				Prepared &	Analyzed: 0	5/03/2018				
Alkalinity, Total (As CaCO3)	240	2.0	mg/L	250.0		96	90-110	0	10	
Matrix Spike (1805027-MS1)	Sou	rce: 18D0606	5-02	Prepared &	Analyzed: 0	5/03/2018				
Alkalinity, Total (As CaCO3)	370	2.0	mg/L	250.0	130	96	85-115			
Matrix Spike Dup (1805027-MSD1)	Sou	rce: 18D0606	5-02	Prepared &	Analyzed: 0	5/03/2018				
Alkalinity, Total (As CaCO3)	370	2.0	mg/L	250.0	130	95	85-115	0.5	10	
Batch 1805103 - SM2510 B										
LCS (1805103-BS1)				Prepared &	Analyzed: 0	5/09/2018				
Conductivity	140	0.10	μmhos/cm	141.2		101	0-200			
LCS Dup (1805103-BSD1)				Prepared &	Analyzed: 0	5/09/2018				
Conductivity	140	0.10	μmhos/cm	141.2		101	0-200	0.7	200	
Duplicate (1805103-DUP1)	Sou	rce: 18E0192	-01	Prepared &	Analyzed: 0	5/09/2018				
Conductivity	4.0	0.10	μmhos/cm		4.0			0	10	

Client: Brown & Caldwell

 Project:
 PTF

 Work Order:
 18D0619

 Date Received:
 04/25/2018

QC Summary

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Qual
Batch 1805074 - SW8260B										
Blank (1805074-BLK1)				Prepared &	Analyzed:	05/07/2018	;			
Benzene	ND	0.50	ug/L	•	•					
Carbon disulfide	ND	2.0	ug/L							
Ethylbenzene	ND	0.50	ug/L							
Toluene	ND	0.50	ug/L							
Xylenes, Total	ND	1.5	ug/L							
Surrogate: 4-Bromofluorobenzene	25.0		ug/L	25.00		100	70-130			
Surrogate: Dibromofluoromethane	26.9		ug/L	25.00		107	70-130			
Surrogate: Toluene-d8	25.1		ug/L	25.00		100	70-130			
LCS (1805074-BS1)				Prepared &	Analyzed:	05/07/2018	}			
1,1-Dichloroethene	29		ug/L	25.00		114	70-130			
Benzene	27		ug/L	25.00		109	70-130			
Chlorobenzene	29		ug/L	25.00		115	70-130			
Toluene	25		ug/L	25.00		101	70-130			
Trichloroethene	26		ug/L	25.00		103	70-130			
Surrogate: 4-Bromofluorobenzene	24.6		ug/L	25.00		98	70-130			
Surrogate: Dibromofluoromethane	25.6		ug/L	25.00		102	70-130			
Surrogate: Toluene-d8	24.8		ug/L	25.00		99	70-130			
LCS Dup (1805074-BSD1)				Prepared &	Analyzed:	05/07/2018	;			
1,1-Dichloroethene	27		ug/L	25.00		110	70-130	4	30	
Benzene	26		ug/L	25.00		104	70-130	5	30	
Chlorobenzene	26		ug/L	25.00		105	70-130	9	30	
Toluene	24		ug/L	25.00		96	70-130	5	30	
Trichloroethene	25		ug/L	25.00		98	70-130	4	30	
Surrogate: 4-Bromofluorobenzene	24.4		ug/L	25.00		98	70-130			
Surrogate: Dibromofluoromethane	26.1		ug/L	25.00		104	70-130			
Surrogate: Toluene-d8	25.1		ug/L	25.00		100	70-130			
Matrix Spike (1805074-MS1)	So	urce: 18D0582-	-02	Prepared &	Analyzed:	05/07/2018	;			
1,1-Dichloroethene	27		ug/L	25.00	0.070	109	70-130			
Benzene	26		ug/L	25.00	0.020	104	70-130			
Chlorobenzene	26		ug/L	25.00	0.0	105	70-130			
Toluene	27		ug/L	25.00	3.5	95	70-130			
Trichloroethene	24		ug/L	25.00	0.040	97	70-130			
Surrogate: 4-Bromofluorobenzene	24.4		ug/L	25.00		98	70-130			
Surrogate: Dibromofluoromethane	26.4		ug/L	25.00		106	70-130			
Surrogate: Toluene-d8	24.9		ug/L	25.00		100	70-130			
Matrix Spike Dup (1805074-MSD1)	So	urce: 18D0582-	-02	Prepared &	Analyzed:	05/07/2018	<u> </u>			
1,1-Dichloroethene	27		ug/L	25.00	0.070	108	70-130	0.8	30	
Benzene	25		ug/L	25.00	0.020	101	70-130	2	30	
Chlorobenzene	26		ug/L	25.00	0.0	105	70-130	0.3	30	
Toluene	27		ug/L	25.00	3.5	95	70-130	0.1	30	
Trichloroethene	24		ug/L	25.00	0.040	95	70-130	2	30	
Surrogate: 4-Bromofluorobenzene	24.7		ug/L	25.00		99	70-130			
Surrogate: Dibromofluoromethane	26.4		ug/L	25.00		106	70-130			
Surrogate: Toluene-d8	25.3		ug/L	25.00		101	70-130			

Client: Brown & Caldwell

 Project:
 PTF

 Work Order:
 18D0619

 Date Received:
 04/25/2018

QC Summary

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Qual
Batch 1804245 - E300.0 (2.1)			0.2220			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				Q
Blank (1804245-BLK1)				Prepared &	Analyzed: (04/25/2018				
Chloride	ND	1.0	mg/L							
Fluoride	ND	0.50	mg/L							
Nitrogen, Nitrate (As N)	ND	0.50	mg/L							
Nitrogen, Nitrite (As N)	ND	0.10	mg/L							
Sulfate	ND	5.0	mg/L							
LCS (1804245-BS1)				Prepared &	Analyzed: (04/25/2018				
Chloride	12	1.0	mg/L	12.50		92	90-110			
Fluoride	2.0	0.50	mg/L	2.000		101	90-110			
Nitrogen, Nitrate (As N)	4.7	0.50	mg/L	5.000		95	90-110			
Nitrogen, Nitrite (As N)	2.3	0.10	mg/L	2.500		92	90-110			
Sulfate	12	5.0	mg/L	12.50		96	90-110			
LCS Dup (1804245-BSD1)				Prepared &	Analyzed: (04/25/2018				
Chloride	12	1.0	mg/L	12.50		94	90-110	2	10	
Fluoride	2.0	0.50	mg/L	2.000		101	90-110	0.4	10	
Nitrogen, Nitrate (As N)	4.9	0.50	mg/L	5.000		98	90-110	3	10	
Nitrogen, Nitrite (As N)	2.4	0.10	mg/L	2.500		95	90-110	3	10	
Sulfate	12	5.0	mg/L	12.50		98	90-110	3	10	
Matrix Spike (1804245-MS1)	Sor	ırce: 18D0613-	-08	Prepared &	Analyzed: (04/25/2018				
Fluoride	3.7	0.50	mg/L	2.000	1.7	100	80-120			
Nitrogen, Nitrate (As N)	4.7	0.50	mg/L	5.000	0.22	89	80-120			
Matrix Spike (1804245-MS2)	Sor	ırce: 18D0625-	-01	Prepared &	Analyzed: (04/26/2018				
Nitrogen, Nitrate (As N)	5.0	0.50	mg/L	5.000	0.46	92	80-120			
Nitrogen, Nitrite (As N)	2.2	0.10	mg/L	2.500	ND	88	80-120			
Matrix Spike (1804245-MS3)	Sor	ırce: 18D0614	-01RE1	Prepared &	Analyzed: (04/26/2018				
Chloride	17		mg/L	12.50	6.4	88	80-120			
Sulfate	28		mg/L	12.50	18	85	80-120			
Matrix Spike Dup (1804245-MSD1)	Sor	ırce: 18D0613-	-08	Prepared &	Analyzed: (04/25/2018				
Fluoride	3.7	0.50	mg/L	2.000	1.7	100	80-120	0.4	10	
Nitrogen, Nitrate (As N)	4.7	0.50	mg/L	5.000	0.22	90	80-120	0.6	10	
Matrix Spike Dup (1804245-MSD2)	Sor	ırce: 18D0625-	-01	Prepared &	Analyzed: (04/26/2018				
Nitrogen, Nitrate (As N)	5.1	0.50	mg/L	5.000	0.46	92	80-120	0.2	10	
Nitrogen, Nitrite (As N)	2.2	0.10	mg/L	2.500	ND	88	80-120	0.4	10	
Matrix Spike Dup (1804245-MSD3)	Sor	ırce: 18D0614	-01RE1	Prepared &	Analyzed: (04/26/2018				
Chloride	18		mg/L	12.50	6.4	89	80-120	0.6	10	
Sulfate	29		mg/L	12.50	18	86	80-120	0.6	10	



CHAIN OF CUSTODY/LABORATORY ANALYSIS REQUEST FORM

- DATE \$123 (S) TURNER WORK ORDER # 1806 619

QF.

PAGE

PROJECT NAME_Florence Copper#			CIRCI	E AN	4LYSI!	S REQ	UESTED	AND/OR (CHECKT	HE APP	CIRCLE ANALYSIS REQUESTED AND/OR CHECK THE APPROPRIATE BOX	
CONTACT NAME : Barb Sylvester	SA						_					
COMPANY NAME: Brown and Caldwell		× 1000000				71<	(¢tə)		_			
ADDRESS: 2 N Central Ave, Suite 1600	CONT	- Annual Control			(qn	edqlA						
CITY Phoenix STATE AZ ZIP CODE 85004	9 1907				is Vaəl	.e if G.						
PHONE_602-567-3894 ,FAX	50V	ı) wn			_	τίνίτγ						
SAMPLER'S SIGNATURE (L.)	NUN sletəM	Urani	· soine;	ide (fro l - soin	у) ' ецс	oe wni	8SS ,8					
SAMPLE I.D. DATE TIME LAB I.D. SAMPLE MATRIX*		Total				Uran						
	101	Y	_	_^	_		_					F
\$260 TB 4-23-18 160c GW	_		_	×								
MS												
MS												F
MS												
MB												
MS GW									-			I
MS GW												
MB												
M9 GM												
M9 GM												
1. RELINQUISHED BY: TURNAF	TURNAROUND REQUIREMENTS:	REMENT		REPO	RT REQU	REPORT REQUIREMENTS:	VTS:	INVOICE INFORMATION:	NFORM/	TION	SAMPLE RECEIPT:	T
200	X Standard (approx10 days)*	*js/i	×	 8	I. Routine Report	ort)		
Signature Signature Next day	V_2 Day_	_S Day*	real	II. Repo	rt (includ	II. Report (includes DUP,MS,MSD	II. Report (includes DUP,MS,MSD, as red. may be charged as samples)	Account X	N ≻		Total Containers	
Printed Name	Email Preliminary Results To:	.To:	All A	III. Date	Validatio	n Report	III. Date Validation Report (Includes	P.O.#			Temperature 7	7
Firm			Add	Add 10% to invoice	woice							
2018 1630	ays		-	×				Bill to: Florence Copper	се Сорр	er	☑ Wet Ice □ BI	Blue Ice
W.	*LEGEND		SP	ECIAL	INSTE	NCTI	ONS/CO	SPECIAL INSTRUCTIONS/COMMENTS:				
1	DW = DRINKING WATER GW = GROUNDWATER	22	Co	Compliance Analysis:	Analys	100	☐ Yes ☐ No	lo Custody Seals	Seals	□ Pre	Preservation Confirmation	Ø
(a) actemo	D		AD	ADEQ Forms:	rms:		☐ Yes ☐ No		Container Intact	App App	Appropriate Head Space	M
Firm TURNER LABORATORIES INC. SG = SUUDGE	JGE		ž	il ADE	Q For	Mail ADEQ Forms: Yes	Yes No		COC/Labels Agree	Z Kee	Received Within Hold Time	
2	ST = STORMWATER											
M-101	BIEWAIEN		1		l						Page	13 of 32



Ask-

www.testamericainc.com

Visit us at:

Expert

TestAmerica

THE LEADER IN ENVIRONMENTAL TESTING

ANALYTICAL REPORT

TestAmerica Laboratories, Inc.

TestAmerica Phoenix 4625 East Cotton Ctr Blvd Suite 189 Phoenix, AZ 85040

Tel: (602)437-3340

TestAmerica Job ID: 550-101943-1

Client Project/Site: 18D0619

For:

Turner Laboratories, Inc. 2445 North Coyote Drive Suite 104 Tucson, Arizona 85745

Attn: Kevin Brim

Authorized for release by: 5/16/2018 12:23:25 PM

Ken Baker, Project Manager II (602)659-7624

ken.baker@testamericainc.com

This report has been electronically signed and authorized by the signatory. Electronic signature is intended to be the legally binding equivalent of a traditionally handwritten signature.

Results relate only to the items tested and the sample(s) as received by the laboratory.

Client: Turner Laboratories, Inc. Project/Site: 18D0619

Table of Contents

Cover Page	1
Table of Contents	2
Definitions/Glossary	3
Case Narrative	4
Sample Summary	5
Detection Summary	6
Client Sample Results	7
Surrogate Summary	8
QC Sample Results	9
QC Association Summary	10
Lab Chronicle	11
Certification Summary	12
Method Summary	13
Chain of Custody	14
Receipt Checklists	15

9

11

12

14

Definitions/Glossary

Client: Turner Laboratories, Inc.

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Qualifiers

GC Semi VOA

Q9 Insufficient sample received to meet method QC requirements.

Glossary

Abbreviation	These commonly used abbreviations may or may not be present in this report.

Listed under the "D" column to designate that the result is reported on a dry weight basis

%R Percent Recovery **CFL** Contains Free Liquid **CNF** Contains No Free Liquid

DER Duplicate Error Ratio (normalized absolute difference)

Dil Fac Dilution Factor

DL Detection Limit (DoD/DOE)

DL, RA, RE, IN Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample

Decision Level Concentration (Radiochemistry) DLC

Estimated Detection Limit (Dioxin) **EDL** LOD Limit of Detection (DoD/DOE) LOQ Limit of Quantitation (DoD/DOE)

MDA Minimum Detectable Activity (Radiochemistry) MDC Minimum Detectable Concentration (Radiochemistry)

MDL Method Detection Limit ML Minimum Level (Dioxin)

NC Not Calculated

Not Detected at the reporting limit (or MDL or EDL if shown) ND

PQL Practical Quantitation Limit

QC **Quality Control**

RER Relative Error Ratio (Radiochemistry)

Reporting Limit or Requested Limit (Radiochemistry) RL

RPD Relative Percent Difference, a measure of the relative difference between two points

TEF Toxicity Equivalent Factor (Dioxin) Toxicity Equivalent Quotient (Dioxin) **TEQ**

3

Case Narrative

Client: Turner Laboratories, Inc.

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Job ID: 550-101943-1

Laboratory: TestAmerica Phoenix

Narrative

Job Narrative 550-101943-1

Comments

No additional comments.

Receipt

The sample was received on 4/27/2018 10:50 AM; the sample arrived in good condition, properly preserved and, where required, on ice. The temperature of the cooler at receipt was 3.8° C.

GC Semi VOA

Method(s) 8015D: Insufficient sample volume was available to perform a matrix spike/matrix spike duplicate/sample duplicate (MS/MSD) associated with preparation batch 550-145985 and analytical batch 550-146884. Affected samples have been added a Q9 qualifier. 18D0619-01 (550-101943-1)

No additional analytical or quality issues were noted, other than those described above or in the Definitions/Glossary page.

Organic Prep

Method(s) 3510C: Insufficient sample volume was available to perform a matrix spike/matrix spike duplicate (MS/MSD) associated with 3510C.

No additional analytical or quality issues were noted, other than those described above or in the Definitions/Glossary page.

2

3

4

<u>၂</u>

7

8

9

10

13

14

Sample Summary

Client: Turner Laboratories, Inc. Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Lab Sample ID	Client Sample ID	Matrix	Collected Received
550-101943-1	18D0619-01	Water	04/23/18 15:55 04/27/18 10:50

Detection Summary

Client: Turner Laboratories, Inc.

Client Sample ID: 18D0619-01

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Lab Sample ID: 550-101943-1

Analyte	Result Qualifier	RL	Unit	Dil Fac D	Method	Prep Type
ORO (C22-C32)	0.21 Q9	0.20	mg/L		8015D	Total/NA

3

4

5

6

8

9

11

12

13

41

Client Sample Results

Client: Turner Laboratories, Inc.

Client Sample ID: 18D0619-01

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Lab Sample ID: 550-101943-1

Matrix: Water

Date Collected: 04/23/18 15:55 Date Received: 04/27/18 10:50

Method: 8015D - Diesel Range Organics (DRO) (GC)

Metriod, 6013D - Dieser Kange Organics (DRO) (GC)									
	Analyte	Result	Qualifier	RL	Unit	D	Prepared	Analyzed	Dil Fac
	ORO (C22-C32)	0.21	Q 9	0.20	mg/L		04/30/18 14:16	05/10/18 23:29	1
	DRO (C10-C22)	ND	Q9	0.10	mg/L		04/30/18 14:16	05/10/18 23:29	1

Surrogate	%Recovery Qualifie	r Limits	Prepared	Analyzed	Dil Fac
o-Terphenyl (Surr)	79	10 - 150	04/30/18 14:16	05/10/18 23:29	1

Surrogate Summary

Client: Turner Laboratories, Inc.

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

2

3

Method: 8015D - Diesel Range Organics (DRO) (GC)

Matrix: Water Prep Type: Total/NA

Recovery (Acceptance Limits)
_

TestAmerica Phoenix

Page 21 of 32

QC Sample Results

Client: Turner Laboratories, Inc.

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Method: 8015D - Diesel Range Organics (DRO) (GC)

Lab Sample ID: MB 550-145985/1-A	Client Sample ID: Method Blank
Matrix: Water	Prep Type: Total/NA
Analysis Batch: 146884	Prep Batch: 145985
MR MR	·

	MB MB	3				•	
Analyte	Result Qu	alifier RL	Unit	D	Prepared	Analyzed	Dil Fac
ORO (C22-C32)	ND ND	0.20	mg/L		04/30/18 14:15	05/11/18 11:16	1
DRO (C10-C22)	ND	0.10	mg/L		04/30/18 14:15	05/11/18 11:16	1
	MB MB	3					

	MB	MB				
Surrogate	%Recovery	Qualifier	Limits	Prepared	Analyzed	Dil Fac
o-Terphenyl (Surr)	65		10 - 150	04/30/18 14:15	05/11/18 11:16	1
-						

Lab Sample ID: LCS 550-7 Matrix: Water Analysis Batch: 146884	145985/2-A					Clie	nt Sa	mple ID	Prep Type: Total/NA Prep Batch: 145985
			Spike	LCS	LCS				%Rec.
Analyte			Added	Result	Qualifier	Unit	D	%Rec	Limits
ORO (C22-C32)			1.60	1.59		mg/L		99	69 - 107
DRO (C10-C22)			0.400	0.450		mg/L		113	42 - 133
	LCS	LCS							
Surrogate	%Recovery	Qualifier	Limits						
o-Terphenyl (Surr)	79		10 - 150						

Lab Sample ID: LCSD 550-145985/3-A Matrix: Water			C	Client S	ample	ID: Lab	Control Prep Ty	•	•
Analysis Batch: 146884							Prep Ba	itch: 14	45985
	Spike	LCSD	LCSD				%Rec.		RPD
Analyte	Added	Result	Qualifier	Unit	D	%Rec	Limits	RPD	Limit
ORO (C22-C32)	1.60	1.59		mg/L		100	69 - 107	0	20
DRO (C10-C22)	0.400	0.447		mg/L		112	42 - 133	1	22

DRO (C10-C22)		0.400	0.447	
	LCSD LCSD			
Surrogate	%Recovery Qualifier	Limits		
o-Terphenyl (Surr)	79	10 - 150		

TestAmerica Phoenix

Page 22 of 32

Page 9 of 15

2

3

1

5

7

8

9

10

11

12

4 4

-

QC Association Summary

Client: Turner Laboratories, Inc.

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

2

GC Semi VOA

Prep Batch: 145985

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method Prep Batch	ı
550-101943-1	18D0619-01	Total/NA	Water	3510C	
MB 550-145985/1-A	Method Blank	Total/NA	Water	3510C	
LCS 550-145985/2-A	Lab Control Sample	Total/NA	Water	3510C	
LCSD 550-145985/3-A	Lab Control Sample Dup	Total/NA	Water	3510C	

Analysis Batch: 146884

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
550-101943-1	18D0619-01	Total/NA	Water	8015D	145985
MB 550-145985/1-A	Method Blank	Total/NA	Water	8015D	145985
LCS 550-145985/2-A	Lab Control Sample	Total/NA	Water	8015D	145985
LCSD 550-145985/3-A	Lab Control Sample Dup	Total/NA	Water	8015D	145985

3

4

5

7

0

10

11

40

14

Lab Chronicle

Client: Turner Laboratories, Inc.

Date Received: 04/27/18 10:50

Analysis

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Lab Sample ID: 550-101943-1

Client Sample ID: 18D0619-01 Date Collected: 04/23/18 15:55 Matrix: Water

Batch Batch Dilu **Prep Type** Method Run Fa Type Total/NA Prep 3510C

8015D

ution	Batch	Prepared			
actor	Number	or Analyzed	Analyst	Lab	
	145985	04/30/18 14:16	REM	TAL PHX	
1	146884	05/10/18 23:29	TC1	TAL PHX	

Laboratory References:

Total/NA

TAL PHX = TestAmerica Phoenix, 4625 East Cotton Ctr Blvd, Suite 189, Phoenix, AZ 85040, TEL (602)437-3340

TestAmerica Phoenix

Accreditation/Certification Summary

Client: Turner Laboratories, Inc.

TestAmerica Job ID: 550-101943-1

Project/Site: 18D0619

Laboratory: TestAmerica Phoenix

Unless otherwise noted, all analytes for this laboratory were covered under each accreditation/certification below.

Authority Arizona	Program State Prog	ram	EPA Region	AZ0728	Expiration Date 06-09-18
Analysis Method	Prep Method	Matrix	Analyt	e	

2

Method Summary

Client: Turner Laboratories, Inc.

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Method	Method Description	Protocol	Laboratory
8015D	Diesel Range Organics (DRO) (GC)	SW846	TAL PHX
3510C	Liquid-Liquid Extraction (Separatory Funnel)	SW846	TAL PHX

Protocol References:

SW846 = "Test Methods For Evaluating Solid Waste, Physical/Chemical Methods", Third Edition, November 1986 And Its Updates.

Laboratory References:

TAL PHX = TestAmerica Phoenix, 4625 East Cotton Ctr Blvd, Suite 189, Phoenix, AZ 85040, TEL (602)437-3340

2

4

5

6

a

10

11

12

14

15

Page 26 of 32

SUBCONTRACT ORDER

Turner Laboratories, Inc.

18D0619

SENDING LABORATORY:

Turner Laboratories, Inc.

2445 N. Coyote Drive, Ste #104

Tucson, AZ 85745 Phone: 520.882.5880 Fax: 520.882.9788

Project Manager: Kevin Brim

RECEIVING LABORATORY:

TestAmerica Phoenix

4625 East Cotton Center Boulevard Suite 189

Phoenix, AZ 85540 Phone :(602) 437-3340

Fax:

Please CC Kevin Brim Kbrim@turnerlabs.com

Analysis

Expires

Laboratory ID

Comments

-07

Sample ID: 18D0619-01 Drinking Water Sampled: 04/23/2018 15:55

8015D Sub

04/30/2018 15:55

8015D DRO and ORO Paramaters Only

Containers Supplied:

8015D Sub

o-Terphenyl C10-C32 (Total) C22-C32 (Oil Range Organics) C10-C22 (Diesel Range Organics) C6-C10 (Gasoline Range Organics)



(3,8°2) UPS GR

TA-PHX

Released By

Date

Received By

トコス

Date

Page 1 of 1

Released By

Date

Received

Page 27 of 32

Login Sample Receipt Checklist

Client: Turner Laboratories, Inc.

Job Number: 550-101943-1

Login Number: 101943 List Source: TestAmerica Phoenix

List Number: 1

Creator: Gravlin, Andrea

orcator. Gravini, Anarca		
Question	Answer	Comment
Radioactivity wasn't checked or is = background as measured by a survey meter.</td <td>True</td> <td></td>	True	
The cooler's custody seal, if present, is intact.	True	
Sample custody seals, if present, are intact.	True	
The cooler or samples do not appear to have been compromised or tampered with.	True	
Samples were received on ice.	True	
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	True	
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
Is the Field Sampler's name present on COC?	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
Appropriate sample containers are used.	True	
Sample bottles are completely filled.	True	
Sample Preservation Verified.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	True	
Multiphasic samples are not present.	True	
Samples do not require splitting or compositing.	True	
Residual Chlorine Checked.	False	Check done at department level as required.



Radiation Safety Engineering, Inc.

3245 N. WASHINGTON ST. + CHANDLER, ARIZONA 85225-1121

(480) 897-9459

Website: www.radsafe.com

FAX (480) 892-5446

Radiochemical Activity in Water (pCi/L)

Turner Laboratories 2445 N. Coyote Drive, Ste. 104 Tucson, AZ 85745

Sampling Date: April 23, 2018 Sample Received: May 01, 2018 Analysis Completed: May 22, 2018

Sample ID	Gross Alpha Activity Method 600/00-02 (pCi/L)	Uranium Activity Method ASTM D6239 (pCi/L)	Adjusted Gross Alpha (pCi/L)	Radium 226 Activity Method GammaRay HPGE (pCi/L)	Radium 228 Activity Method GammaRay HPGE (pCi/L)	Total Radium (pCi/L)
18D0619-01	17.7 ± 0.9	12.9 ± 1.2	4.8 ± 1.5	3.1 ± 0.3	3.1 ± 0.4	6.2 ± 0.5

					T	
Date of Analysis	5/2/2018	5/21/2018	5/21/2018	5/4/2018	5/4/2018	5/4/2018

Robert L. Metzger, Ph.D., C.H.P.

5/22/2018

Laboratory License Number AZ0462

Date



Radiation Safety Engineering, Inc.

3245 N. WASHINGTON ST. + CHANDLER, ARIZONA 85225-1121 Website: www.radsafe.com

(480) 897-9459 FAX (480) 892-5446

Isotopic Uranium Analysis

Turner Laboratories 2445 N. Coyote Drive, Ste. 104 Tucson, AZ 85745

Sampling Date: April 23, 2018 Sample Received: May 01, 2018 Uranium Analysis Date: May 21, 2018

Sample No.	²³⁸ U	²³⁵ U	²³⁴ U	Total	
18D0619-01	6.0 ± 0.6	0.280 ± 0.004	6.6 ± 0.6	12.9 ± 1.2	Activity (pCi/L)
	17.9 ± 1.7	0.131 ± 0.002	0.00106 ± 0.00010	18.0 ± 1.7	Content (μg/L)
	Comments:		Page 11 and 12		

Robert L. Metzger, Ph.D., C.H.P.

5/22/2018

Date

Laboratory License Number AZ0462

Arizona Department of Environmental Quality

Drinking Water Radionuclides-Adjusted Gross Alpha, Radium 226 & 228, Uranium Analysis Report ***Samples To Be Taken At Entry Point Into Distribution System (EPDS) Only***

PWS ID#: AZ04 April 23, 2018				PWS Name:					
		15:55	(24 hour clock)						
Sample Date			me	Owner/Contact Person					
Owner/Contact Fax Number				Owner/Contact Phone Number					
Sample Collection EPDS #	ction Point								
Complianc	e Sample	Type:							
Reduced Monitoring			Date (Q1 collected:					
Quar	terly		¥1	Date (Q2 collected:		_		
Composite of four quarterly samples			Date (Q3 collected:		_			
	1	\$1	.Me	Date (Q4 collected:	19	-		
Per			***RADIOCHEN >>>To be filled out b			• • • • • • • • • • • • • • • • • • • •		2	
		***Coml	pined Uranium must be						
Analysis Method	MCL	Reporting Limit	Contaminant	Cont. Code	Analyses Run Date	Result		Exceed	
	15 pCi/L		Adjusted Gross Alpha	4000	5/21/2018	4.8 ± 1.5		MCL	
600/00-02		3 pCi/L	Gross Alpha	4002	5/2/2018	$\frac{4.8 \pm 1.3}{17.7 \pm 0.9}$	-		
7500 - Rn			Radon	4004	3/2/2016	17.7 ± 0.9	-		
ASTM D6239	30 μg/L	1 μg/L	Combined Uranium	4006	5/21/2018	18.0 ± 1.7	- "		
			Uranium 234	4007	5/21/2018	0.00106 ± 0.00010	μg/L		
			Uranium 235	4008	5/21/2018	0.00708 ± 0.00070 0.131 ± 0.002			
			Uranium 238	4009	5/21/2018	17.9 ± 1.7			
	5 pCi/L	1 pCi/L	Combined Radium (226,228)	4010	5/4/2018	6.2 ± 0.5	-	х	
GammaRay HPGE		1 pCi/L	Radium 226	4020	5/4/2018	3.1 ± 0.3		Λ	
GammaRay HPGE		1 pCi/L	Radium 228	4030	5/4/2018	3.1 ± 0.4			
			***LABORATORY I	NEODMA	TIONALL		•		
		5	>>>To be filled out by la						
Specimen Numb	er DCEA		>>>To be filled out by la	вогатогу р	ersonner<<				
	-	50312	>>>To be filled out by la	- -	ersonner				
Specimen Numb Lab ID Number: Lab Name: R.	AZ04	60312 62		- - -	ersonner				
Lab ID Number: Lab Name: R	AZ04 adiation Safe	60312 62 ty Engineering	, Inc.	-		50			
Lab ID Number: Lab Name: R Printed Name an	AZ04 adiation Safe	60312 62 ty Engineering	, Inc.	-	C.H.P. (480) 897-94	59			

DWAR 6: 11/2007

SUBCONTRACT ORDER

Turner Laboratories, Inc. 18D0619

SENDING LABORATORY:

Turner Laboratories, Inc.

2445 N. Coyote Drive, Ste #104

Tucson, AZ 85745

Phone: 520.882.5880 Fax: 520.882.9788

Project Manager:

Kevin Brim

RECEIVING LABORATORY:

Radiation Safety Engineering, Inc.

3245 N. Washington St.

Chandler, AZ 85225-1121

Phone: (480) 897-9459

Fax: (480) 892-5446

Please CC Kevin Brim Kbrim@turnerlabs.com

Analysis

Expires

Laboratory ID

Comments

Sample ID: 18D0619-01 Drinking Water Sampled:04/23/2018 15:55

Radiochemistry, Gross Alpha

Radiochemistry, Radium 226/228

10/20/2018 15:55

Analyze Uranium and Adjusted Alpha if G. Alpha is > 12

Containers Supplied:

05/23/2018 15:55

tt 60312

Received By

Released By

Date

Received By

Date

APPENDIX D

Well Completion Documentation

PIPE TALLY \mathcal{O}

Project Name.: FC PTF	Project No.: 129687-007
Well No.: (5-06	Date: 2 (0/18
Location: Florenco, AZ	Pipe Talley for: Well Installation
Total Depth:	Geologist: S. Kane.
Type of Connections: 🔲 Welded 🚨 T+C 🗷 Flush	Thread Other

Pipe	\ \	Length	Length ∑	Pipe Type	Dist. from sensor bottom to bottom of	Sensor Type (ACD, CS,	Sensor ID	Wire Lead ID	Depth of Sensor
		(ft)	(ft)		pipe (feet)	ERT)		TWING ECAN ID	(feet bgs)
1	17,	0.36	0.36	SSENdrap	pipe (feet)	ERTS	105K		
2	V,	20.05		SCH80 PUCL	5.90	ERT	10		1194 94
ب	1	20.06	40.47	Sincerous	0				
4	大		0.036050						
	W,	20.05	80.55						
φ 7	11/	20.05	100.60		0.75	ERT	9		1119,93
		20.03							
ઈ	-X/	20.00			. Rec				
9	+	20.02			15.90	ERT	8		1044.68
<u>(0</u>	K,	20.05							
	1	20.05	200.77						
13	1	20.04			* 4				
13	-1%		240.86		11.00	ERT	7		969.42
15	 	20.04	260.93						
16	*	20.04	280.96						
10	 	20.04	301.00		~ SIM	==0			004 90
18	K	20.06	341.10		5.80	ERT	<u></u>		894.43
19	17		361.14						
35	1/1		381.21						
21	7	30.05	401.26		0.75	ERT	5		0100
22	- 1 /2		421 27		0.73	DICI	3		819.27
03	7	30.04	441.31						
24	N,	20.06			15.66	ERT	4		744,26
25	J		481.40		13.00		-4		14,20
06	K.	20.02							
	<i>L</i>		521.46						
ე <u>ე</u> 2&_		20.04	541.50		11.06	ERT	3		668:11
39		20.05	561.55			·	<u> </u>		<u> </u>
30	A	20.05	581.60	No.					

Notes:	SUMMARY OF 1	ALLY
	Total Length tallied:	1301-23 12116
40 feet	Casing Stick-Up:	1.05
AS centralizer placed 5.2 from top	Length of Casing Cut-Off: (Land 169)	9.40
of joint dule to proximity to	Bottom of Well:	1201.23
Sensor	Screened Interval: 1200.84 - 499. 40	70.00
	Total Screen in Hole:	701.44
joint due to proximity to sensor	Sensor Types: Annular Conductivity Device (A	CD), installed as pairs with 3 ft spacing
	Conductivity Sensor (CS) 4 sen	sors with sing lead 20 ft spacing
	Electrical Resistivity Tomograph	

ERT Sensor 5/N: 6113497304-2-65 1305' Length, 55' Spacing

ALDRICH

9.35 - 10/11 who capier

7.5 inches - 70.6 feet

PIPE TALLY

roject N	lame.:	PCI	PTE		Project No.: 12	1627-0	つひフ		
Vell No.:	<u>6-</u>	<i>196</i>			Date: 2 6 1	8			
ocation	: <i>Fla</i>	renco	A2		Pipe Talley for:		1		
otal Dep					Geologist: S.//	one o	M. Hens	man	
ype of C	Connect	ions: 🚨	Welded 🚨	T+C 🔀 Flush	Thread 🚨 Other	<i>d</i>	·		
Pipe	✓	Length (ft)	Length ∑	Pipe Type	Dist. from sensor bottom to bottom of pipe (feet)	Sensor Type (ACD, CS, ERT)	Sensor ID	Wire Lead ID	Depth of Sensor (feet bgs)
3) 20	M	20.05	601.65	SCH 80PUC		THE RESERVE OF THE PARTY OF THE	-2-		6 15, 63
32				Screen D.62		報	2		E34 F
23	×	20.05	641.73	1	, vivi				543.57
37		20.03	661.76					,	
35	×	20.05							
36	B.	20.02		1	. 8	EKT			8-17 1-
37		0.60		SS PUC - FRP		EL	I .		518.12
	*	29 49	702.15	Fiberylass					
39	*	29.10	7/1/2	Hiperylass					
40		29.14	760.63						
721		19 2	818-98		2000	<i>i p</i>			
			840 01		27.57	<u> </u>			335.00
		29.28			18.51	CS	_3		363.75
	W	29.34	877.6		9.84	CS	2		343.14
14	*		906.7		.01	CS ACD			323.63
			935.75		23.66		24		270.88
			964.86	also,	6/26.51	KKA	ĭ		268.03
	*	29.11	993.97		*				
			1023.05					,	
	V		10.52.09						
50			1081.1						
9/ 3	Ar		1110.12						
		29.05	1139.17						
T3 5	A	29.02	1168.19						
4 2	*	28.90	1197.09						
5 V	/ 1	5,20	1202.29	V					· · · · · · · · · · · · · · · · · · ·
6	-		1211.69	- YEMB					
				For lan	11.401				
201									
es:	61 B	ece	Nas 9.	1 hans 1	Total Length tallied:	S	UMMARY OF TAI	.LY	
PUM	tart	to call	OF L		Casing Stick-Up:		-	- WS-COM-	
	76.5				Length of Casing Cut	-Off:	-		
			*		Bottom of Well:	-11.	-		
					Screened Interval:		_		
					Total Screen in Hole:				
					Sensor Types: A	nnular Conduc	tivity Device (ACD), installed as pair	s with 3 ft spacing
					C	onductivity Se	nsor (CS) 4 sensor	s with sing lead 2) ft spacing
					E	lectrical Resist	ivity Tomography	ERT)	
									HALEY
									ALDRIG

2.6

5.99

Hilly 9.4

Casing Layout

Project Name.:	Florence Copper INC	Project No.:	129687-007
Well No.:	O-06	Date:	2.6.18
Location:	Florence AZ	Layout for:	Well Casing Install
Total Depth:		Geologist:	M. Hensman & S. Kanev

Pipe Length		Depth BGS	Pipe Length		Depth BGS	Pipe Length		Depth BGS
		759.92			236.38			
20.04	23	779.96	29.11	46	265.49		69	
20.01	22	799.97	29.05	45	294.54		68	
20.05	21	820.02	29.10	44	323.64		67	
20.07	20		29.34	43			66	
20.04	19	840.09	29.28	42	352.98		65	
20.06	18	860.13	29.21	41	382.26		64	
20.04	17	880.19	29.14	40	411.47		63	
		900.23		20	440.61			
20.04	16	920.27	29.10	39	469.71		62	
20.04	15	940.31	29.09	38	498.80		61	
20.06	14	960.37	0.60	37	499.40		60	
20.05	13	980.42	20.02	36	519.42		59	
20.04	12		20.05	35			58	
20.05	11	1000.46	20.03	34	539.47		57	
20.05	10	1020.51	20.05	33	559.50	9.40	56	-10.45
20.02	9	1040.56	20.03	32	579.55	5.20	55	-1.05
		1060.58			599.58			4.15
20.02	8	1080.60	20.05	31	619.63	28.90	54	33.05
20.03	7	1100.63	20.05	30	639.68	29.02	53	62.07
20.05	6	1120.68	20.05	29	659.73	29.05	52	91.12
20.05	5	1140.73	20.04	28	679.77	29.02	51	120.14
20.03	4		20.04	27		29.01	50	
20.06	3	1160.76	20.02	26	699.81	29.04	49	149.15
20.05	2	1180.82	20.03	25	719.83	29.08	48	178.19
0.36	1	1200.87	20.06	24	739.86	29.11	47	207.27
0.00		1201.23	20.00	24	759.92	20.11	71	236.38

			SENSOR DETAILS	
Sensor Type	Sensor ID	Pipe #	Distance from Bottom of Sensor to Bottom of Pipe	Depth of Sensor (BGS)
ERT	10	2	5.90	1194.97
ERT	9	6	0.75	1119.93
ERT	8	9	15.90	1044.68
ERT	7	13	11.00	969.42
ERT	6	17	5.80	894.43
ERT	5	21	0.75	819.27
ERT	4	24	15.66	744.26
ERT	3	28	11.06	668.71
ERT	2	32	6.01	593.57
ERT	1	36	0.80	518.62
CS	4	41	27.57	383.90
CS	3	42	18.51	363.75
CS	2	43	9.84	343.14
CS	1	44	0.01	323.63
ACD	2	45	23.66	270.88
ACD	1	45	26.51	268.03

Pipe Number	Туре
1	SS End Cap
2 - 36	PVC SCH 80 Screen 0.020
37	SS: PVC/Fiberglass Transition
38-55	FRP
56	Fiberglass/For Landing!!!!

ESTIMATED ANNULAR MATERIAL RECORD

Project Name: 下た マイド Project #:: 129687-007 Date: 3/フ/ハヤ Well No.: ೧・あし Geologist: Sソタルト	
ANNULAR VOLUME CALCULATIONS	Dark 32 feet
<=(D²) 0.005454*L,]:] ith [L _{ct}] neter [d _{ct}]	feet feet inches
Screen Annular Volume (A _c): (D²-d _c ²) 0.005454 = $\frac{\mathcal{O}_{c}(\mathcal{O}_{c})}{\mathcal{O}_{c}(\mathcal{O}_{c})}$ Et ^g /Lin. Ft Casing Annular Volume (A _c): (D²-d _c ²) 0.005454 = $\frac{\mathcal{O}_{c}(\mathcal{O}_{c})}{\mathcal{O}_{c}(\mathcal{O}_{c})}$ Casing/Cam. Tube Annular Volume (A _{c+ct}): (D²-d _c ²-d _{ct} ²) 0.005454 = $\frac{\mathcal{O}_{c}(\mathcal{O}_{c})}{\mathcal{O}_{c}(\mathcal{O}_{c})}$	Ft%Lin. Ft
EQUATIONS 2,700 lbs. Silica Sand = 1 cubic yard = 27 cubic feet 1 Volume of bag (Ft³) = bag weight/100 2 Calculated depth = Previous Calculated depth - (v/A)	olbs. # Filter Pack
No. ✓ Weight Volume Total Vol. Calculated Tagged Comments of Bag of Bag¹(v) of Bags Depth² Depth (ft bls.) (ft²) (ft²) (ft²) (ft bls.)	
30 1179 1187 #8grave1	tremmie @1806.5 1@144
1 3500 30 90 1095 1097 #84 a 1 1	hemmie 6 1036
3000 30 150 1055× 1050 #84 cruel	
50 000 000 000 000 000 000 000 000 000	Aremie @956
"betwee from columne 1 de	
\$ \frac{2}{4}	Shick up > 9.4
. Ilb" borehale from 1050 - 1025, and	a ld" beserves starting at 1025-990. MERCH
K:\Templates\Field Forms\Well fnst & Testing Forms.xls	

900-850 -0 [3]

					7 remme	- Hrenie Boac	(3) XQA	10X &	889	ı	の 9 H	(B) 448	(0 + (0 d	8796	で は よ な よ は に は に に に に に に に に に に に に に	<u>タラ</u> (変)	(2,585	で を を を を を を を を を を を を を	1 532 (Fromde	. ``		ソファアルマンノノるたらー		18491	551 Dock 540	 	SSI Cock					
ATED ANNULAR MATERIAL RECORD (Continued)	Geologist: & / Lang		Comments			#X ordiel	# 8 S COSE	#80gk	#8 dow	# 8 order 1	井るらんで	あるとうとする。) / (%	# Sankil	10	80	ÒC	#8 & rave	#8 arausel	120001	4 86-hurl 1	Swale 1200-1100 15min	5wa 6 1200-1100 20-m	6 1100-1000		2 1000 T 000 1 J	5.mg 1008-,006 9 mms			- TANKET	The state of the s	
ATERIAL	27		Tagged	Depth	(ft bls)	-	くななし	-	367		80.3		734		685		-	593		539	513	(538	27. S	5/75	590	Sylo					
UNULAR M	129-189601		Calculated	Depth ²	(ft bis)	300 m	927	388	848	835	804	762	723	3 000	659	652	603		67		50%		1	ţ	1	··· · · · · · · · · · · · · · · · · ·						
MATED A	Project No.:	Date: \mathcal{Z} \mathcal{B}	Total Vol.'	of Bags	(ff?)	940	276	300	300	300	300	300	300	300	300	300	300	<i>3</i> 00	130 pt	660	080	l	•	((
ESTIM			Volume	of Bag ¹ (v)	(ft³)	30	30	30	30	00 0	8	30	30	R	Ŗ	30	30	8	0	30	R	į	(1)			21,516000				
(FUPTY	, Ole	Weight	of Bag	(lbs.)	3000	2000	3000	3000	3000	3000	3000	30CC	3000	3000	3000	3000	3000	3000	5000 Seec	3000	1		(1	\		Swal 15 21				
	Project Name: FC	No.:	` <u>`</u>			>	7	7	7	7	7		7	>	>	7	>	5	7	2	642) 	\	l	7		1						
	Projec	Well No.	Š			æ	0	2	******	d	i M	4	25	9		Æ	S	8	ર્લ	なり	rd F	Ì	1)	1)	I	Notes:				

0

TO THE TOTAL OF TH

				7	<u></u>	T		760		Ţ	13/10	\mathcal{Q}	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		1	1	1			T				
ESTIMATED ANNULAR MATERIAL RECORD (Continued)	ರಂಗ Geologist: ಖ.ಗುಣ್ವು೬	Tagged Comments	Depth (# his)	15was 800-700' tog 651' From Lee	140 Sweet 7001-6001 15-m2, 43	7 7	44 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2	00. C 41.10 + 210. 600' 30 m'n 5 do 1/2'	Sinah 700-600 (10 mins tag 4	10	add ibucket Pelalua	add 27 6045 #605and Transce	1 add 1 buckey of pelplug	‴										
NNULAR WA	124684-	Calcula	Depth ² (# hls)	(CIGNI)	510	495	100	3 (\\	5.88%	4800	やプ	<u> </u>	_							de la constanta de la constant			
IMATED AI	Project No.:	\ \ \	of Bags		720	735		750	11	C:122	4/5/2.0	2,695	1.05.2	3 /										
		Volume	of Bag ¹ (v)	١ (١	200	<i>i</i> 5		5	and the second	14	90	200	0.00											
Ш	FCI PIF	Weight	of Bag	(lbs.)	3000	1500		0051		100	202	いない	07 665	- 31										
	ame	Well No.: O			7	35		20 7			7 5	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1000	2,20							Notes:			

			de creta annano:					
Plant:	Begin Loading:	To Job:	Arrive Job:	Start Unload:	Finish Unload:	Leave	Job:	Return Plant:
加拉拉	ing with two error daily tood Vish	Heys been new a	elipirtuses sel Remedicilipoits	Athernias veneral	wel dement and and degregate da	y fine of	Fresh	Hazards:
Customer Code:	Customer Name:	COPPER INC	contain silica, uncounts of water		omer Job Number:		rder Code / Date:	01/18/
Project Code:	Project Name:	WELL broads a			ct P.O. Number:		der P.O. Number	
Ticket Date:	Delivery Address:	INT HIGHWAY		olonged contact v	DRUM/BATCH	Map I	group, right approx . The latest and the	Row/Column:
	PIN GATE GO	TO 4 WAY	STOP & GO	R, GO APPR	amil bobosimuo: X 1 MILE	Dispa	tcher:	
then pareids.	citre ti nomente	a proper modies					Number:	IDIA SERT
							444626)	29
Due On Job:	Slump: 6.00	Truck Number:	Driver Number:	Driver Name:	KENNETH	End Use:	BLDNG:	OTHER
LOAD CU QUANTITY Q	MULATIVE ORDER UANTITY QUANTI	ED MATERIAL CODE	dosensky yng n	PRODUCTION DESCRIPTION	ON	UOM	UNIT PRICE	AMOUNT
mabZe-QD) ber	1.99 inter	000123304	STIMPE II	TU SLURBY E	WITH DRIVE	Vp3	oreuse offe	confiles), co
		SHOTE BY SOUR	LEGACYU	MATERIALINO	is Con suc does			
		ni-unouge co ma	om is ususquan					
						JIN 1	8 118 12;	29101
						oa aoba		
IP), agulejo de		The Carle and Jennierin	a FUEL SUF	CHARGE ADS				
stimology axis		observation of the second		RCHARGE ADJ MENTAL FEE				
obsiding at the	his Airl Solution	ANS PER	S FREIDHT	NON TAXABL	praya y otros mi			
				INCHA I MAHOL	C_DUTE STUDIE			
Cash Check	# / Auth Code: Signa	NAME OF THE OWNER, OF	obenings show	log a hose oteros	Thin of my one	matte an	notiona	
Check	# / Auth Code: Signa	ture of Driver Receiving Cas	sh:	anejo en el tritută	Cash Received:	espirato	Total COD Orde Without Standby	Amount to Collect
Charge	iso de ser ingend				s pueden causar	os cuale	silicos. I	
Comments:	and arranged at the same	MOVEMBER OF THE	anie ob establi	equar grandes can	alida, reposal v ti	ratura c	en lempe	Company of
	h resgo in h a		dir iningdinap	WATER ADDED:	GAL	YARDS WHEN	IN DRUM: _ ADDED.	Seguridad
				oros y contacto o	moo otoemes Ev	any (In	binnosz	SIGNATURE
	ocjo do marerialo siratoria	artologides del ma se protección res		CURB LINE CRO	SSED AT OWNER'S	AGENT'S	REQUEST:	Primeros
oz d 5 minutos os a fondo con	a parte afociada j ur sus calos, lavel	e fluye kung en li none kumu an ca		□ LOAD WAS TES		odizuc s Zogala	oramin'i Ini se izi	SIGNATURE
Company assumes no reserms of sale and delivery this control after delivery, this controle. Buyers	sponsibility for damages ins y and accepts concrete as Company will not accept ar	materials where the custo side curb or property line. is. Due to important fact by responsibility for the finish all be deemed waived unle	Customer agrees to the ors which are out of our ned results. No credit for	may be hazardous to you	VARNING: Product may come safety and health. Pleas and to the material safety	ause skin and	l/or eye irritation.	CAUTION: Materi

X

CUSTOMER

PREV TRK:

68UNIVERSAL



3451 LeTourneau Gillette, WY 82718 307-682-5258

Cementing Ticket

No. 1719

21376

Date	Customer Order N	lo. Sect.	Twp.	Range Tr	ick Called Out	On Location	Job Began	Job Co	mpleted
02-09-18	Oustomer Order in		11112.	1 1	5:30 a.m.	7:00 a	1 -		:00 p.m.
Owner Flora	ance Copp	er Mine	Contractor	์ Hvdro R	esources	Ct	narge To Hvd i	o West	
Mailing Address			City			St	ate		ganggrangs nebungs seseniginé moneté situ sebbé biblié Péré
Well No. & Form	Observati	ion well 0-06		Place	copper m	ine	County Pi	nal	State AZ
Depth of Well	Depth of Job	P/New	Size	5.5	Size of Hole	12 1/4	/ Cement Left	Reguest	
1225	470	New Used	Weight		Amt. and Kind of Cement		in casing by	Necessity_	<u>0</u> _{fee}
Kind of Job	Obs	ervation We			Drillpipe	7/8 (Rotary Truck No	28	3983
Price Reference N	0	rtemarks	meeting						
Price of Job	4040		-		se and valv	'e			
Second Stage	1			clear tul	_				
	3825				type 2/5 ce	ement			
Pump Truck Mileag	765			thru mix	er				
P.U. Mileage			vn from 1 up in cell				***************************************		
Other Charges	5 800 00			o surface					
Total Charges	3,000.00	9000 0		ANK YOU	·····				
Cementer	Brvan Hamn	nond Lead \				6 100	division 6.8	6/1	148
	John Craha								
Helper	Oomi Orana					Lead	d Water	3v	
District	dana undar ausan	Gillette vision of the owner, or		State			av y		
							A	gent of contra	actor or operator
			Sales	Ticket for N	aterials Only				
QUANTITY SACK	S		BRAND AN		One Committee of the Co		PRICE		P OOO OO
16 12	•		<u>w subsi</u>				500		8,000.00
14		Transp	ortaton	of ceme	<u>nt</u>		150		1,800.00
**************************************									0.00
									0.00
			0 445	0044	01				0.00
			P.O. # 15	2014	······································				0.00
	***************************************			Guerra de la companya del companya de la companya del companya de la companya de					0.00
values de la composition della composition de la composition della composition della composition della composition della composition della composition della									
									0.00
72-00-90-00-00-00-00-00-00-00-00-00-00-00-									0.00
on the state of th					012-04-08-04-08-04-04-04-04-04-04-04-04-04-04-04-04-04-				0.00
								- HO 60	0.00
Plugs									0.00
		1		600	and the state of t		2.44		1,464.00
THE RESERVE THE PROPERTY OF THE PARTY OF THE	ipment# 983	1.5		000	Handling & Dur	mping	6,°°°	-20.000	0.00
	303 127	1.3			Mileage			4.	7,064.00
U4	t &u [Sub Total				.,007.00
					Discount				
					Sales Tax			and the second s	
Signature of operat	DI				Total				

APPENDIX E

Geophysical Logs


	Se	Southwest Exploration Services, LLC	StE	Cxplor	ation	ia 1176-776 1
A	borel	borehole geophysics & video services	ysics 8	k video s	ervices	
	COMPANY	FLORENCE COPPER	OPPER			
	WELL ID	0-06				
	FIELD	FLORENCE COPPER	OPPER			
	COUNTY	PINAL		STATE	ARIZONA	
	TYPE OF	TYPE OF LOGS: E-LOG	Ğ		OTHER SERVICES	7ICES
	MORE:	NAT.	NAT. GAMMA		TEMPERATURE	RE
	LOCATION				FLUID RESISTIVITY SONIC DEVIATION	TIVITY
	SEC	TWP	RGE			
PERMANENT DATUM			ELEVATION		K.B.	
LOG MEAS. FROM	GROUND LEVEL		ABOVE PERM. DATUM	M	D.F.	
DRILLING MEAS. FROM GROUND LEVEL	GROUND LEVE	T			G.L.	
DATE	2-6-18		TYPE FLUID IN HOLE	D IN HOLE	MUD	
RUN No	1 & 2		MUD WEIGHT	EIGHT	N/A	
TYPE LOG	E-LOG - N	E-LOG - NAT. GAMMA	VISCOSITY	ТҮ	N/A	
DEPTH-DRILLER	1220 FT.		LEVEL	TEMP	FULL FULL	
BTM I OGGED INTERVAL	1215 FT		IMAGE ORIENTEI	IMAGE ORIENTED TO:	N/A	
TOP LOGGED INTERVAL			SAMPLE INTERVAL	NTERVAL	0.2 FT.	
DRILLER / RIG#	HYDRO R	HYDRO RESOURCES	LOGGING TRUCK	[RUCK	TRUCK #900	
RECORDED BY / Logging Eng.	Eng. A. OLSON		TOOL STRING/SN	NG/SN	GEOVISTA E	GEOVISTA E-LOG SN 4035
WITNESSED BY	MAAYA- H&A	H&A	LOG TIME	LOG TIME:ON SITE/OFF SITE	ΓΕ 7:15 A.M.	
RUN BOREHOLE RECORD	ECORD		CASING RECORD	CORD		
NO. BIT I	FROM	ТО	SIZE	WGT. FF	FROM	ТО
1 ? IN>	SURFACE	40 FT.	14 IN.	STEEL SU	SURFACE	40 FT.
2 12 1/4 IN. ²	40 FT.	TOTAL DEPTH				
COMMENTS:			•			


Tool Summary:					
Date	2-6-18	Date	2-6-18	Date	2-6-18
Run No.	1	Run No.	2	Run No.	3
Tool Model	MSI COMBO TOOL	Tool Model	GEOVISTA E-LOG	Tool Model	MSI 60mm SONIC
Tool SN	5543	Tool SN	4035	Tool SN	5050
From	SURFACE	From	SURFACE	From	SURFACE
То	1220 FT.	То	1220 FT.	То	1220 FT.
Recorded By	A. OLSON	Recorded By	A. OLSON	Recorded By	A. OLSON
Truck No	900	Truck No	900	Truck No	900
Operation Check	2-5-18	Operation Check	2-5-18	Operation Check	2-5-18
Calibration Check	2-5-18	Calibration Check	2-5-18	Calibration Check	
Time Logged	8:15 A.M.	Time Logged	9:10 A.M.	Time Logged	9:55 A.M.
Date	2-6-18	Date		Date	^
Dato	2 6 18	Dato		Date	
Run No.	4	Run No.	5	Run No.	6
Tool Model	MSI DEVIATION	Tool Model		Tool Model	
Tool SN	6002	Tool SN		Tool SN	
From	SURFACE	From		From	
То	1220 FT.	То		То	
Recorded By	A. OLSON	Recorded By		Recorded By	
Truck No	900	Truck No		Truck No	
Operation Check	2-5-18	Operation Check		Operation Check	
Calibration Check	N/A	Calibration Check		Calibration Check	
Time Logged	11:00 A.M.	Time Logged		Time Logged	
Additional Comm	nents:				
Caliper Arms Use	d: 15 IN.	Calibi	ration Points: 8 l	N. & 23 IN.	
=	- 40 4000 0				·


E-Log Calibration Range: 10-1000 OHM-M Calibration Points: 10 & 1000 OHM-M
--


Disclaimer:


All interpretations of log data are opinions based on inferences from electrical or other measurements. We do not guarantee the accuracy or correctness of any interpretations or recommendations and shall not be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our employees or agents. These interpretations are also subject to our general terms and conditions set out in our current Service Invoice.














GeoVista E-Log Tool

Probe Top = Depth Ref.

Tool SN: 4035 & 4790



Bridle connects to wireline cablehead: Wireline armor is the B Electrode.

Four Conductor Probe Top

Bridle Electrode (N Electrode)

64" Normal Resistivity Electrode/Spontaneous Potential Electrode (M Electrode)

Probe Length = 2.3 m or 7.55 ft Bridle Length = 10.0 m or 32.81 ft

Probe Weight = 7.0 kg or 15.4 lbs

Can only be collected in fluid

Isolation Bridle - Not shown in diagram but is necessary for operation

Electrode Measuring Points (from bottom of probe)
Spontaneous Potential (SP): 0.65 m or 2.13 ft
16" Normal Resistivity (16" NRes): 0.50 m or 1.64 ft
64" Normal Resistivity (64" NRes): 1.10 m or 3.61 ft
Single Point Resistance (SPR): 0.25 m or 0.82 ft

Temperature Rating: 80 Deg C (176 Deg F)

Presure Rating: 200 bar (2900 psi)

16" Normal Resistivity Electrode (M Electrode)



MSI Gamma-Caliper-Temperature-Fluid Resistivity

Probe Top = Depth Ref.

Single Conductor MSI Probe Top

Probe Length = 2.59 m or 8.5 ft Probe Weight = 6.80 kg or 15.0 lbs

Natural Gamma and Caliper can only be collected logging up hole.

Fluid Temperature/Resistivity can only be collected logging down hole.

Temperature Rating: 70 Deg C (158 Deg F)

Presure Rating: 200 bar (2900 psi)

Natural Gamma Ray = 0.76 m (29.75 in)

NOTE: Lengths on a particular tool may vary from those listed on this document due to probe sizes and styles utilized

3-Arm Caliper = 1.44 m (56.75 in)

Distance from tool top: 2.20 m (86.5 in)

Available Arm Sizes: 3", 9", and 15"

1.375" or 34.9 mm Diameter



Company FLORENCE COPPER

Well

O-06

Field

FLORENCE COPPER

County State PINAL ARIZONA

Final

E-Log Summary


Kut	Sei	Southwest Exploration Services, LLC	st E	C	ation	
	bore	borehole geophysics & video services	ysics 8	દ્ર video s	ervices	
	COMPANY	FLORENCE COPPER	OPPER			
	WELL ID	O-06				
	FIELD	FLORENCE COPPER	OPPER			
	COUNTY	PINAL		STATE	ARIZONA	
	TYPE OF LOGS:		GAMMA - CALIPER	LIPER	OTHER SERVICES	/ICES
	MORE:	TEMI	TEMP. / FLUID RES.	D RES.	SONIC	
	LOCATION				DEVIATION	
	SEC	TWP	RGE			
PERMANENT DATUM			ELEVATION		K.B.	
LOG MEAS. FROM	GROUND LEVEL		ABOVE PERM. DATUM	JM	D.F.	
DRILLING MEAS. FROM GROUND LEVEL	GROUND LEVEI				G.L.	
DATE	2-6-18		TYPE FLUID IN HOLE	D IN HOLE	MUD	
RUN No	1		MUD WEIGHT	EIGHT	N/A	
TYPE LOG	GAMMA -	GAMMA - CALIPER - TFR	VISCOSITY	ITY	N/A	
DEPTH-DRILLER	1220 FT.		LEVEL		FULL	
DEPTH-LOGGER			MAX. REC. TEMP.	TEMP.	26.48 DEG. C	
TOP LOGGED INTERVAL	SURFACE		SAMPLE INTERVAL	SAMPLE INTERVAL	0.2 FT.	
DRILLER / RIG#	HYDRO RI	HYDRO RESOURCES	LOGGING TRUCK	TRUCK	TRUCK #900	
RECORDED BY / Logging Eng.	Eng. A. OLSON		TOOL STRING/SN	NG/SN	MSI COMBO	MSI COMBO TOOL SN 5543
WITNESSED BY	MAAYA- H&A	I&A	LOG TIME	LOG TIME:ON SITE/OFF SITE	TE 7:15 A.M.	
RUN BOREHOLE RECORD	CORD		CASING RECORD	CORD		
NO. BIT FF	FROM	ТО	SIZE	WGT. FI	FROM	ТО
1 ? IN. St	SURFACE	40 FT.	14 IN.	STEEL SU	SURFACE	40 FT.
2 12 1/4 IN. 40 3	40 FT.	TOTAL DEPTH				
COMMENTS:						


Tool Summary:					
Date	2-6-18	Date	2-6-18	Date	2-6-18
Run No.	1	Run No.	2	Run No.	3
Tool Model	MSI COMBO TOOL	Tool Model	GEOVISTA E-LOG	Tool Model	MSI 60mm SONIC
Tool SN	5543	Tool SN	4035	Tool SN	5050
From	SURFACE	From	SURFACE	From	SURFACE
То	1220 FT.	То	1220 FT.	То	1220 FT.
Recorded By	A. OLSON	Recorded By	A. OLSON	Recorded By	A. OLSON
Truck No	900	Truck No	900	Truck No	900
Operation Check	2-5-18	Operation Check	2-5-18	Operation Check	2-5-18
Calibration Check	2-5-18	Calibration Check	2-5-18	Calibration Check	
Time Logged	8:15 A.M.	Time Logged	9:10 A.M.	Time Logged	9:55 A.M.
Date	2-6-18	Date		Date	^
Dato	2 6 18	Dato		Date	
Run No.	4	Run No.	5	Run No.	6
Tool Model	MSI DEVIATION	Tool Model		Tool Model	
Tool SN	6002	Tool SN		Tool SN	
From	SURFACE	From		From	
То	1220 FT.	То		То	
Recorded By	A. OLSON	Recorded By		Recorded By	
Truck No	900	Truck No		Truck No	
Operation Check	2-5-18	Operation Check		Operation Check	
Calibration Check	N/A	Calibration Check		Calibration Check	
Time Logged	11:00 A.M.	Time Logged		Time Logged	
Additional Comm	nents:				
Caliper Arms Use	d: 15 IN.	Calibi	ration Points: 8 l	N. & 23 IN.	
=	- 40 4000 0				·


|--|


Disclaimer:


All interpretations of log data are opinions based on inferences from electrical or other measurements. We do not guarantee the accuracy or correctness of any interpretations or recommendations and shall not be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our employees or agents. These interpretations are also subject to our general terms and conditions set out in our current Service Invoice.














Probe Top = Depth Ref. **Single Conductor MSI Probe Top** Probe Length = 2.59 m or 8.5 ft Probe Weight = 6.80 kg or 15.0 lbs Natural Gamma and Caliper can only be collected logging up hole. Fluid Temperature/Resistivity can only be collected logging down hole. Temperature Rating: 70 Deg C (158 Deg F) Presure Rating: 200 bar (2900 psi) **Natural Gamma Ray = 0.76 m (29.75 in)** *NOTE: Lengths on a particular tool may vary from those listed on this document due to probe sizes and styles utilized* 3-Arm Caliper = 1.44 m (56.75 in) Distance from tool top: 2.20 m (86.5 in) Available Arm Sizes: 3", 9", and 15" TFR (Temperature/Fluid Resistivity) = 0.39 m (15.5 in) 1.375" or 34.9 mm Diameter



Company FLORENCE COPPER

Well O-06

Field FLORENCE COPPER

County PINAL State ARIZONA

Final

GCT Summary

	Se	Southwest Exploration Services, LLC	StE	Cxplor	ation	A 1767A1
A	borel	borehole geophysics & video services	ysics 8	₹ video se	rvices	
	COMPANY	FLORENCE COPPER	OPPER			
	WELL ID	O-06				
	FIELD	FLORENCE COPPER	OPPER			
	COUNTY	PINAL		STATE	ARIZONA	
	TYPE OF LOGS:		60mm SONIC		OTHER SERVICES	TCES
	MORE:	GAMI	GAMMA - CALIPER	LIPER	E-LOG TEMPERATURE	RE
	LOCATION				FLUID RESISTIVITY DEVIATION	TIVITY
	SEC	TWP	RGE			
PERMANENT DATUM			ELEVATION		K.B.	
LOG MEAS. FROM	GROUND LEVEL		ABOVE PERM. DATUM	M	D.F.	
DRILLING MEAS. FROM GROUND LEVEL	GROUND LEVE				G.L.	
DATE	2-6-18		TYPE FLUID IN HOLE	D IN HOLE	MUD	
RUN No	1 & 3		MUD WEIGHT	EIGHT	N/A	
TYPE LOG	SONIC - G	SONIC - GAMMA - CALIPER	VISCOSITY	ITY	N/A	
DEPTH-LOGGER	1220 FT.		MAX. REC. TEMP.	TEMP	26.48 DEG. C	
BTM LOGGED INTERVAL			IMAGE OR	IMAGE ORIENTED TO:	N/A	
TOP LOGGED INTERVAL	SURFACE		SAMPLE INTERVAL	NTERVAL	0.25 FT.	
DRILLER / RIG#	₩	HYDRO RESOURCES	LOGGING TRUCK	TRUCK	TRUCK #900	
RECORDED BY / Logging Eng.	Eng. A. OLSON		TOOL STRING/SN	NG/SN	MSI 60mm SONIC SN 5050	NIC SN 5050
WITNESSED BY	MAAYA- H&A	∃&A	LOG TIME	LOG TIME:ON SITE/OFF SITE	E 7:15 A.M.	
RUN BOREHOLE RECORD	CORD		CASING RECORD	CORD		
NO. BIT F	FROM	ТО	SIZE	WGT. FR	FROM	ТО
1 ? IN. S	SURFACE	40 FT.	14 IN.	STEEL SU	SURFACE	40 FT.
2 12 1/4 IN. 4	40 FT.	TOTAL DEPTH				
COMMENTS:						
-						


Tool Summary:	2-6-18	Date	2-6-18	Date	2-6-18
Run No.	1	Run No.	2	Run No.	3
Tool Model	MSI COMBO TOOL	Tool Model	GEOVISTA E-LOG		MSI 60mm SONIC
Tool SN	5543	Tool SN	4035	Tool SN	5050
From	SURFACE	From	SURFACE	From	SURFACE
To	1220 FT.	To	1220 FT.	To	1220 FT.
Recorded By	A. OLSON	Recorded By	A. OLSON	Recorded By	A. OLSON
Truck No	900	Truck No	900	Truck No	900
Operation Check		Operation Check	000	Operation Check	7 7 7
Calibration Check		Calibration Check		Calibration Check	
Time Logged		Time Logged		Time Logged	9:55 A.M.
Date	2-6-18	Date		Date	
Run No.	4	Run No.	5	Run No.	6
Tool Model	MSI DEVIATION	Tool Model		Tool Model	
Tool SN	6002	Tool SN		Tool SN	
From	SURFACE	From		From	
То	1220 FT.	To		To	
Recorded By	A. OLSON	Recorded By		Recorded By	
Truck No	900	Truck No		Truck No	
Operation Check	2-5-18	Operation Check		Operation Check	
Calibration Check		Calibration Check		Calibration Check	
Time Logged		Time Logged		Time Logged	
Additional Comr		99		33	
, wantional collin					
Caliper Arms Use	ط۰ 15 INI	Calib	ration Points: 8	INI & 23 INI	


E-Log Calibration Range:	10-1000 OHM-M	Calibration Points:	10 & 1000 OHM-M


Disclaimer:


All interpretations of log data are opinions based on inferences from electrical or other measurements. We do not guarantee the accuracy or correctness of any interpretations or recommendations and shall not be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our employees or agents. These interpretations are also subject to our general terms and conditions set out in our current Service Invoice.


Nat. Gamma		Depth		RX1 - VDL			RX2 - VDL	
0 API	400	1in:20ft	100	uSec	1000	100	uSec	1000
3-Arm Caliper			R	K1 - Travel Tim	ne	F	RX2 - Travel Tim	ne
0 Inches	40		100	uSec	1000	100	uSec	1000
Delta T								
240 uSec/ft	40							
*		0.0						
}								
		20.0						
		20.0						
								瑪斯茲
	>		5	Hi Zing	Contract of		Sun m	disting
} !,	_	40 -			MATERIAL PROPERTY.			//
		40.0			77.14.884			
**					Willy S			
\$ 1			Date of		11111111			
					mm.			
E		60.0			KKKY			
K III					HSPAT			
\$					BBB			
2		80.0			HHM			
					HIIII			
B			Physical Co					
					HIRW			
		100.0		NAME OF				
			图面积值		1177			
			A ball		1 (((18)	Jan 1965		
		120.0	사람들.		ΠM	神器)		
			1.17.191		111111			
					11833			
3 12					Halli			
§		140.0			11/3/4			
\$ 1		170.0			Maria			
8			그런 것		THE W			
\$ 1					-11100E			












MSI 60 mm 2 RX Full Waveform Sonic Tool

Probe Top = Depth Ref.

Tool SN: 5001, 5050 & 6003



MSI Gamma-Caliper-Temperature-Fluid Resistivity

Probe Top = Depth Ref.

Single Conductor MSI Probe Top

Probe Length = 2.59 m or 8.5 ft Probe Weight = 6.80 kg or 15.0 lbs

Natural Gamma and Caliper can only be collected logging up hole.

Fluid Temperature/Resistivity can only be collected logging down hole.

Temperature Rating: 70 Deg C (158 Deg F)

Presure Rating: 200 bar (2900 psi)

- Natural Gamma Ray = 0.76 m (29.75 in)

NOTE: Lengths on a particular tool may vary from those listed on this document due to probe sizes and styles utilized

3-Arm Caliper = 1.44 m (56.75 in)

Distance from tool top: 2.20 m (86.5 in)

Available Arm Sizes: 3", 9", and 15"

1.375" or 34.9 mm Diameter



Company FLORENCE COPPER

Well

O-06

Field

FLORENCE COPPER

County State PINAL ARIZONA

Final

Sonic Summary

	Se Se	Southwest Exploration Services, LLC	St E	xplor	ation	
	bore	borehole geophysics & video services	ysics 8	દ્ર video s	ervices	Í
	COMPANY	FLORENCE COPPER	OPPER			
	WELL ID	O-06				
	FIELD	FLORENCE COPPER	OPPER			
	COUNTY	PINAL		STATE	ARIZONA	
	TYPE OF	TYPE OF LOGS: 3-ARM CALIPER	M CALI	PER	OTHER SERVICES	TCES
	MORE:	W / V	W / VOLUME CALC.	CALC.	SONIC	
	LOCATION				DEVIATION NAT. GAMMA TEMPERATURE	A RE
	SEC	TWP	RGE		FEOID NESISTIVIT	114111
PERMANENT DATUM			ELEVATION		K.B.	
LOG MEAS. FROM	GROUND LEVEL		ABOVE PERM. DATUM	ЛМ	D.F.	
DRILLING MEAS. FROM GROUND LEVEL	GROUND LEVE	L			G.L.	
DATE	2-6-18		TYPE FLUID IN HOLE	D IN HOLE	MUD	
RUN No	1		MUD WEIGHT	EIGHT	N/A	
TYPE LOG	VOLUME	VOLUME CALCULATION	VISCOSITY	ТҮ	N/A	
DEPTH-DRILLER	1220 FT.		LEVEL	TEMP	FULL FULL	
BTM LOGGED INTERVAL			IMAGE ORIENTEI	IMAGE ORIENTED TO:	N/A	
TOP LOGGED INTERVAL			SAMPLE INTERVAL	NTERVAL	0.2 FT.	
DRILLER / RIG#	HYDRO R	HYDRO RESOURCES	LOGGING TRUCK	TRUCK	TRUCK #900	
RECORDED BY / Logging Eng.	Eng. A. OLSON		TOOL STRING/SN	NG/SN	MSI COMBO	MSI COMBO TOOL SN 5543
WITNESSED BY	MAAYA- H&A	H&A	LOG TIME	LOG TIME:ON SITE/OFF SITE	TE 7:15 A.M.	
RUN BOREHOLE RECORD	ECORD	-	CASING RECORD	CORD		
NO. BIT I	FROM	ТО	SIZE	WGT. FF	FROM	ТО
1 ? IN.	SURFACE	40 FT.	14 IN.	STEEL SU	SURFACE	40 FT.
2 12 1/4 IN. 4	40 FT.	TOTAL DEPTH				
COMMENTS:						


Tool Summary:			·		
Date	2-6-18	Date	2-6-18	Date	2-6-18
Run No.	1	Run No.	2	Run No.	3
Tool Model	MSI COMBO TOOL	Tool Model	GEOVISTA E-LOG	Tool Model	MSI 60mm SONIC
Tool SN	5543	Tool SN	4035	Tool SN	5050
From	SURFACE	From	SURFACE	From	SURFACE
То	1220 FT.	То	1220 FT.	То	1220 FT.
Recorded By	A. OLSON	Recorded By	A. OLSON	Recorded By	A. OLSON
Truck No	900	Truck No	900	Truck No	900
Operation Check	2-5-18	Operation Check	2-5-18	Operation Check	2-5-18
Calibration Check	2-5-18	Calibration Check	2-5-18	Calibration Check	N/A
Time Logged	8:15 A.M.	Time Logged	9:10 A.M.	Time Logged	9:55 A.M.
Date	2-6-18	Date		Date	
- 4.10					
Run No.	4	Run No.	5	Run No.	6
Tool Model Tool SN	MSI DEVIATION 6002	Tool Model Tool SN		Tool Model Tool SN	
From	SURFACE	From		From	
To	1220 FT.	To		To	
Recorded By	A. OLSON	Recorded By		Recorded By	
Truck No	900	Truck No		Truck No	
Operation Check					
Calibration Check	1	Operation Check Calibration Check		Operation Check Calibration Check	
Time Logged		Time Logged		Time Logged	
Additional Comr		Time Logged		Tille Logged	
		Calib	ration Points: 8	INI 8 22 INI	
Caliper Arms Use	a: ID IIV.	Calibr	aliun Punts: 8	IIN. OX ZO IIN.	


E-Log Calibration Range:	10-1000 OHM-M	Calibration Points:	10 & 1000 OHM-M


Disclaimer:


All interpretations of log data are opinions based on inferences from electrical or other measurements. We do not guarantee the accuracy or correctness of any interpretations or recommendations and shall not be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our employees or agents. These interpretations are also subject to our general terms and conditions set out in our current Service Invoice.


Total Volume	Depth	3-Arm Caliper	Cumulated Volume (cu.yd)
0 cu.yd 54.99	1in:20ft	0 Inches 40	
3-D View			Paged on E.E.I. OD Casin
-0°			Based on 5.5" OD Casing
	0.0		
	20.0		54.58
	40.0		53.94
	60.0		52.91
	80.0		51.75
	100.0		50.41
	120.0		49.07
	140.0		47.63
	160.0		46.33











MSI Gamma-Caliper-Temperature-Fluid Resistivity Probe Top = Depth Ref.

A	Single Conductor MSI Probe Top
	Probe Length = 2.59 m or 8.5 ft Probe Weight = 6.80 kg or 15.0 lbs
	Frobe Weight - 0.00 kg of 13.0 lbs
	Natural Gamma and Caliper can only be collected logging up hole.
	Fluid Temperature/Resistivity can only be collected logging down hole.
	Temperature Rating: 70 Deg C (158 Deg F)
	Presure Rating: 200 bar (2900 psi)
_ _	— Natural Gamma Ray = 0.76 m (29.75 in)
	NOTE: Lengths on a particular tool may vary from those listed on this document due to probe sizes and styles utilized
11-	- 3-Arm Caliper = 1.44 m (56.75 in)
	Distance from tool top: 2.20 m (86.5 in)
	Available Arm Sizes: 3", 9", and 15"
	TFR (Temperature/Fluid Resistivity) = 0.39 m (15.5 in)
1.375" or 34.9 m	nm Diameter
	Company FLORENCE COPPER



Well O-06

Field FLORENCE COPPER

County PINAL State ARIZONA

Final

Caliper w / Volume Calculation Summary



Wellbore DRIFT Interpretation

PREPARED ESPECIALLY FOR FLORENCE COPPER O-06

Tuesday - February 6, 2018



This Wellbore Interpretation Package represents our best efforts to provide a correct interpretation. Nevertheless, since all interpretations are opinions based on inferences from electrical or other types of measurements, we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by Customer resulting from any interpretation made by this document. We do not warrant or guarantee the accuracy of the data, specifically including (but without limitations) the accuracy of data transmitted by electronic process, and we will not be responsible for accidental or intentional interception of such data by third parties. Our employees are not empowered to change or otherwise modify the attached interpretation. Furthermore, along with Eagle Pro Software we do not warrant or quarantee the accuracy of the programming techniques employed to produce this document. By accepting this Interpretation Package, the Customer agrees to the foregoing, and to our General Terms and Conditions.

WELLBORE DRIFT INTERPRETATION

Southwest Exploration Services, LLC

Company:	FLO	PRENCE COPI	PER	Well Owner:					
County:	PINAL		State:	Arizona		Country:		United States	
Well Number:	O-06		Survey Date:	Tuesday - February 6, 20	18	Magnetic Declination	n: De	clination Correctio	n Not Used
Field:	FLORENCE	COPPER		Drift Calculation Methodol	logy:	Bala	inced Tangen	ntial Method	
Location:									
Remarks:									
Witness:	Vehicle No.:	900	Invoice No.:	Operator:	A. OLSON	Well Depth:	1220 Feet	Casing size:	12.25 Inches

Long.:

Sec.:

Twp.:

Rge.:

M	EASURED DA	TA			DA	TA COMPUTA	TIONS		
DEPTHS, feet	INCLINATIONS, degrees	AZIMUTHS, degrees	TVD, feet	T. LATITUDE, feet	T. LONGITUDE, feet	DOGLEG SEV., degrees per 20 Feet	DOGLEG SEV., degrees per 100 feet	DRIFT DIST., feet	DRIFT BGR. degrees
0	0.59	032.41	0.00						
20	0.57	042.64	19.99	0.160	0.123	1.00	0.71	0.20' (2.40")	037.40
40	0.29	203.48	39.98	0.187	0.170	0.41	7.83	0.25' (3.00")	042.30
60	0.40	180.87	59.97	0.071	0.149	0.96	1.56	0.16' (1.92")	064.60
80	0.33	186.69	79.96	-0.056	0.141	0.84	0.40	0.15' (1.80")	111.60
100	0.09	207.88	99.96	-0.127	0.127	0.42	1.46	0.18' (2.16")	135.00
120	0.13	224.10	119.95	-0.157	0.104	0.13	1.12	0.19' (2.28")	146.50
140	0.31	155.80	139.94	-0.223	0.110	0.43	4.46	0.25' (3.00")	153.60
160	0.20	212.32	159.93	-0.302	0.114	0.83	3.76	0.32' (3.84")	159.40
180	0.15	168.79	179.92	-0.357	0.100	0.95	2.94	0.37' (4.44")	164.30
200	0.01	259.11	199.91	-0.383	0.103	0.37	5.63	0.40' (4.80")	164.90
220	0.19	174.60	219.90	-0.416	0.104	1.00	5.34	0.43' (5.16")	165.90
240	0.15	160.22	239.89	-0.474	0.116	1.00	0.99	0.49' (5.88'')	166.20
260	0.14	155.02	259.88	-0.521	0.135	0.34	0.36	0.54' (6.48'')	165.40
280	0.12	183.62	279.87	-0.564	0.144	0.93	1.96	0.58' (6.96")	165.70
300	0.24	175.31	299.86	-0.627	0.146	0.78	0.58	0.64' (7.68'')	166.90
320	0.16	197.08	319.85	-0.695	0.141	0.53	1.50	0.71' (8.52")	168.50
340	0.15	188.84	339.84	-0.748	0.129	0.00	0.57	0.76' (9.12'')	170.20

Page No. 1 True Vertical Depth: 1219.41' Final Drift Distance: 7.42' (89.04") Final Drift Bearing: 160.50°

Lat.:

Tool:

Compass - 6002

Note: Magnetic Declination is not used because it is not a factor in the calculation of well drift or alignment. Magnetic Declination is only important if attempting to hit a target or miss another well and then it is included in the calculations.

WELLBORE DRIFT INTERPRETATION Southwest Exploration Services, LLC (480) 926-4558

O-06

M	EASURED DA	TA			DA	TA COMPUTA	TIONS		
DEPTHS, feet	INCLINATIONS, degrees	AZIMUTHS, degrees	TVD, feet	T. LATITUDE, feet	T. LONGITUDE, feet	DOGLEG SEV., degrees per 20 Feet	DOGLEG SEV., degrees per 100 feet	DRIFT DIST., feet	DRIFT BRG. degrees
360	0.23°	190.52°	359.83	-0.813	0.118	0.56	0.12	0.82' (9.84")	171.80
380	0.22°	189.58°	379.82	-0.890	0.104	0.73	0.07	0.90' (10.80'')	173.30
400	0.35°	183.32°	399.81	-0.989	0.094	0.88	0.43	0.99' (11.88'')	174.60
420	0.32°	175.18°	419.80	-1.106	0.095	0.20	0.56	1.11' (13.32")	175.10
440	0.33°	194.40°	439.79	-1.217	0.085	0.97	1.33	1.22' (14.64'')	176.00
460	0.35°	169.70°	459.78	-1.333	0.082	0.96	1.70	1.34' (16.08'')	176.50
480	0.17°	172.26°	479.77	-1.423	0.097	0.12	0.18	1.43' (17.16'')	176.10
500	0.31°	188.36°	499.76	-1.506	0.093	0.81	1.11	1.51' (18.12'')	176.50
520	0.37°	175.95°	519.75	-1.624	0.090	0.59	0.86	1.63' (19.56")	176.80
540	0.33°	165.53°	539.74	-1.744	0.109	0.73	0.72	1.75' (21.00")	176.40
560	0.28°	184.96°	559.73	-1.848	0.119	0.28	1.34	1.85' (22.20'')	176.30
580	0.36°	177.23°	579.72	-1.959	0.118	0.77	0.54	1.96' (23.52'')	176.60
600	0.53°	178.40°	599.71	-2.114	0.124	0.49	0.08	2.12' (25.44'')	176.70
620	0.40°	161.61°	619.70	-2.273	0.149	0.69	1.16	2.28' (27.36")	176.30
640	0.30°	154.61°	639.69	-2.387	0.193	0.13	0.48	2.39' (28.68")	175.40
660	0.21°	182.42°	659.68	-2.471	0.214	0.83	1.91	2.48' (29.76")	175.10
680	0.36°	171.30°	679.67	-2.570	0.222	0.80	0.77	2.58' (30.96")	175.10
700	0.36°	178.13°	699.66	-2.695	0.234	0.25	0.47	2.71' (32.52")	175.00
720	0.38°	165.70°	719.65	-2.822	0.252	0.54	0.86	2.83' (33.96")	174.90
740	0.48°	171.11°	739.64	-2.969	0.281	0.24	0.37	2.98' (35.76")	174.60
760	0.49°	154.35°	759.63	-3.129	0.331	0.94	1.16	3.15' (37.80'')	174.00
780	0.47°	158.99°	779.62	-3.283	0.397	0.65	0.32	3.31' (39.72")	173.10
800	0.49°	162.25°	799.61	-3.441	0.452	0.97	0.23	3.47' (41.64'')	172.50
820	0.36°	136.19°	819.60	-3.568	0.522	0.06	1.79	3.61' (43.32'')	171.70
840	0.39°	153.03°	839.59	-3.674	0.596	0.29	1.16	3.72' (44.64")	170.80
860	0.43°	142.01°	859.58	-3.794	0.673	0.57	0.76	3.85' (46.20")	169.90
880	0.53°	155.47°	879.57	-3.937	0.758	0.47	0.93	4.01' (48.12")	169.10
900	0.64°	164.81°	899.56	-4.129	0.826	0.42	0.65	4.21' (50.52")	168.70
920	0.41°	146.13°	919.55	-4.296	0.895	0.69	1.29	4.39' (52.68")	168.20
940	0.53°	152.54°	939.54	-4.437	0.978	0.04	0.44	4.54' (54.48")	167.60
960	0.74°	139.15°	959.53	-4.617	1.105	0.30	0.93	4.75' (57.00")	166.50
980	0.30°	171.69°	979.52	-4.767	1.197	0.98	2.23	4.91' (58.92")	165.90
1,000	0.37°	144.94°	999.52	-4.872	1.242	0.95	1.84	5.03' (60.36")	165.70


Page No. 2 True Vertical Depth: 1219.41' **Final Drift Distance:** <u>7.42'</u> (89.04") Final Drift Bearing: 160.50°

WELLBORE DRIFT INTERPRETATION Southwest Exploration Services, LLC (480) 926-4558

O-06

M	EASURED DAT	ГА			DA	TA COMPUTA	TIONS		
DEPTHS, feet	INCLINATIONS, degrees	AZIMUTHS, degrees	TVD, feet	T. LATITUDE, feet	T. LONGITUDE, feet	DOGLEG SEV., degrees per 20 Feet	DOGLEG SEV., degrees per 100 feet	DRIFT DIST., feet	DRIFT BRG. degrees
1,020	0.42°	143.46°	1,019.51	-4.984	1.323	0.96	0.10	5.16' (61.92'')	165.10
1,040	0.64°	160.25°	1,039.50	-5.148	1.404	0.46	1.16	5.34' (64.08'')	164.70
1,060	0.53°	119.15°	1,059.49	-5.298	1.523	0.25	2.79	5.51' (66.12")	164.00
1,080	0.64°	148.55°	1,079.48	-5.438	1.662	0.92	2.02	5.69' (68.28")	163.00
1,100	0.82°	158.53°	1,099.47	-5.666	1.773	0.09	0.69	5.94' (71.28")	162.60
1,120	0.68°	141.47°	1,119.46	-5.892	1.899	0.16	1.18	6.19' (74.28")	162.10
1,140	0.39°	136.79°	1,139.45	-6.034	2.020	0.98	0.32	6.36' (76.32")	161.50
1,160	0.76°	167.60°	1,159.44	-6.213	2.095	0.54	2.11	6.56' (78.72")	161.40
1,180	0.95°	150.25°	1,179.43	-6.486	2.206	0.80	1.20	6.85' (82.20")	161.20
1,200	0.76°	150.65°	1,199.42	-6.746	2.353	0.66	0.03	7.14' (85.68")	160.80
1,220	0.83°	155.73°	1,219.41	-6.994	2.478	0.94	0.35	7.42' (89.04")	160.50


Page No. 3 True Vertical Depth: 1219.41' **Final Drift Distance:** <u>7.42'</u> (89.04") Final Drift Bearing: 160.50°



3D PROJECTION VIEW - O-06

FLORENCE COPPER

251.0




Date of Survey: Tuesday - February 6, 2018

Balanced Tangential Calculation Method

Southwest Exploration Services, LLC (480) 926-4558


POLAR VIEW - O-06 FLORENCE COPPER




Date of Survey: Tuesday - February 6, 2018

Balanced Tangential Calculation Method

Southwest Exploration Services, LLC (480) 926-4558





boreh	NICES	ysics &	C video	serv	ices	
OMPANY	FLORENCE C	OPPER	, Alder	00	1000	
ELL ID	0-06	CLIEN				
ELD	FLORENCE C	OPPER				
YTNUC	PINAL		STA		\RIZONA	
YPE OF I	OGS: GAM	MA - CA	LIPER		OTHER SER	VICES
ORE:	TEMI	./FLUII	D RES.		SONIC 4 PI DENSIT	Y
CATION					DUAL DENS	ПҮ
Ω	TWP	RGE				
		ELEVATION			K.B.	
OUND LEVEL		PERM. DATU	Ā		D.F.	
OUND LEVEL					3.L.	
3-22-18		TYPE FLUI	D IN HOLE		FORMATION	WATER
1		MUD W	EIGHT		N/A	
GAMMA - 0	CALIPER - TFR	VISCOS	ITY		N/A	
1200 FT.		LEVEL			~228 FT	
1190 FT.		MAX. REC.	TEMP.	1.3	34.47 DEG. C	
1190 FT.		IMAGE OR	ENTED TO:		N/A	
SURFACE		SAMPLE IN	TERVAL).2 FT	
₩	SOURCES	LOGGING 1	RUCK		TRUCK #750	
-	NES / A. OLSON	TOOL STRI	NG/SN		MSI COMBO	MSI COMBO TOOL SN 5543
-	I&A	LOG TIME:	ON SITE/OFF		11:00 A.M.	
ZD		CASING RE	CORD			
M	TO	SIZE	WGT.	FROM		TO
FACE	40 FT.	14"	STEEL	SURFA	CE	500 FT.
	500 FT.	5"	FG	SURFA	CE	500 FT.
T.	TOTAL DEPTH	5"	PVC	500 FT.		TOTAL DEPTH
	COMPANY WELL ID FIELD COUNTY TYPE OF 1 MORE: LOCATION SEC PERMANENT DATUM LOG MEAS. FROM GROUND LEVEL DATE DATE TYPELOG DEPTH-DRILLER DEPTH-LOGGED INTERVAL DEPTH-LOGGED INTE		BOREHOLE GEOPHYSICS MPANY FLORENCE COPPER ELL ID O-06 ELD FLORENCE COPPER OUNTY PINAL TWP FLORENCE COPPER OUND LEVEL ABOVE PERM. D./ SUND LEVEL ABOVE PERM. D./ SUND LEVEL ABOVE PERM. D./ SUND LEVEL TYPE FI 1190 FT. NACE SURFACE SUR	BOREHOLE GEOPHYSICS MPANY FLORENCE COPPER ELL ID O-06 ELD FLORENCE COPPER OUNTY PINAL TWP FLORENCE COPPER OUND LEVEL ABOVE PERM. D./ SUND LEVEL ABOVE PERM. D./ SUND LEVEL ABOVE PERM. D./ SUND LEVEL TYPE FI 1190 FT. NACE SURFACE SUR	DORE: TWP RELUID NOOLEYEL ABOVE PERM. DATUM OUND LEVEL BATTON OUND LEVEL ABOVE PERM. DATUM OUND LEVEL ABOVE PERM. DATUM OUND LEVEL BATTON OUND LEVEL ABOVE PERM. DATUM OUND LEVEL BATTON OUND LEVEL ABOVE PERM. DATUM OUND LEVEL BATTON OUND LEVEL BATTON	DORE: TWP RELUID NOOLEYEL ABOVE PERM. DATUM OUND LEVEL BATTON OUND LEVEL ABOVE PERM. DATUM OUND LEVEL ABOVE PERM. DATUM OUND LEVEL BATTON OUND LEVEL ABOVE PERM. DATUM OUND LEVEL BATTON OUND LEVEL ABOVE PERM. DATUM OUND LEVEL BATTON OUND LEVEL BATTON


Tool Summary:					
Date	3-22-18	Date	3-22-18	Date	3-22-18
Run No.	1	Run No.	2	Run No.	3
Tool Model	MSI COMBO TOOL	Tool Model	ALT 4 RX SONIC	Tool Model	COMPROBE 4 PI
Tool SN	5543	Tool SN	4572	Tool SN	6009
From	SURFACE	From	220 FT.	From	SURFACE
То	1190 FT.	То	1190 FT.	То	1190 FT.
Recorded By	A. OLSON	Recorded By	A. OLSON	Recorded By	A. OLSON
Truck No	750	Truck No	750	Truck No	750
Operation Check	3-22-18	Operation Check	3-22-18	Operation Check	3-22-18
Calibration Check		Calibration Check	N/A	Calibration Check	N/A
		Calibration Check Time Logged	N/A 12:00 P.M.	Calibration Check Time Logged	N/A 12:45 P.M.
Calibration Check	3-22-18				
Calibration Check Time Logged	3-22-18 11:00 A.M.	Time Logged		Time Logged	
Calibration Check Time Logged Date	3-22-18 11:00 A.M. 3-22-18 4 ALT QL DENSITY	Time Logged Date Run No. Tool Model	12:00 P.M.	Date Run No. Tool Model	12:45 P.M.
Calibration Check Time Logged Date Run No.	3-22-18 11:00 A.M. 3-22-18	Time Logged Date Run No.	12:00 P.M.	Date Run No. Tool Model Tool SN	12:45 P.M.
Calibration Check Time Logged Date Run No. Tool Model	3-22-18 11:00 A.M. 3-22-18 4 ALT QL DENSITY	Time Logged Date Run No. Tool Model	12:00 P.M.	Date Run No. Tool Model Tool SN From	12:45 P.M.
Calibration Check Time Logged Date Run No. Tool Model Tool SN From To	3-22-18 11:00 A.M. 3-22-18 4 ALT QL DENSITY 6187 SURFACE 1190 FT.	Date Run No. Tool Model Tool SN From To	12:00 P.M.	Date Run No. Tool Model Tool SN From To	12:45 P.M.
Calibration Check Time Logged Date Run No. Tool Model Tool SN From To Recorded By	3-22-18 11:00 A.M. 3-22-18 4 ALT QL DENSITY 6187 SURFACE 1190 FT. A. OLSON	Date Run No. Tool Model Tool SN From To Recorded By	12:00 P.M.	Date Run No. Tool Model Tool SN From To Recorded By	12:45 P.M.
Calibration Check Time Logged Date Run No. Tool Model Tool SN From To Recorded By Truck No	3-22-18 11:00 A.M. 3-22-18 4 ALT QL DENSITY 6187 SURFACE 1190 FT. A. OLSON 750	Date Run No. Tool Model Tool SN From To Recorded By Truck No	12:00 P.M.	Date Run No. Tool Model Tool SN From To Recorded By Truck No	12:45 P.M.
Calibration Check Time Logged Date Run No. Tool Model Tool SN From To Recorded By Truck No Operation Check	3-22-18 11:00 A.M. 3-22-18 4 ALT QL DENSITY 6187 SURFACE 1190 FT. A. OLSON 750 3-22-18	Date Run No. Tool Model Tool SN From To Recorded By Truck No Operation Check	12:00 P.M.	Date Run No. Tool Model Tool SN From To Recorded By Truck No Operation Check	12:45 P.M.
Calibration Check Time Logged Date Run No. Tool Model Tool SN From To Recorded By Truck No	3-22-18 11:00 A.M. 3-22-18 4 ALT QL DENSITY 6187 SURFACE 1190 FT. A. OLSON 750 3-22-18 3-22-18	Date Run No. Tool Model Tool SN From To Recorded By Truck No	12:00 P.M.	Date Run No. Tool Model Tool SN From To Recorded By Truck No	12:45 P.M.


E-Log Calibration Range: N/A	Calibration Points:	N/A	


All interpretations of log data are opinions based on inferences from electrical or other measurements. We do not guarantee the accuracy or correctness of any interpretations or recommendations and shall not be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our employees or agents. These interpretations are also subject to our general terms and conditions set out in our current Service Invoice.


Disclaimer:


Na	at. Gamma	T	Depth			3-Arm Calipe	r		
API 200 Fluid Resistivity Ohm-m 20			1in:20ft	0 Inches 10 Temperature					
				•					
3						3			
3						3			
}									
\$			20.0						
3									
\{						<u> </u>			
ξ						3			
٤									
5	>		40.0						
₹									
3									
3									
حج م			60.0						
<u> </u>			00.0						
5						3			
7									
\$									
3			80.0						
Ş									
Ę						1			
35									
\{			100.0						
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			100.0						
3						\$			
3						3			
- 5									
			120.0						
1									
4									
Š									
_<			140.0						
\$			170.0						
3									
3									
- 3			160.0						













Natural Gamma and Caliper can only be collected logging up hole. Fluid Temperature/Resistivity can only be collected logging down hole. Temperature Rating: 70 Deg C (158 Deg F) Presure Rating: 200 bar (2900 psi) **Natural Gamma Ray = 0.76 m (29.75 in)** *NOTE: Lengths on a particular tool may vary from those listed on this document due to probe sizes and styles utilized* 3-Arm Caliper = 1.44 m (56.75 in) Distance from tool top: 2.20 m (86.5 in) Available Arm Sizes: 3", 9", and 15" TFR (Temperature/Fluid Resistivity) = 0.39 m (15.5 in)



1.375" or 34.9 mm Diameter

Company

FLORENCE COPPER

Well

O-06

Field

FLORENCE COPPER

County

PINAL

State

ARIZONA

Final GCT Summary

APPENDIX F

Cement Bond Log Summary

WELL 0-06

Geophysical Log Summary

COMPANY: FLORENCE COPPER COMPANY

FLORENCE COPPER COMPANY

STATE: ARIZONA

WELL ID: O-06

FIELD:

COUNTY: PINAL

Logging Engineer: VARIOUS


Date Logged: VARIOUS


Processed By: K.M / B.C.


Date Processed: 07-17-18




















				gario (A.H.)		rinnininininininininininininininininini	ř										
												Version	on 4-8-18,	RECC			
1220.0													!				
														Cement			
		,											40	us/ft	220	700	
	-3	g/cc	1											PVC	•••••	700 CPS	
		Cased 3-22-18											40	us/ft	220	Cased 3-22-1	8
		Compensation											40	us/II	220	4 Pi Density (V	Vet)
	-1	g/cc	3											FRP		2000 CPS	
		Cased 3-22-18											40	us/ft	220	Cased 3-22-1	8
		Comp Density												Steel		4 Pi Density (D	
	0	Inches	10	100	uSec	1000	100	uSec	1020	100	uSec	1020	40	us/ft	220	1 g/cc	. ,
		Cased 3-22-18			Open 2-6-18			Cased 3-22-18			Cased 3-22-18			Cased 3-22-18		Cased 3-22-1	8
		3-Arm Caliper			RX1 - TT (60mm)			RX1 - TT			RX4 -TT			P-Wave Slow		Far Density	,
	0	API	200	100	uSec	1000	100	uSec	1020	100	uSec	1020	40	us/ft	220	1 g/cc	
		Cased 3-22-18			Open 2-6-18			Cased 3-22-18			Cased 3-22-18			Cased 3-22-18		Cased 3-22-1	8
		Nat. Gamma			RX1 - VDL (60mm)			RX1 - VDL			RX4 - VDL			Velocity Analysis		Near Densit	y
1in:20ft							•	0.000 : 6			:4 0						
Depth								U-ue Sonic C	BL MI	ith Der	sity Summar	У					

APPENDIX G SAPT Documentation

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY STANDARD ANNULAR PRESSURE TEST

Operator_FLORENC	E COPPER, INC		State Permit No. P-101704				
	HUNT HWY		USEPA Permit No. R9UIC-AZ3-FY11-1				
FLOREN	ICE, AZ 85132		Date of Test <u>4/05/2018</u>				
Well Name O-06			Well Type ENV-MONITORING- Class III				
LOCATION INFOR	MATION	SE Quarter	of the <u>NW</u> Quarter of the <u>SW</u> Quarter				
of Section 28	; Range	9E ; Tow	vnship 4S; County PINAL;				
Company Representa			; Field Inspector LAUREN CANDREVA ;				
Type of Pressure Ga	Pressure transductuge with data logger		psi full scale; 0.001 psi increments;				
New Gauge? Yes	No I If no, date	of calibration	Calibration certification submitted? Yes 🗖 No 🕡				
TEST RESULTS							
Readings must be tal			5-year or annual test on time? Yes No				
minimum of 30 minu		I and V wells and 6	0 2-year test for TA'd wells on time? Yes \(\boxed{\textsup}\) No \(\boxed{\textsup}\)				
minutes for Class I w		111	After rework? Yes No				
For Class II wells, an psig. For Class I well			Newly permitted well? Yes ♥ No ■				
greater of 300 psig or			Newly permitted well? Yes W No L				
injection pressure.	r ree par dee re me	ammani perimited					
Original chart record	ings must be subm	itted with this form	n.				
•	D						
Time	<u>Pressure</u> Annulus		C : : FIL NOMINAL				
13:15	164.39	Tubing same	Casing size 5" - NOMINAL Tubing size 2"				
13:20	165.35	same	Packer type INLFATABLE PACKER				
13:30	165.73	same	Packer set @ 3.66(top), 481.86(bottom)				
13:45	166.76	same	Top of Permitted Injection Zone 405 feet				
			Is packer 100 ft or less above top of				
			Injection Zone ? Yes No 🛘				
			If not, please submit a justification.				
			Fluid return (gal.)				
			Comments: Two tests were conducted to confirm results, data				
Test Pressures:	Max. Allowable		for both tests included in attached table and chart nitial test pressure x 0.05 8.22 psi				
		1	est Period Pressure change 2.37 psi				
Test Passed	Test Failed						
If failed test, well mu	st be shut in, no in	jection can occur, a	and USEPA must be contacted within 24 hours.				


If failed test, well must be shut in, no injection can occur, and USEPA must be contacted within 24 hours. Corrective action needs to occur, the well retested, and written authorization received before injection can recommence.

I certify under penalty of law that this document and all attachments are, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. (See 40 CFR 144.32(d))

Printed Name of Company Representative

Signature of Company Representative

Date



Well O-06 SAPT Data		
Transducer Serial Number:	554227	
Tranducer Model Number:	Level TROLL 400 non-vented 300 psi	
Date and Time	Pressure (PSI)	Corrected Pressure (PSI) (Sensor pressure - barometric pressure)
4/5/2018 12:30	176.291	162.33
4/5/2018 12:31	176.462	162.50
4/5/2018 12:32	176.609	162.65
4/5/2018 12:33	176.77	162.81
4/5/2018 12:34	176.936	162.98
4/5/2018 12:35	177.068	163.11
4/5/2018 12:36	177.206	163.25
4/5/2018 12:37	177.313	163.36
4/5/2018 12:38	177.427	163.47
4/5/2018 12:39	177.581	163.62
4/5/2018 12:40	177.789	163.83
4/5/2018 12:41	177.824	163.87
4/5/2018 12:42	177.968	164.01
4/5/2018 12:43	178.139	164.18
4/5/2018 12:44	178.228	164.27
4/5/2018 12:45	178.383	164.43
4/5/2018 12:46	178.546	164.59
4/5/2018 12:47	178.603	164.65
4/5/2018 12:48	178.773	164.82
4/5/2018 12:49	178.875	164.92
4/5/2018 12:50	179.034	165.08
4/5/2018 12:51	179.156	165.20
4/5/2018 12:52	179.289	165.33
4/5/2018 12:53	179.396	165.44
4/5/2018 12:54	179.504	165.55
4/5/2018 12:55	179.625	165.67
4/5/2018 12:56	179.721	165.76
4/5/2018 12:57	179.809	165.85
4/5/2018 12:58	179.922	165.96
4/5/2018 12:59	180.095	166.14
4/5/2018 13:00	180.181	166.22
4/5/2018 13:01	13.958	0.00
4/5/2018 13:02	13.977	0.02
4/5/2018 13:15	178.352	164.39
4/5/2018 13:16	178.479	164.52
4/5/2018 13:17	178.585	164.63
4/5/2018 13:18	178.645	164.69
4/5/2018 13:19	178.775	164.82
4/5/2018 13:20	178.844	164.89
4/5/2018 13:21	178.981	165.02
4/5/2018 13:22	179.061	165.10

Well O-06 SAPT Data		
Transducer Serial Number:	554227	
Tranducer Model Number:	Level TROLL 400 non-vented 300 psi	
Date and Time	Pressure (PSI)	Corrected Pressure (PSI) (Sensor pressure - barometric pressure)
4/5/2018 13:23	179.153	165.20
4/5/2018 13:24	179.228	165.27
4/5/2018 13:25	179.312	165.35
4/5/2018 13:26	179.371	165.41
4/5/2018 13:27	179.451	165.49
4/5/2018 13:28	179.521	165.56
4/5/2018 13:29	179.57	165.61
4/5/2018 13:30	179.686	165.73
4/5/2018 13:31	179.767	165.81
4/5/2018 13:32	179.873	165.92
4/5/2018 13:33	179.867	165.91
4/5/2018 13:34	179.97	166.01
4/5/2018 13:35	180.011	166.05
4/5/2018 13:36	180.104	166.15
4/5/2018 13:37	180.132	166.17
4/5/2018 13:38	180.255	166.30
4/5/2018 13:39	180.271	166.31
4/5/2018 13:40	180.387	166.43
4/5/2018 13:41	180.466	166.51
4/5/2018 13:42	180.481	166.52
4/5/2018 13:43	180.568	166.61
4/5/2018 13:44	180.603	166.65
4/5/2018 13:45	180.713	166.76
4/5/2018 13:46	13.976	0.02
4/5/2018 13:47	13.974	0.02

APPENDIX H

Well Development Field Forms

Project Name: FC	Project No.: 129(687-607	
Well No.: 0 - 06	Date: 77 19118 - 2/20/18	
Location: See Plan	Measuring Point:	
Total Depth of Well (ft bls):	Screen Interval (ft bis): ~ 508 - 1000	
Pump Type/Setting (ft bls):	Activity: AIR LIFT	
How Q Measured:	H&A Personnel: Philip Clarkin	

	Comments	Turbidity NTU	Temp. °C	Sp. Cond. (μmhos/cm)	рН	Sand Content (ppm)	Specific Capacity (gpm/ft)	Pumping Water Level (ft)	Discharge (gpm)	Time
STAN	Brain MUD	OR	_	_	_	0.1	_	-	2	1450
ME	BROWLMUD	01-	-	-		01)	-)	1500
	Opaque Brown, Mulely	OR	7	/	_	0.0)	_	VI	1530
	Oprove Brown, Muddy	OR	-	-	_	0.0	-	_	21	1545
	Opaque Muddy Brown	OR	-	1	1	0:0	-		~1	1600
	Lighter brown, muddy	OR	_		_	0.0)		~1	1620
IV	Opaque light brown, mudel	OR	_	-	-	0.0	-	_	~1	1640
	bent blown, muddy	OR	-		_	0.0		_	21	1700
	Went books, muddy	901	20.45	1502	8.02	0.0	_	-	~1	715
pare	light brown, slightly trans	970	19.50	1469	7,77	0.0	-	_	~1	730
+	light tan brown, slightly	758	19.35	1462	7.91	0.0			21	1745
Fran	light tan brown slightly	945	19.48	1474	7.78	0.0	_	-	~1	1800
tra	Ival + tan brown, Slightly	685	19.09	1459	7.72	0,0)	-	21	1815
tra	light tan brown, Slightly	634	19.33	1467	8.10	0.0	_	-	~1	0881
	light brown, muddy	OR	15.43	1860	7.89	0.1	-	-	~ 9	0815
	Hight tan brown muddy	699	19.96	2065		0.1	-		21,9	2830
+00	1-ght tan brown, Slightly	230	19.63	2049	8.19	D.0	-	-	~1.9	6845
	light tan brown ST	409	20.01	2066			-		21.9	0400
	Itaht tan brown, ST	394	20.57	2083	8.19	0.0	-	-	-1.9	0915
	Stightly boun, FT	325	19.60	2047	8,23	0.0	_	_	21.9	0930
+_		val -	Inter	next	a to	movin	Ftrag	al April	Stopp	0940
mohn	Took a minote between sam	6			775	1	811.85	Eductor		A.c.In
1	light tan brown, FT	365	20.63	2092	8.21	0.0	-		~3.2	1145
-	light lan brown, ST	624	21.50	2111	8.25	0.0	_		~3.2	
-	Itahit tah brown, FT	483		2132	8.23	0.0	_	_	~3.2	
-	light ten bown, FT	307	22.47	2144	8.16	0.0	-	-	~3.2	1230
4	light tan, FT	240	22,41	327136	8.01	0.0	-	-	23.2	
4		val,	inter	next	24 to	mouri	Etino.	el airlif	Stoppe	1250
					0		U		11	
								414176	ts:	Commen
1	erange.	11 (m)	4.1.10	des t			0 0		Over	20 17 0
1	a mide.	12 00	Blarry	then to	sary h	vanece	dings			Collin
Mar	through come art 16 1	1.7437	of Vo	art les	See	- car	acent	transp	=> Fair	21

HALEY

Project Name: FCT	Project No.: 129687-007
Well No.: 0-06	Date: 2/20/18
Location: See plan	Measuring Point:
Total Depth of Well (ft bls):	Screen Interval (ft bis): ~ S20 - 1200
Pump Type/Setting (ft bls):	Activity: Airlift
How Q Measured:	H&A Personnel: P. Clar; 210

* Turbidity Comments Temp. Sp. Cond. Sand Discharge Pumping Specific °C NTU (µmhos/cm) (gpm) Water Level Capacity Content (ft) (gpm/ft) (ppm) 8. 20 2143 22.17 270 light tan, FT 0.0 1330 light tan brown, ST 8,20 2093 22.41 727 1345 N 0.0 22.84 524 8.26 2126 00 1400 8.27 2140 light tan, FT 0.0 23.00 227 1415 ~7 Haht tan, FT 1430 VZ 2277 169 light tan, Fi 8.18 2117 2291 142 0. 0 1445 - Arristing, setup for next interval 1447 dicline 525 Enductor 1200 1580 8.22 2074 0.0 21.35 176 light tan, FT 1690 f 22.58 OR Opaque brown, muddy 8.28 2152 1615 ~5.0 8.05 2099 22.91 OR Opaque brown modely 1630 5.2 paque light brown fine sand Q.5 8.15 2080 22.18 OR 1645 8.17 2070 22.15 468 1700 POS 52.55 yant tan bown, ST 1715 8.03 2060 0.2 Clybrt fan, ST almost CT 0.1 8.21 2060 2270 150 1730 1734 OR => Overlange, ST = Slightly Transparent through liquid at 12 FT & Fairly Transparent - care see at least CT = Completely Transparent - Can see to other side at YL.

* Only hade one come, sand content measurements are timed ~ 14 mins sample collection.

inductor

06.5

Mine

SAS

178

Project Name: FCI	Project No.: 129687-007
Well No.: 0-06	Date: 02/22/18
Location: See plan	Measuring Point:
Total Depth of Well (ft bls):	Screen Interval (ft bls):
Pump Type/Setting (ft bls):	Activity: A: M. ft Aqua clear
How Q Measured: Stopwartch+ 5. 9al bucket	H&A Personnel: P. CHarizio

Time	Discharge	Pumping	Specific	Sand	pH	Sp. Cond.	Temp.	Turbidity	Comments
Time	(gpm)	Water Level	Capacity	Content	Pil	(μmhos/cm)	°C	NTU	Comments
	(gpiii)	(ft)	(gpm/ft)	(ppm)		(µminos/cm)		*	
G D.	ector	420	A: chine	3781	PSI	175		-	
230	227	-	-	0.0	7. 3		17.60	00.	Opaque brown, mudd
245		_	-	<0.1	8,05		19.47	OR	Opaque brown, mudd
300		-	-	0,0	8.10	2222	18.95		Opaque brown 1
820		_	_	10.1		2264	19.90	995	opaque lyltbrown, m
840		-	-	0.0		2269	19.10	OK	opaque, light brown
900		-	-	0.0		2231	19.07		opaque, lightbown muc
915				00		2855	19.64	921	Oraque, light tan brown
2930		_	_	0.0		2313	20.78		Opaque, light tan brow
2945		_	-	0.0		2316	20.84		Opaque light tan brow
000		_	_	0.0	8.26	2334	21.06		paque, light tan brow
015		-	_	0.0		2315	20.74	979	opagoe, tight tan be
030	3.3	_	_	0.0	8.30	2342	21.22	973	Opaque, light tan brown,
045		-	_	0.0	8.23	2325	20.87		opaque, light tan bown
10.0			_	0.0		2366	21,53		opaque, light tan boun
	oped	awlinin	m	vines		ext o		1,00	The state of the s
1155	Educ		Uch A.	11, ne 4	11' De	I 175	7		
55	22.7	-	-//	20.2	7.99	2443	21.59	OR	opaque light brown, m
215		_	-	0.0	8.11	2367	21.55	692	light tan brown, muddy,
230		_	-	0.0		2362	21.93	577	light tan, STA (Batterie
245		_	-	0.0	8.12	2353	22.01	621	Right tag, ST
1380		_	_	0.0	8.10	2354	21.94	599	light ten, ST-FT
315		_	-	0.0	8.04	2321	21.31	620	light tan ST
1330			_	0.0	8.17	2366	22.18		light tan, ST-FT
1345		_	-	8.0		2362	21,90	584	light tan FT
	ped	Airlinme,	moun	-	nert	depth.			- gar
-10	per		1.100.11	7	· ·	of the			
-				-					

Project Name: FCI	Project No.: 129 687 - 007
Well No.: ()-06	Date: 2/22/18
Location: See Plan	Measuring Point:
Total Depth of Well (ft bls):	Screen Interval (ft bls):
Pump Type/Setting (ft bls):	Activity: A Niffer after ague clear
How Q Measured:	H&A Personnel: P.JCla (1710

	(gpm)		Capacity (gpm/ft)	Content (ppm) A, Cl. A CO. I O. O	e 52 8.48	2337	7 /7-3 21.64 22.20	NTU 815	light bown, black specks
1500 1515 1530 1545 0920	- - Stopp	811.	6S',	A, rlin (0.1	8.03 8.48	2337	21.64		light bown, black specks
1500 1515 1530 1545 0920	- - Stopp		-	0.0	8.03 8.48	2337	21.64		light bown, black specks
1500 1515 1530 1545 0920	- Stopp	=	-	0.0	8.48				light bown, black specks
1515 1530 1545 0920	- Stopp	=	-	0.0		2445	12222		
1530 1545 0920	- Stopp	- -	_	0.0				782	light to brown, 2 5T
0920	Stopp	- led an	-			2379	22,78		I yout tan, min STAF
0920	Stopp	red an		0.00	8.05		22.97	378	light tan, FT
0940	-11	ed all	-		8.13	2755	22.75	247	light ten, FT >CT
0940	-11	-11	TIFtin			to ne		epth	0
1000		-	-0	10.0	8.27		19.79	316	light tan, FT
1000	-	-	-	0.0	8.33		21.61	341	light tan, FT
1020	-	-	-	0.0		2454	22.33	111	light tan, FT->CT
1000	-	-	-	0.0	8.29	2433	22.30	79.7	Hear, CT
5	toppe	d airl	Aina						
1100	A	_	4	0,0		2416	21.08	163	light tan FT
1120	-	_	-	0.0	8.32			472	light tan, ST
1140	~	-	-	1.8	8.27	2670	22.74		bown, moddy
1205	-	_	1	0.8	8.25	2446	23.03	OR	light brown middy
1225	-		-	10.1	8.34	2447	23.15	702	light tak brown, mud
1250	_	-	-	1.5	8.28	2415	22.96	OR	brown, myddy, op
1325	_	_	_	10.1	8.27	1381	22.40	OR	Profit tan bown, SF
	-	-	-	101	8.29	7377	22.32	588	inght tan, = T
1420	-	-	-	<0.1	8,22	7374	22.45	126	Dedr, FT-DCT
1510	-	Taran Land	-	0.0	8, 28	2343	21.93	223	light tan, FT
1530	-	-	-	0.0	8. 29	2357	22.32		light tan, FT
1545	-	_	_	0.0	8.37	2342	22-12	81.3	Clear, CT
1600	~	_	-	00	8.36	2335	22.02	39.0	Clear
1615	-	_	_	0.9	8.37	2275	21.05	31.8	clear
1012									

HALEYICH

Project Name: FC1	Project No.: 129687-804
Well No.: 0-06	Date:4 2-24-18
Location:	Measuring Point:
Total Depth of Well (ft bls): (200	Screen Interval (ft bls):
Pump Type/Setting (ft bls):	Activity: ALR-UPT
How Q Measured:	H&A Personnel: C-GIUSTI

Time	Discharge (gpm)	Pumping Water Level (ft)	Specific Capacity (gpm/ft)	Sand Content (ppm)	pН	Sp. Cond. (µmhos/cm)	Temp. °C	Turbidity NTU	Comments
225		1		and the same of	-				STALL AIR LIFT, EDUCTO
	26.PM	30 Liters min	- Aleksania	40,1				OR	STALL ALL LIFE, EDUCTO R 1177 Jight Brown Trus SUBHITILY LEHTED BLOW MICKY / BROWN
7051				10.1				en	SUBHITINY LIGHTED BLOG
35 4	9			0				342	MICKY BROWN
			No. of London	0				449	Educa @ 1175
50		V	1 3 9 10	0				247	
210					1				RIMP OFF
10					TOWN.				START AIRLIGT 1/77
45		V					- 138	4000	END ALLERT 148
				1200					CLEAR TO MILKY
							37.		
							100	-	
					7.				
									- 13
								1 1	
					-		_	1	
							-		
		-							
-			-						

2/25 1345 EDUCTOR WORKERD DOWN TO 1198 SURPING FREQUENCY DISCHARGE HAS BECOME CONSISTENTLY CLEAN MICKY

2/25

Project Name: FLT PTF	Project No.: 129687 - 067
Well No.: 9-04 0-04	Date: 2/26/19 2/27/18 - 3/1/18
Location: Florence, AZ	Measuring Point: Dychard Spiller
Total Depth of Well (ft bls):	Screen Interval (ft bls):
Pump Type/Setting (ft bls):	Activity: Airtist Pumpino
How Q Measured: Con / Chopworth Totalizer	H&A Personnel: 5 Hensel

Time	Discharge	Pumping	Specific	Sand	рН	Sp. Cond.	Temp.	Turbidity	Comments	(655)
300	(gpm)	Water Level	Capacity	Content		(µmhos/cm)	°C	NTU	1	
		(ft)	(gpm/ft)	(ppm)	-					DTW
1245		1164	_	0.3	7.60	14.78	24.57	bierrand		289.6
1310	53.3	1164	~	0.0	7.64	1445	24.73	26.0	cloudy	258,2
1399	353.3	1164	-	0.0	7.70	1433	24,63	14-1	clear	291.6
	60-0	1164	-	0.0		1420		10.2	elear	250.8
1355	53.3	1164	~	0.0	7.69	1416	24,77	7.26	cheur	249.5
1405	"	11604	4	0.0	7.58	1391	24.04	10.5	Pump off	751.6
1435		1164	-	6.0	7.5%	1391	24.04	1005	Rumpon clear	252,6
1455	55.0	1164	Sm-	0.0	7,74	1399	24,16	8.74	clear 1	251.2
1560	-	ilen	-	-	-	-	-	4	Punp of	251.6
1535	47	1164	~	6.0	7.74	1347	22.81	6.85	Pump on elear	282.6
1545	-	1164	-	-	-	-	-	-	Pump off	251.6
1600	76	1164	-	0,0	7.80	1363	23,40	7,08	Pumpon lear	1222.6
1610	*	1164	4-	-	-	-	-	-	Pump sift,	1250.6
1625		1164	-	0.0	7,72	1358	23.09	6.50	Pemp on ilear	1222,4
1635	-	1164	ba-	-	-	~	-		Pumo nost	
FERU	1620 62	1164	in.	0-0	8-20	1242	20-15	46.0	Pumpon yearle	Love 218.
1640	62	1164	-	6.0	7.80	1455	24,46	199	1bear	1244.6
1458	62	1164	-	0.0	7,89	1449	24.64	6.52	Clear	258.1
1740	-	4	-	~	-	~	-	,	Pump 055	
955	-	~	-	-	-	-	-	-	Pumpon	01011
1000	64	902	-	0.0	8.54	1333	21.71	34.0	clear	2184
1010	64	962	1	0.0	9.72		23.80	14.7	clear	244.4
1039	64	902	-	0.0	7.72	1431	24.23	9.19	CRAT	246.1
1055	64	982	-	0,0	7.72	1433	24.59	9.69	clear	247.0
1110	(44	402	*	6.0	7.71	1430	24,40	5.18	clear	248.1
1115	1	-	~	-	-	-	-	, -	Rupors	2487
1130	68	902	~	0.0	7.75	1402	23.67	5.25	Pump on clear	221.6
1145	68	962	*	6.0	7.73	14 38	24.44	5.65	clear "	1247.6
Commer	nts:									
Commen	nts:									

HALEY

Project Name: FCI PTF	Project No.: 129687-607	
Well No.: 0 - 0 6	Date: 3/1/18 - 3/2/18	
Location: Florence, AZ	Measuring Point: Spicket	
Total Depth of Well (ft bls): \ 200	Screen Interval (ft bis): 500 - 1200	
Pump Type/Setting (ft bls): 400200 electric	Activity: Pumpina	
How Q Measured: totaline	H&A Personnel: /3 Hetnise	

Time	Discharge	Pumping	Specific	Sand	pH	Sp. Cond.	Temp.	Turbidity	Comments	
	(gpm)	Water Level	Capacity	Content		(µmhos/cm)	°C	NTU		(645)
	111111111111111111111111111111111111111	(ft)	(gpm/ft)	(ppm)		- 30 1614			0 10	DTW
150	16		-		~	-	-11	- 1.77		40.6
210	65	902	de	0.0	7.73	14/8	84,143	5.18		122.5
aas	65	105	~	0.0	1.7	1416	23.44	5.67		247.4
230	~	-	-	-	7	1 111	211.12	-	Pung of	249.2
249	68	902	-	0,0	7.77	IMIM	24.17	3.66		2271
300		902	-	0.0	7.73	1431	2457	3.66		447.8
305		1 100	- 20	6.0		10.11	211 67	- 05		
420	75	600	-	0.0	7.68	1946	24.03	7.05		2000
435	79	660	-	0.0	7.73	1438	25.00	3.42	chear	246.6
500	75	600		6.0	7.81	1440	15.13	2,62	Chear	246,2
509	~	_	-	-	- 11	-	- 100	101	Rimpose	247.0
200	66	600	-	0.0	7.56	1341	20.45	15.6	Pump on cleur	218.3
7725	tele	(00)	~	0.0	7,60	1365	23.34	4.72	Clear Pump off	246.2
730	-	-	-	-	-	-	- 0 0/	(0.39		
145	65	600	~	0.0	7.74	1347	23.06		Rimpon, elear	
605	45	600	,	0.0	7,73	13623	23.85	5-53	zkar	246.1
325	(95)	600		0,0	7,74	1361	23.78	8.63	Clear	24246
135	100	-	-	-	-		05 97	0 21	Punp off	248.9
455	71	600	h	0.0	7.79	1373	23.92	9.22	Rimp on, clear	247.4
10	71	000	-	0.0	7.76	1381	24.02	3.63	clear	248.2
25	71	600	-	0.0	7,79	1381	24.65	3.53		248.2
430	-	- 03	-	~ ~	7.76		24.33	18.1	Pump off	1
955	71	(000)	-	0.0	7 77	1386	24.65	5.76	Pump on their	244.6
010	71	600	-	0.0	1.11	1344	-	2.49	Clear	246.7
039	71	600	_	0.0	7.76	1387	24,90			24639
1040	-	-	-	-		1410		575	Rupost	218.6
100	77	6.00	4	0.0	7,80	1389	24,21	10.9	Rump on clear	1245,1
1120	77	000	~	0.0	7,76	1385	24.89	3,71	clear	12.1

3/2/18

ALDRICH

Project Name: FCI PTF	Project No.: 121687 - 007			
Well No.: 0 - 0 6	Date: 1/2/18			
Location: FLOTENCE, AZ	Measuring Point: Spicked			
Total Depth of Well (ft bls): 1700	Screen Interval (ft bls): 500 ~ 1200			
Pump Type/Setting (ft bls): Arvalass elacht?	Activity: Pumping			
How Q Measured: Total zer	H&A Personnel: 3 Hersel			

Time	Discharge (gpm)	Pumping Water Level	Specific Capacity	Sand Content	pH	Sp. Cond. (µmhos/cm)	Temp.	Turbidity NTU	Commen	ts (bg5)
564	(96)	(ft)	(gpm/ft)	(ppm)		(January)				DTW
145	77	600	~	0.0	7.80	1389	24.97	4.21	Clear	249.5
200	77	600	-	0.0	7.79	1390	24.99	4.73	Clear	246,1
205	~	-	-	~	~	_	~	-	Rompost	246.3
1220	80	600	L .	0.0	7.80	1391	24.62	6.18	Pumpon, chear	214,4
240	80	600	- 3	0.0	7.81	1389	25.19	3,33	Clear	236.1
1245	~	_	_	14	-	-	_	-	Pump of	23613
305	40	600	-	0.0	7.76	1409	24.27	3.81	Puny on dear	820.0
325	60	600	t-m	0.0	7,77	1390	25.13	2.36	clear	245,3
340	80	(000)	-	6.0	7.75	1364	25.12	2.86	dear	246.2
1355	40	600		0.0	7.77	112	25.23	2.59	(jacon	245.9
1400	-	_	-	_	_		~	-	PUMP OFF	246-2
415	69	(000)	-	0.0	7.73	1377	24,59	3.56	Pung on year	
430	69	000	-	0.0	7.80	1399	25,25	3.67	Clear	245.6
1445	69	6,00	-	0.0	7,75	1389	25,26	3.41	cleur	246.0
500	-	~	-	_	-	-	_	~	RIMP Off,	246.2
300									End pumping	
			-	1		2			117	71
				1		1	15			
				- FIE						
							J. 195		0	
						10.				
3-11			7			¥ - 15				
TO SECOND						1				
						-				
						1 1				
							1			
							1			
comment	ts:	1								
							TE.			
				7			1			

APPENDIX I

Well Video Log and Gyroscopic Survey Reports



Southwest Exploration Services, LLC

25811 S. Arizona Avenue Chandler, AZ. 85248

Phone: (480) 926-4558 Fax: (480) 926-4579 Web: www.swexp.com

Client: Florence Copper			Survey Date:	March 21, 2018				
Address: 1575 West Hunt Hwy					Run: 1			
	State	e: AZ Zip: 85132						
		P.O.:		Florence Copper				
Copy To:				CCV S.S. Color Ca	mera - Ring of Lights			
5			Zero Datum:	Top of Casing				
Location:				1200 ft. Vehicle	e: 290			
Field: Florence Copper Project		Type Perfs: Horizontal Slots						
1st Csg.O.D. 5 In. Csg Weight:	From: 0 ft. To: 11	96 ft. 2nd	Csg.O.D	_Csg Weight:	_From:To:			
Standing Water Level: 232.07 ft. Pumping Water	r Level:Pum	p Depth:O.D.Ref.: Me	asured	_Casing Buildup: None				
Operator: D. Beam Lat.:	L	ong.:	Sec:	Twp:	Rge:			
Other Information: Wellbore Snapshots	True Depths: (SideScan-Feet)	WEI	LLBORE / CAS	ING INFORMATIO	N			
0 Ft (See Other Side) 232.1 Ft (See Other Side)	, ,	Survey started at the top of th	e casing.					
SM EXPLORATION FLORENCE COPPER	232.1	Static water level observed.						
FELSON ME TO THE STATE OF THE S	501.1	Transition piece observed.						
	503.	First perforations observed.						
501.1 Ft (See Other Side) 503 Ft (See Other Side)	600.	Perforations at 600 ft.						
Sur of	705.	Perforations at 700 ft still appo	ear clear.					
103.00	900.	Perforations are still clear.						
600 Ft (See Other Side) 705 Ft (See Other Side)	100.	No change in perforation cond	dition.					
	1,194.1	View of the casing just above	the bottom of the ca	asing.				
SOF OF 16 M	1,195.1	Soft Bottom observed, survey	ended.					
1								
900 Ft (See Other Side) 1000 Ft (See Other Side)								
800, 03, 1000, 03,								
1194.1 Ft (See Other Side) 1195.1 Ft (See Other Side	<u> </u>							
1151.05								
Notes:								
Page Number: 1								



Wellbore DRIFT Interpretation

PREPARED ESPECIALLY FOR

Florence Copper and Florence Copper

O-06

Wednesday - March 21, 2018



This Wellbore Interpretation Package represents our best efforts to provide a correct interpretation. Nevertheless, since all interpretations are opinions based on inferences from electrical or other types of measurements, we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by Customer resulting from any interpretation made by this document. We do not warrant or guarantee the accuracy of the data, specifically including (but without limitations) the accuracy of data transmitted by electronic process, and we will not be responsible for accidental or intentional interception of such data by third parties. Our employees are not empowered to change or otherwise modify the attached interpretation. Furthermore, along with Eagle Pro Software we do not warrant or quarantee the accuracy of the programming techniques employed to produce this document. By accepting this Interpretation Package, the Customer agrees to the foregoing, and to our General Terms and Conditions.

WELLBORE DRIFT INTERPRETATION Southwest Exploration Services, LLC

OULIIWESL		١
	(480) 926-4558	

Company:		Florence Copper			Well Owner	:		Florence Copp	er	
County:		Pinal	State: Arizon		Arizona		Country:	United States		
Well Number:		O-06		Survey Date:	Wednesday - March 21, 2018		Magnetic Declination: Declination Correction		on Not Used	
Field:		Florence Cop	per Project		Drift Calculation Metho	dology:	Balanced Tangential Method			
Location:										
Remarks:										
Witness:	н&А	Vehicle No.:	800	Invoice No.:	Operator:	K. MITCHELL	Well Depth:	1220 Feet	Casing size:	5 Inches
Tool:		Gyro - 1422		l at·	l ong ·		Sec ·	Twn ·	Rae ·	

MEASURED DATA			DATA COMPUTATIONS								
DEPTHS, feet	INCLINATIONS, degrees	AZIMUTHS, degrees	TVD, feet	T. LATITUDE, feet	T. LONGITUDE, feet	DOGLEG SEV., degrees per 20 Feet	DOGLEG SEV., degrees per 100 feet	DRIFT DIST., feet	DRIFT BGR. degrees		
0	0.37	252.11	0.00								
20	0.47	238.07	19.99	-0.063	-0.131	1.00	0.49	0.15' (1.80'')	244.30		
40	0.49	255.93	39.98	-0.127	-0.284	0.41	0.62	0.31' (3.72")	245.80		
60	0.61	237.79	59.97	-0.205	-0.457	0.96	0.63	0.50' (6.00")	245.90		
80	0.69	210.64	79.96	-0.365	-0.608	0.84	0.94	0.71' (8.52'')	239.00		
100	0.73	188.05	99.96	-0.595	-0.687	0.42	0.78	0.91' (10.92")	229.10		
120	0.70	169.55	119.95	-0.841	-0.683	0.13	0.64	1.08' (12.96")	219.10		
140	0.70	157.79	139.94	-1.074	-0.615	0.43	0.41	1.24' (14.88'')	209.80		
160	0.61	136.95	159.93	-1.265	-0.496	0.83	0.72	1.36' (16.32'')	201.40		
180	0.53	144.05	179.92	-1.418	-0.369	0.95	0.25	1.46' (17.52'')	194.60		
200	0.50	122.33	199.91	-1.540	-0.241	0.37	0.75	1.56' (18.72'')	188.90		
220	0.65	130.46	219.90	-1.660	-0.081	1.00	0.28	1.66' (19.92'')	182.80		
240	0.62	155.21	239.89	-1.832	0.051	1.00	0.86	1.83' (21.96'')	178.40		
260	0.65	154.52	259.88	-2.033	0.145	0.34	0.02	2.04' (24.48'')	175.90		
280	0.76	183.33	279.87	-2.268	0.186	0.93	0.99	2.28' (27.36'')	175.30		
300	0.50	216.15	299.86	-2.471	0.127	0.78	1.13	2.47' (29.64")	177.10		
320	0.46	241.82	319.85	-2.579	0.005	0.53	0.89	2.58' (30.96")	179.90		
340	0.39	279.34	339.84	-2.606	-0.133	0.00	1.28	2.61' (31.32")	182.90		

Page No. 1 True Vertical Depth: 1196.18

Final Drift Distance: 4.65' (55.80")

Final Drift Bearing: 184.60°

Note: Magnetic Declination is not used because it is not a factor in the calculation of well drift or alignment. Magnetic Declination is only important if attempting to hit a target or miss another well and then it is included in the calculations.

WELLBORE DRIFT INTERPRETATION

Southwest Exploration Services, LLC

MEASURED DATA			DATA COMPUTATIONS							
DEPTHS, feet	INCLINATIONS, degrees	AZIMUTHS, degrees	TVD, feet	T. LATITUDE, feet	T. LONGITUDE, feet	DOGLEG SEV., degrees per 20 Feet	DOGLEG SEV., degrees per 100 feet	DRIFT DIST., feet	DRIFT BRG. degrees	
360	0.32°	269.48°	359.83	-2.595	-0.256	0.56	0.34	2.61' (31.32'')	185.60	
380	0.30°	029.96°	379.82	-2.550	-0.286	0.73	3.47	2.57' (30.84")	186.40	
400	0.40°	073.56°	399.81	-2.485	-0.193	0.88	1.48	2.49' (29.88'')	184.40	
420	0.44°	093.59°	419.80	-2.470	-0.049	0.20	0.69	2.47' (29.64'')	181.10	
440	0.56°	134.36°	439.79	-2.543	0.098	0.97	1.39	2.55' (30.60'')	177.80	
460	0.75°	154.54°	459.78	-2.730	0.224	0.96	0.70	2.74' (32.88'')	175.30	
480	0.65°	177.65°	479.77	-2.962	0.285	0.12	0.80	2.98' (35.76")	174.50	
500	0.78°	200.03°	499.76	-3.203	0.243	0.81	0.78	3.21' (38.52'')	175.70	
520	0.54°	195.31°	519.75	-3.422	0.171	0.59	0.16	3.43' (41.16")	177.10	
540	0.36°	242.68°	539.74	-3.542	0.090	0.73	1.60	3.54' (42.48'')	178.50	
560	0.38°	249.08°	559.73	-3.595	-0.028	0.28	0.22	3.59' (43.08'')	180.40	
580	0.27°	283.07°	579.72	-3.608	-0.136	0.77	1.17	3.61' (43.32'')	182.20	
600	0.15°	261.48°	599.71	-3.601	-0.208	0.49	0.75	3.61' (43.32'')	183.30	
620	0.24°	291.86°	619.70	-3.589	-0.273	0.69	1.05	3.60' (43.20'')	184.30	
640	0.19°	263.70°	639.69	-3.577	-0.345	0.13	0.97	3.59' (43.08'')	185.50	
660	0.22°	293.40°	659.68	-3.565	-0.413	0.83	1.02	3.59' (43.08'')	186.60	
680	0.17°	317.22°	679.67	-3.528	-0.468	0.80	0.82	3.56' (42.72'')	187.60	
700	0.25°	301.13°	699.66	-3.484	-0.526	0.25	0.56	3.52' (42.24")	188.60	
720	0.23°	264.46°	719.65	-3.465	-0.603	0.54	1.26	3.52' (42.24'')	189.90	
740	0.23°	276.89°	739.64	-3.464	-0.683	0.24	0.43	3.53' (42.36")	191.20	
760	0.29°	321.16°	759.63	-3.420	-0.755	0.94	1.50	3.50' (42.00")	192.40	
780	0.07°	006.28°	779.62	-3.368	-0.785	0.65	1.53	3.46' (41.52'')	193.10	
800	0.20°	247.47°	799.61	-3.369	-0.816	0.97	3.44	3.47' (41.64")	193.60	
820	0.33°	264.68°	819.60	-3.388	-0.906	0.06	0.60	3.51' (42.12'')	195.00	
840	0.16°	176.84°	839.59	-3.421	-0.962	0.29	2.77	3.55' (42.60")	195.70	
860	0.24°	208.74°	859.58	-3.486	-0.981	0.57	1.10	3.62' (43.44")	195.70	
880	0.27°	210.35°	879.57	-3.563	-1.025	0.47	0.06	3.71' (44.52'')	196.00	
900	0.17°	265.57°	899.56	-3.606	-1.078	0.42	1.85	3.76' (45.12'')	196.70	
920	0.25°	245.62°	919.55	-3.626	-1.147	0.69	0.69	3.80' (45.60'')	197.60	
940	0.38°	247.83°	939.54	-3.669	-1.248	0.04	0.08	3.88' (46.56'')	198.80	
960	0.64°	183.91°	959.53	-3.805	-1.317	0.30	2.11	4.03' (48.36'')	199.10	
980	0.60°	195.22°	979.52	-4.017	-1.352	0.98	0.39	4.24' (50.88'')	198.60	
1,000	0.43°	180.63°	999.52	-4.193	-1.380	0.95	0.51	4.41' (52.92'')	198.20	


Page No. 2 True Vertical Depth: 1196.18' Final Drift Distance: 4.65' (55.80") Final Drift Bearing: 184.60°

WELLBORE DRIFT INTERPRETATION

Southwest Exploration Services, LLC

MEASURED DATA			DATA COMPUTATIONS							
DEPTHS, feet	INCLINATIONS, degrees	AZIMUTHS, degrees	TVD, feet	T. LATITUDE, feet	T. LONGITUDE, feet	DOGLEG SEV., degrees per 20 Feet	DOGLEG SEV., degrees per 100 feet	DRIFT DIST., feet	DRIFT BRG degrees	
1,020	0.56°	142.99°	1,019.51	-4.346	-1.322	0.96	1.29	4.54' (54.48'')	196.90	
1,040	0.67°	136.40°	1,039.50	-4.509	-1.183	0.46	0.23	4.66' (55.92'')	194.70	
1,060	1.11°	125.63°	1,059.49	-4.707	-0.945	0.25	0.38	4.80' (57.60'')	191.40	
1,080	0.79°	114.99°	1,079.48	-4.878	-0.663	0.92	0.37	4.92' (59.04")	187.70	
1,100	0.96°	029.04°	1,099.47	-4.790	-0.457	0.09	2.72	4.81' (57.72'')	185.40	
1,120	0.26°	053.40°	1,119.46	-4.616	-0.339	0.16	0.84	4.63' (55.56'')	184.20	
1,140	0.53°	022.13°	1,139.45	-4.503	-0.268	0.98	1.08	4.51' (54.12'')	183.40	
1,160	0.66°	214.26°	1,159.44	-4.513	-0.298	0.54	3.97	4.52' (54.24")	183.80	
1,180	0.29°	143.97°	1,179.43	-4.649	-0.333	0.80	2.30	4.66' (55.92'')	184.10	
1,197	0.55°	308.53°	1,196.18	-4.633	-0.371	0.62	4.72	4.65' (55.80'')	184.60	

Page No. 3 True Vertical Depth: 1196.18' Final Drift Distance: 4.65' (55.80") Final Drift Bearing: 184.60°



3D PROJECTION VIEW - O-06


Florence Copper Florence Copper

Drift Distance = 4.65 Feet

Drift Bearing = 184.6 Degrees

True Vertical Depth = 1196.18 Feet

0.0




Date of Survey: Wednesday - March 21, 2018

Balanced Tangential Calculation Method

Southwest Exploration Services, LLC (480) 926-4558

POLAR VIEW - 0-06

Florence Copper Florence Copper



Date of Survey: Wednesday - March 21, 2018

Balanced Tangential Calculation Method

Southwest Exploration Services, LLC (480) 926-4558

